# **GUARDDOG CONNECT**



DTC: SPN 5891 FMI 4

Bulletin: GDC22-398 Date: April 01, 2022

**Description:** See below for fault code description(s)

Applies to: US ARMY VEHICLES

### **General Information**

These repair instructions are intended to address the following fault(s):

D	TC	Description	Possible Cause	Possible (Observable) Symptoms
	I 5891 VI 4	Transmission Fluid Pressure Switch 1 Circuit Low – Voltage Below Normal or Shorted Low	N/A	N/A

### **Required Parts**

Part Number	Description	Quantity
N/A	PTT, VOCOMII	1

### **Repair Instructions**

Please reference the following file(s):

- IETM, WP File Name: T00657
- IETM, WP Number: **422**

### Additional Resources

 For support with a warrantable fault/fault code, please submit an SF368 Product Quality Deficiency Report (PQDR) in the Product Data Reporting & Evaluation Program (PDERP) at <a href="https://www.pdrep.csd.disa.mil/">https://www.pdrep.csd.disa.mil/</a> and CC or forward the PDREP generated .pdf copy of the SF368 to appropriate Mack Defense Warranty Managers:

Margaret Baranowski (484)-743-7127 margaret.baranowski@mackdefense.com

William Beard (610)-573-4954 william.beard@mackdefense.com

## **GUARDDOG CONNECT**



DTC: SPN 5891 FMI 4

Bulletin: GDC22-398 Date: April 01, 2022

• For assistance with normal service or technical related questions, please contact our Contractor Logistics Support (CLS) provider POCs:

Rich Rader (910) 797-0903 richard.rader@mantech.com

Gil Esplana (254) 404-5409 gil.esplana@mantech.com