

GUARDDOG CONNECT



DTC: P0341-38

Bulletin: GDC22-200

Date: April 01, 2022

Description: See below for fault code description(s)

Applies to: US ARMY VEHICLES

General Information

These repair instructions are intended to address the following fault(s):

DTC	Description	Possible Cause	Possible (Observable) Symptoms
P0341-38	IDTC_CAMSPD_N – Abnormal Frequency, Pulse, Width, or Period	<ul style="list-style-type: none">• Connector• Wiring harness• Tooth wheel• Camshaft position (CMP) sensor	<ul style="list-style-type: none">• Difficult to start at next start despite the fact that no diagnostic trouble code (DTC) is set when the engine is running• Loss of power

Required Parts

Part Number	Description	Quantity
N/A	PTT, VOCOMII	1

Repair Instructions

Please reference the following file(s):

- IETM, WP File Name: **T00806**
- IETM, WP Number: **166**

Additional Resources

- For support with a warrantable fault/fault code, please submit an SF368 Product Quality Deficiency Report (PQDR) in the Product Data Reporting & Evaluation Program (PDERP) at <https://www.pdrep.csd.disa.mil/> and CC or forward the PDREP generated .pdf copy of the SF368 to appropriate Mack Defense Warranty Managers:

Margaret Baranowski
(484)-743-7127
margaret.baranowski@mackdefense.com

William Beard
(610)-573-4954
william.beard@mackdefense.com

DTC: P0341-38

Bulletin: GDC22-200

Date: April 01, 2022

- For assistance with normal service or technical related questions, please contact our Contractor Logistics Support (CLS) provider POCs:

Rich Rader
(910) 797-0903
richard.rader@mantech.com

Gil Esplana
(254) 404-5409
gil.esplana@mantech.com