

Service Bulletin

Bulletin No.: 19-NA-237

Date: January, 2022

INFORMATION

Subject: Diagnostic Tip - Diesel Exhaust Fluid System Contamination

This bulletin replaces PIP5370D. Please discard PIP5370D.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	Engine.	ITAIISIIIISSIOII.
Cadillac	Escalade Models	2020	2022			LM2	
	Cruze	2014	2015			LUZ	
		2017	2019			LH7	
	Colorado	2016	2022			LH7	
	Equinox	2018	2019			LH7	
	Express	2010	2016			LGH	
		2017	2022			LWN	
	Cilvarada	2011	2016			LML	
	Silverado	2017	2018			L5P	
	Silverado 1500 - 4WD (New Model, 12th VIN Digit = 7)	2019	2019				
Chevrolet	Silverado 1500	2020	2021				
Cheviolet	Silverado 1500 (LTD, RPO J21, 12th VIN Digit = 4 or less)	2022	2022			LM2	
	Silverado 1500 - 2WD (LTD, RPO J21, 12th VIN Digit = 4 or less)						
	Silverado 2500/3500	2019	2022			L5P	
	Silverado 4500HD, 5500HD and 6500HD	2019	2022			L5D	
	Silverado LD	2019	2019			L5P	
	Suburban	2020	2022			LM2	
	Tahoe	2020	2022			LM2	

Brand:	Model:	Model Year:		VIN:		Fasina	Tuenemiesien
		from	to	from	to	Engine:	Transmission:
	Savana	2010	2016			LGH	
		2017	2022			LWN	
	Sierra	2011	2016			LML, LGH	
GMC		2017	2018			L5P	
	Sierra 1500	2020	2021				
	Sierra 1500 (LTD, RPO J21, 12th VIN Digit = 4 or less)	- 2022	2022			LM2	
	Sierra 1500 - 2WD (LTD, RPO J21, 12th VIN Digit = 4 or less)						
	Sierra2500/3500	2019	2022			L5P	
	Sierra Limited	2019	2019			L5P	
	Yukon Models	2020	2022			LM2	

Involved Region or Country	North America
Condition	Some customers may comment on one or more of the following conditions: • Exhaust fluid quality poor message on the Driver Information Center (DIC). • Diesel exhaust fluid warning lamp on. • Other exhaust fluid quality related concerns.
Cause	This condition may be caused by contamination in the diesel exhaust fluid (DEF) system and it's components.
	Note: Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.
Correction	Refer to SI for Contaminants in Diesel Exhaust Fluid Diagnosis and use special tools J26568 Coolant and Battery Fluid Tester or EN50422 Diesel Exhaust Fluid Refractometer for fluid testing.
	Note: All 2017 and newer model year diesel vehicles, with the exception of the Colorado and Canyon, are equipped with a DEF quality sensor integrated into the DEF tank. The value of this sensor can be read with the scan tool in the reductant data as the Reductant Concentration.

Information

Below are examples of DEF mixed with different sources of contamination.



Diesel Exhaust Fluid (DEF) mixed with Brake Fluid.



4373641

Diesel Exhaust Fluid (DEF) mixed with Dexcool.



4373642

Diesel Exhaust Fluid (DEF) mixed with Diesel Fuel.



4373644

Diesel Exhaust Fluid (DEF) mixed with Engine Oil.



4373645

Diesel Exhaust Fluid (DEF) mixed with Power Steering Fluid.



4373646

Diesel Exhaust Fluid (DEF) mixed with Transmission Fluid.



Diesel Exhaust Fluid (DEF) mixed with Windshield Washer Fluid.



4373648

Diesel Exhaust Fluid (DEF) mixed with Water.

Warranty Information

This bulletin is being published to help technicians identify signs of contamination in Diesel Exhaust Fluid (DEF). If you see evidence of contamination take appropriate measures to ensure that all of the contaminated fluid is removed from the vehicle. Any components that have failed as a result of contamination should NOT be covered by warranty.

4373647

Version	3
	Released October 17, 2019
Modified	Revised October 27, 2020 - Added 2021 Model Year.
	Revised January 10, 2022 - Added 2022 Model Year.