



Service Bulletin

Bulletin No.: 14-06-04-004H

Date: May, 2022

INFORMATION

Subject: Various Engine Noises During Cold Start and Warm Engine Operation

Models: 2015-2022 Cadillac Escalade, Escalade ESV
2016-2019 Cadillac CTS
2014-2019 Chevrolet Corvette
2015-2022 Chevrolet Suburban, Tahoe
2016-2022 Chevrolet Camaro
2014-2018 Chevrolet Silverado 1500
2019 Chevrolet Silverado 1500 LD
2019 Chevrolet Silverado 1500 (New Model - 12th VIN Digit = 7)
2019 Chevrolet Silverado 1500 (New Model)
2019-2022 Chevrolet Silverado 2500/3500
2020-2021 Chevrolet Silverado 1500
2022 Chevrolet Silverado 1500 LTD (RPO J21, 12th VIN Digit = 4 or less)
2022 Chevrolet Silverado 1500 New (RPO J22, 12th VIN Digit = 5 or greater)
2015-2022 GMC Yukon, Yukon XL
2014-2018 GMC Sierra 1500
2019 GMC Sierra 1500 Limited
2019 GMC Sierra 1500 (New Model)
2019-2022 GMC Sierra 2500/3500
2020-2021 GMC Sierra 1500
2022 Chevrolet Sierra 1500 Limited (RPO J21, 12th VIN Digit = 4 or less)
2022 Chevrolet Sierra 1500 New (RPO J22, 12th VIN Digit = 5 or greater)
Equipped with 4.3L Engine (RPOs LV1, LV3), 5.3L Engine (RPOs L82, L83, L84), 6.2L Engine (RPOs L86, L87, LT1, LT4, LT5) or 6.6L Engine (RPO L8T)

Attention: This bulletin also applies to any of the above models that may be Export from North America vehicles.

This bulletin has been revised to add 2021-2022 Model Years. Please discard Corporate Bulletin Number 14-06-04-004G.

Information For Why New Engine Technologies Are Generating Noises

The latest generation of full size trucks and utilities incorporate a new generation of technologies not previously seen in full size truck and utility applications. As a result these engines generate noises during cold start and during warm operation that owners of previous generation multiport fuel injection (MFI) vehicles may not be familiar with.

Direct Injection (DI) / High Pressure Fuel Pump / Fuel Injectors

The new Small Block Generation 5 engine family incorporates a new fuel system technology known as Direct Injection (DI). With DI, fuel is injected directly into the cylinder using a high pressure fuel system. DI provides many benefits in improving engine efficiency. In particular, DI improves power, torque, and most importantly fuel efficiency. This technology is included as standard equipment on all Generation 5 engines in the Small Block engine family, which are the 4.3L V6, 5.3L V8, 6.2L V8 and the 6.6L V8.

The high pressure fuel system does have unique operating characteristics, in particular the noise emanating from the high pressure fuel pump can result in a subtle ticking noise that is apparent when the vehicle is idling. The sound is more evident when outside around the vehicle, when the hood is open or the vehicle is operated in a drive-through. The sound may be more noticeable during a cold start, but lessens once the engine is warm. A slightly higher pitched clicking sound is the fuel injectors pulsing **ON** and **OFF** under the high fuel pressures.

These sounds are a normal characteristics of the DI high pressure fuel system.

Another operating characteristic is a slightly longer crank time when the engine is started. The increased crank time is the result of the time required to build high pressure in the fuel system before the engine starts.

Oil Pump Cold Start Rrrrp or Rasp

The oil pump design has changed from a gerotor gear type pump to a two-stage vane type pump for fuel economy reasons. At temperatures at or below 0°C (32°F), or when the engine has been sitting for a few

hours, it is possible to have air enter the pump through normal oil drain back. Upon startup, the owner may hear a short "Rrrrp" or "Rasp" coming from the front of the engine. It is most often heard during a remote start.

There is nothing wrong with the oil pump or oil system. No repairs should be attempted for this condition.

6.2L Engine – Dry Sump Oil System Moan

The 6.2L engine dry sump oil system may generate a moan noise that may be heard inside the vehicle at idle and/or low engine rpm operation for approximately the first two minutes following a cold start. The noise cannot be heard from the outside of the vehicle. This noise may be more noticeable on the passenger side of the vehicle and has been described as similar to the sound of running water.

The dry sump oil system is hard mounted to the body of the vehicle, and at cold start, the oil moving through the system can transfer the noise to the body.

This is a normal dry sump oil system operating characteristic and no repairs should be attempted.