

**Volvo Chassis - Automated Manual Transmission** Model F (AMT-F, I-Shift) - Possible Infrequent **Hiccup/Stumble During Steady Engine/Vehicle** Speed; Diagnostic Trouble Code P1074-92, P1074-94, P1074-96 Logging, Appears As Inactive -**Common Model Years 201** 





> Internal Content

If a vehicle presents the symptoms described above:

- 1. Using Premium Tech Tool (PTT) run Operation 4311-08-03-02 -Input Signals for Gear Selection, located under the Test tab.
- 2. Monitor the Transmission 2/3 Cylinder Position, located under the **Gearbox Actuator section of the test while operating the** transmission to replicate the issue.
  - During steady state operations, the signal for the shifter should be stable.
  - If the position values are found to fluctuate, the signal can get outside the MIN/MAX values and the TECU will think the shifter has left the position it was in.
- 3. If the signal is fluctuating: Inspect the internal wiring harness.
- The internal wiring harness have been found in a some cases to have terminals that have pushed back in the connector and not making good connection. An example is shown below:

5/31/22, 2:29 PM Article



## 4. Proceed according to findings:

• If pins are found to be pushed out of the connector: Reinstall the terminals in the connector and verify that the locking tabs are holding the terminals.

o p107492 k43113098 p1074-92 r **the connector is toung to be bad:** keplace the narness.

amt-f with crawler gears **5. verny the repair.**amt-f without crawler gears

## Related links and attachments


No links or attachments available



Give feedback

Live UI

to help improve the content of this article



5/31/2022































