

QUALITY ACTION

CAMPAIGN BULLETIN

Tire Replacement Dealer Inventory

Reference: PC884

Date: April 6, 2022

Attention: Dealer Principal, Sales, Service & Parts Managers

Affected Models/Years:	Affected Population:	Dealer Inventory:	SERVICE COMM Activation date:	Stop Sale In Effect
MY2022 Titan XD Pro-4X (A61)	NA	12	April 6, 2022	YES

*****Dealer Announcement*****

Nissan is conducting a dealer inventory quality action to replace all five (5) tires (including spare tire) on **12** specific MY2022 Nissan Titan XD vehicles identified in Service Comm and National Service History – Open Campaigns. Due to a manufacturing concern, the tires may have been damaged when mounted on the rim.

Affected vehicles **are subject** to stop sale and are either currently in dealer inventory or assigned and in transit to the dealer.

*****What Dealers Should Do*****

PLEASE FOLLOW THE ATTACHED INSPECTION INSTRUCTIONS:

- Verify if vehicles are affected by this quality action using Service Comm or DBS National Service History - Open Campaigns I.D. <u>PC884</u>
 - New vehicles in dealer inventory can also be identified using DBS (Sales-> Vehicle Inventory, and filter by Open Campaign).
 - Refer to NPSB 15-460 for additional information
 - Please continue to check newly arriving inventory for campaign applicability.
- 2. Please <u>do not drive, loan, sell or trade</u> the specific vehicles in dealer inventory subject to this quality action.
- Use the attached procedure to remedy any vehicles affected by this quality action prior to sale.
- 4. Once remedied, dealers should submit the applicable warranty claim for the action performed so it can be closed in Service Comm and release the vehicle for sale.

***** Dealer Responsibility *****

It is the dealer's responsibility to check Service Comm or DBS National Service History - Open Campaign using the appropriate campaign ID for the inspection status on each affected vehicle currently in new vehicle inventory.



PC884 – 2022 TITAN-XD PRO-4X TIRE REPLACEMENT

Service Procedure

- 1. Replace and balance all (5) tires (including spare tire).
 - For tire replacement refer to the Electronic Service Manual (ESM) section:
 SUSPENSION > ROAD WHEELS & TIRES > REMOVAL AND INSTALLATION > WHEEL AND TIRE > Removal and Installation
 - Wheel nut torque: 177 N•m (18 kg-m, 131 ft-lb)

NOTE:

The spare wheel and tire assembly does not have a TPMS sensor. Be sure it is reinstalled in the spare tire area.

NOTICE

Be careful to not damage the wheel or tire pressure sensor when replacing tires.




Figure 1

- 2. Perform TPMS ID registration.
 - For TPMS sensor ID registration refer to the ESM section: SUSPENSION > ROAD WHEELS & TIRES > BASIC INSPECTION > ID REGISTRATION PROCEDURE > Work Procedure

1/2 PC884

- 3. Using a ½" drill bit, drill two holes through the sidewall of each of the <u>removed</u> tires
 - Properly dispose of tires in accordance with local and state regulations.

Parts Information

Description	Part Number	Qty
Replacement Tire General Grabber APT LT275/65 R18 (1)	OETIR-02993 (2)	5

- (1) Order this item through the Nissan Maintenance Advantage program: Phone 877-NIS-NMA1 (877-647-6621). Website order via link on the dealer portal; www.NNAnet.com and click on the Parts, Service & Accessories tab then select "Maintenance Advantage-Tire/Battery/Chemical" link.
- (2) Use below expense code for tire reimbursement. **DO NOT** claim the Dealer Tire part number on the claim.

EXPENSE CODE

EXPENSE CODE	DESCRIPTION	MAX AMOUNT
599*	Replacement General Grabber APT LT275/65R18	\$1750

^{*} **DO NOT** claim the Dealer Tire part number on the claim. Use this expense code for tire(s) reimbursement.

NOTE: MAX AMOUNT includes "5" tires, local and state tax, as well as disposal fees.

Claims Information

Submit a "CM" line claim using the following claims coding:

Campaign ("CM") ID	Description	Op code	FRT
PC884	Remove and Replace 5 tires	PC8840	2.0 hrs

2/2 PC884