

Technical Service Bulletin

48 Red Steering warning in the cluster - DTC B200049 stored in J500

48 22 35 2067555/1 July 29, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7, and Q8	2019 – 2021		
SQ7, SQ8, and RS Q8	2020 – 2021	All	Not Applicable

Condition

Customer states:

• The red steering warning lamp lights up in the instrument cluster. Steering assist is reduced.

Workshop findings:

- The complaint can be reproduced and the following DTC is logged in the power steering control unit J500 (address 0044).
- B200049 with Symptom Code 7353984.

Technical Background

Software issue identified and corrected in production.

Production Solution

Gradually introduced in the assembly line starting on 2nd Quarter 2022.

Page 1 of 3

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

^{© 2022} Audi of America, Inc.



Technical Service Bulletin

Service

SVM Update Instructions

- 1. Follow all instructions in TSB 2011732: *OO Software Version Management (SVM), operating instructions.*
- 2. Update the 0044 (J500) using the SVM action code as listed in the table below, if necessary:

Model	Old Software Part Number	Old Software Version	New Software Part Number (or higher)	New Software Version (or higher)	SVM Code Input
All models	4N0909144E	0505	4N0909144G	0507	44A036

Warranty

Warranty Claim Type	 110 up to 48 Months/50,000 miles G10 for CPO Covered vehicles If this vehicle is outside of any warranty, this Technical Service Bulletin is 		
	informational only.		
Service Number:	4835		
Damage Code:	0040		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin

	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2067555/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2067555) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2022 Audi of America, Inc.

Page 3 of 3

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.