Service Update N222362010 Front Lift System Reservoir Cap Leak



Release Date: August 2022

Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

		Model Year		Model Year			
Make	Model	From	То	RPO	Description		
Chevrolet	Corvette	2022	2023	E60	BODY HEIGHT-INCR GROUND CLEARANCE		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	On certain 2022-2023 model year Chevrolet Corvette vehicles equipped with Front Lift Adjustable Height					
	Memory, (RPO E60), there may be a hydraulic lift fluid leak at the front right hand (passenger) side of					
	the vehicle.					
Correction	Dealers are to replace the front hydraulic lift fluid reservoir vented cap with a non-vented cap.					

Parts

Quantity	Part Name	Part No.	
1	CAP-HYD SUSP FLUID RSVR	86781938	

Parts required to complete this recall are to be obtained from General Motors Customer Care and Aftersales (GMCC&A). Please refer to your "involved vehicles listing" before ordering parts. Normal orders should be placed on a DRO = Daily Replenishment Order. In an emergency situation, parts should be ordered on a CSO = Customer Special Order. A quantity limiter may be in effect.

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor		Labor	Trans.	Net
Operation	Description	Time	Туре	Item
9106416	Replace Hydraulic Suspension Fluid Reservoir Cap	0.3	ZFAT	N/A

Service Procedure

Warning: Refer to Brake Fluid Irritant Warning in SI.

Caution: Refer to Brake Fluid Effects on Paint and Electrical Components Caution in SI.

- 1. Remove the front compartment rear access panel. Refer to *Front Compartment Rear Access Cover Replacement* in SI.
- 2. Locate the hydraulic suspension fluid reservoir mounted on the passenger side of the compartment.

Note: Clean the filler cap and surrounding area before removing the cap, pay special attention to the front spring.



6104621

3. Remove the incorrect reservoir cap. Discard the cap.





6104625

- 4. Install the new corrected reservoir cap.
- 5. Reinstall the front compartment rear access panel. Refer to *Front Compartment Rear Access Cover Replacement* in SI.

Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealer Reports - For USA & Export

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



We Support Voluntary Technician Certification

GLOBAL SAFETY FIELD INVESTIGATIONS DCS6225 URGENT - DISTRIBUTE IMMEDIATELY

Date: August 2, 2022

- Subject: N222362010 Service Update Front Lift System Reservoir Cap Leak
- Models: 2022-2023 Chevrolet Corvette Equipped with BODY HEIGHT-INCR GROUND CLEARANCE (RPO E60)
- To: All General Motors Dealers

General Motors is releasing Service Update N222362010 today. The total number of U.S. vehicles involved is approximately 1,533. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated August 2, 2022. There are **no vehicles** in dealer new inventory. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE GLOBAL SAFETY FIELD INVESTIGATIONS