

WME3 - Adapting Vehicle Order in the Instrument Cluster (Workshop Campaign)

Important: **CRITICAL WARNING** -This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Year: **As of 2021 up to 2022**

Model Series: **Cayenne (9YA / 9YB)**

Equipment: Electric steering column adjustment (M-no. 2C7)

Concerns: **Instrument cluster**

Information: **Due to the still tight supply situation, it was decided that the electrically adjustable steering column will not be retrofitted for the vehicles affected by workshop campaign WME3 in contrast to the originally planned procedure.**
The vehicle order must therefore be changed due to the permanent option changes.

Action required: Adapt vehicle order in instrument cluster and software version **41.000.050** (or higher) installed.

NOTICE

Use of a PIWIS Tester software version that is older than the prescribed version

- **Measure is ineffective**
- ⇒ **Always use the prescribed version or a higher version of the PIWIS Tester software for control unit coding.**

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information)

Important: **CRITICAL WARNING** -This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Series: **Taycan (Y1A / Y1B / Y1C)**

Equipment: Electric steering column adjustment (M-no. 2C7)

Concerns: **Instrument cluster**

Information: **Due to the still tight supply situation, it was decided that the electrically adjustable steering column will not be retrofitted for the vehicles affected by workshop campaign WME3 in contrast to the originally planned procedure.**

The vehicle order must therefore be changed due to the permanent option changes.

Action required: Adapt vehicle order in instrument cluster and software version **41.000.050** (or higher) installed.

NOTICE

Use of a PIWIS Tester software version that is older than the specified version

- **Measure is ineffective**

⇒ **Always use the prescribed version or a higher version of the PIWIS Tester software for control unit coding.**

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information)

Important: **CRITICAL WARNING** -This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Series: **911 (992)**

Equipment: Electric steering column adjustment (M-no. 2C7)
Electric steering column adjustment Exclusive (M-no. 2C8)

Concerns: **Instrument cluster**

Information: **Due to the still tight supply situation, it was decided that the electrically adjustable steering column will not be retrofitted for the vehicles affected by workshop campaign WME3 in contrast to the originally planned procedure.**

The vehicle order must therefore be changed due to the permanent option changes.

Action required: Adapt vehicle order in instrument cluster and software version **41.000.050** (or higher) installed.

NOTICE

Use of a PIWIS Tester software version that is older than the specified version

- **Measure is ineffective**

⇒ **Always use the prescribed version or a higher version of the PIWIS Tester software for control unit coding.**

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information)

Important: **CRITICAL WARNING** -This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Series: **Macan (95B)**

Equipment: Electric steering column adjustment (M-no. 2C4)

Concerns: **Instrument cluster**

Information: **Due to the still tight supply situation, it was decided that the electrically adjustable steering column will not be retrofitted for the vehicles affected by workshop campaign WME3 in contrast to the originally planned procedure.**

The vehicle order must therefore be changed due to the permanent option changes.

Action required: Adapt vehicle order in instrument cluster and software version **41.000.050** (or higher) installed.

NOTICE

Use of a PIWIS Tester software version that is older than the specified version

- **Measure is ineffective**

⇒ **Always use the prescribed version or a higher version of the PIWIS Tester software for control unit coding.**

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information)

Important: **CRITICAL WARNING** -This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician

must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Series: **Panamera (971)**

Equipment: Electric steering column adjustment (M-no. 2C4)

Concerns: **Instrument cluster**

Information: **Due to the still tight supply situation, it was decided that the electrically adjustable steering column will not be retrofitted for the vehicles affected by workshop campaign WME3 in contrast to the originally planned procedure.**

The vehicle order must therefore be changed due to the permanent option changes.

Action required: Adapt vehicle order in instrument cluster and software version **41.000.050** (or higher) installed.

NOTICE

Use of a PIWIS Tester software version that is older than the specified version

- **Measure is ineffective**

⇒ **Always use the prescribed version or a higher version of the PIWIS Tester software for control unit coding.**

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information)

Important: **CRITICAL WARNING** -This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Series: **718 Boxster (982) / 718 Cayman (982)**

Equipment: Electric steering column adjustment without electric steering column lock (M-no. 648)
Electric steering column adjustment with electric steering column lock (M-no. 656)

Concerns: **Instrument cluster**

Information: **Due to the still tight supply situation, it was decided that the electrically adjustable steering column will not be retrofitted for the vehicles affected by workshop campaign WME3 in contrast to the originally planned procedure.**

The vehicle order must therefore be changed due to the permanent option changes.

Action required: Adapt vehicle order in instrument cluster and software version **41.000.050** (or higher) installed.

NOTICE

Use of a PIWIS Tester software version that is older than the specified version

- Measure is ineffective
- ⇒ **Always use the prescribed version or a higher version of the PIWIS Tester software for control unit coding.**

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information)

Required tools

- Tool:
- **9900 - PIWIS Tester 3** with PIWIS Tester software version **41.000.050** (or higher) installed
 - Battery charger with a current rating of **at least 90 A**, e.g. **VAS 5908 battery charger 90A**

Matching vehicle order in the instrument cluster (Cayenne)

Work Procedure:



Information

To rule out any campaign allocation errors, check the installation status of the steering column adjustment system at the beginning.

- 1 Check installation status of steering column adjustment.
 - The vehicle is equipped with **electric** steering column adjustment:

– End of action –
Continue with ⇒ *Technical Information 'warranty processing'*, Scope 1.
 - The vehicle is equipped with **mechanical** steering column adjustment and is assigned to **campaign scope 2**:

– End of action –
The control number 'C03' was already assigned to this vehicle during production. Proceed to ⇒ *Technical Information 'Warranty processing'*, Scope 2.
 - The vehicle is equipped with **mechanical** steering column adjustment and is assigned to **campaign scope 3**: Continue with Step 2.

- 2 Follow the general preliminary work for control unit programming or coding as described in the Workshop Manual. In this connection, see ⇒ *Workshop Manual 'Basic instructions and procedure for control unit programming using the PIWIS Tester'*.



Information

To carry out the campaign, the PIWIS Tester must be online and logged into the Porsche Partner Network (PPN).

- 3 In the control unit selection (**Overview** menu) press •F7" to call up the Additional menu.
- 4 Select **'Maintenance of vehicle data with PIWIS ONLINE'** and press •F12" ('Next') to confirm. The guided Tester procedure starts and the vehicle data between the vehicle and PIWIS ONLINE is compared.
- 5 Once the comparison has been completed and the message that significant differences were found is displayed, press •F12" ('Next') to continue.
The following new PR number (control number) from PIWIS ONLINE is displayed: **C03 (COC PAPERS (INSTALLED 2C5 INSTEAD OF 2C7))**.
- 6 Press •F8" to write the changes to the vehicle order.
- 7 Press •F12" ('Next') button to skip the displays containing information on vehicle description and colors/materials.



Information

As a rule, the M-number for **electric** steering column adjustment is set in the vehicle master data for all vehicles with the concerned WME3 campaign. This does not apply to Cayenne vehicles. In Cayenne vehicles with the concerned WME3 campaign, the M-number for **mechanical** steering column adjustment (M-no. 2C5) is set.

- 8 For PR numbers under **'Steering column systems'** family, check whether the value **2C5** (STEERING COLUMN, MECH. AX., VERT. ADJUSTABLE) is selected.
If it is not and instead the value 2C7 (STEER. COL. AX., VERT. ADJ. + MEMORY) is selected, the value 2C7 must be replaced by the value **2C5**.
- 9 The data is then synchronized and the PIWIS Tester automatically checks which control units must be re-coded. Confirm the displayed overview of control units with •F12" ('Next') and re-code it.

When coding is complete, the message "Coding has been completed successfully" is displayed and a tick appears in the relevant 'Status' box.
- 10 Read out and erase the fault memories of all control units.
 - 10.1 In the control unit selection (Overview menu) press •F7" to call up the Additional menu.

- 10.2 Select the function "Read all fault memories and erase if necessary" and press •F12" ('Next') to confirm.
- 11 Press •F11" ('Back') to return to the control unit selection screen.
- 12 Switch off ignition.
- 13 Disconnect the PIWIS Tester from the vehicle.
- 14 Switch off and disconnect the battery charger.
- 15 Enter the campaign in the Guarantee and Maintenance booklet.

Matching vehicle order in the instrument cluster (Panamera)



Information

Once the relevant control number has been written to the vehicle order, all fault memories that were active due to lack of electric steering column adjustment are deactivated. As a result, fault memories must no longer be active in connection with the absence of electric steering column adjustment.

Work
Procedure:



Information

To rule out any campaign allocation errors, check the installation status of the steering column adjustment system at the beginning.

- 1 Check installation status of steering column adjustment.
 - The vehicle is equipped with **mechanical** steering column adjustment: Continue with Step 2.
 - The vehicle is equipped with **electric** steering column adjustment:

– End of action –
Continue with ⇒ *Technical Information 'warranty processing'*, Scope 1.
- 2 Follow the general preliminary work for control unit programming or coding as described in the Workshop Manual. In this connection, see ⇒ *Workshop Manual 'Basic instructions and procedure for control unit programming using the PIWIS Tester'*.



Information

To carry out the campaign, the PIWIS Tester must be online and logged into the Porsche Partner Network (PPN).

- 3 In the control unit selection (**Overview** menu) press •F7" to call up the Additional menu.

- 4 Select **'Maintenance of vehicle data with PIWIS ONLINE'** and press •F12" ('Next') to confirm. The guided Tester procedure starts and the vehicle data between the vehicle and PIWIS ONLINE is compared.
- 5 Once the comparison has been completed and the message that significant differences were found is displayed, press •F12" ('Next') to continue.
The following new PR number (control number) from PIWIS ONLINE is displayed: **SJ7 (DIFFERENT INSTALLATION, MVLS)**.
- 6 Press •F8" to write the changes to the vehicle order.
- 7 Press •F12" ('Next') button to skip the displays containing information on vehicle description and colors/materials.
- 8 For PR numbers under **'Steering column systems'** family, check whether the value **2C4** (STEERING COLUMN AX., VERT. ADJ. + MEMORY) is selected.
If not and instead the value 2C5 (MECH STEERING COLUMN AX., VERT. ADJUSTB) is selected, the value 2C5 must be replaced by the value **2C4** .
- 9 The data is then synchronized and the PIWIS Tester automatically checks which control units must be re-coded. Confirm the displayed overview of control units with •F12" ('Next') and re-code it.
When coding is complete, the message "Coding has been completed successfully" is displayed and a tick appears in the relevant 'Status' box.
- 10 Read out and erase the fault memories of all control units.
 - 10.1 In the control unit selection (Overview menu) press •F7" to call up the Additional menu.
 - 10.2 Select the function "Read all fault memories and erase if necessary" and press •F12" ('Next') to confirm.
- 11 Press •F11" ('Back') to return to the control unit selection screen.
- 12 Switch off ignition.
- 13 Disconnect the PIWIS Tester from the vehicle.
- 14 Switch off and disconnect the battery charger.
- 15 Enter the campaign in the Guarantee and Maintenance booklet.

Matching vehicle order in the instrument cluster (911)

Work
Procedure:

**Information**

To rule out any campaign allocation errors, check the installation status of the steering column adjustment system at the beginning.

- 1 Check installation status of steering column adjustment.
 - The vehicle is equipped with **mechanical** steering column adjustment: Continue with Step 2.
 - The vehicle is equipped with **electric** steering column adjustment:
- End of action –**
Continue with ⇒ *Technical Information 'warranty processing'*, Scope 1.
- 2 Follow the general preliminary work for control unit programming or coding as described in the Workshop Manual. In this connection, see ⇒ *Workshop Manual 'Basic instructions and procedure for control unit programming using the PIWIS Tester'*.

**Information**

To carry out the campaign, the PIWIS Tester must be online and logged into the Porsche Partner Network (PPN).

- 3 In the control unit selection (**Overview** menu) press •F7" to call up the Additional menu.
- 4 Select '**Maintenance of vehicle data with PIWIS ONLINE**' and press •F12" ('Next') to confirm. The guided Tester procedure starts and the vehicle data between the vehicle and PIWIS ONLINE is compared.
- 5 Once the comparison has been completed and the message that significant differences were found is displayed, press •F12" ('Next') to continue.
The following new PR number (control number) from PIWIS ONLINE is displayed: **SA9 (CONTROL DIFF. INSTALLATION EVLS)**.
- 6 Press •F8" to write the changes to the vehicle order.
- 7 Press •F12" ('Next') button to skip the displays containing information on vehicle description and colors/materials.

- 8 For PR numbers under '**Steering column systems**' family, check whether the value **2C7** (STEERING AX., VERT. ADJ. + MEMORY) or for Exclusive leather trim, the value **2C8** (Leather steering column casing (in conjunction with memory package)) is selected.
If it is not and instead the value 2C5 (MECH STEERING COLUMN AX., VERT. ADJUSTB.) is selected or for Exclusive leather covering, the value 2C6 is selected, the value 2C5 must be replaced by the value **2C7** or the value 2C6 must be replaced by the value **2C8**.
- 9 The data is then synchronized and the PIWIS Tester automatically checks which control units must be re-coded. Confirm the displayed overview of control units with •F12" ('Next') and re-code it.

When coding is complete, the message "Coding has been completed successfully" is displayed and a tick appears in the relevant 'Status' box.

- 10 Read out and erase the fault memories of all control units.



Information

Once the relevant control number has been written to the vehicle order, all fault memories that were active due to lack of electric steering column adjustment are deactivated. As a result, fault memories must no longer be active in connection with the absence of electric steering column adjustment.

- 10.1 In the control unit selection (Overview menu) press •F7" to call up the Additional menu.
- 10.2 Select the function "Read all fault memories and erase if necessary" and press •F12" ('Next') to confirm.
- 11 Press •F11" ('Back') to return to the control unit selection screen.
- 12 Switch off ignition.
- 13 Disconnect the PIWIS Tester from the vehicle.
- 14 Switch off and disconnect the battery charger.
- 15 Enter the campaign in the Warranty and Maintenance booklet.

Matching vehicle order in the instrument cluster (Taycan)

Labor time:



Information

To rule out any campaign allocation errors, check the installation status of the steering column adjustment system at the beginning.

- 1 Check installation status of steering column adjustment.
 - The vehicle is equipped with **mechanical** steering column adjustment: Continue with Step 2.

- The vehicle is equipped with **electric** steering column adjustment:

– End of action –

Continue with ⇒ *Technical Information 'warranty processing'*, Scope 1.

- 2 Follow the general preliminary work for control unit programming or coding as described in the Workshop Manual. In this connection, see ⇒ *Workshop Manual 'Basic instructions and procedure for control unit programming using the PIWIS Tester'*.



Information

To carry out the campaign, the PIWIS Tester must be online and logged into the Porsche Partner Network (PPN).

- 3 In the control unit selection (**Overview** menu) press •F7" to call up the Additional menu.
- 4 Select '**Maintenance of vehicle data with PIWIS ONLINE**' and press •F12" ('Next') to confirm. The guided Tester procedure starts and the vehicle data between the vehicle and PIWIS ONLINE is compared.
- 5 Once the comparison has been completed and the message that significant differences were found is displayed, press •F12" ('Next') to continue.
The following new PR number (control number) from PIWIS ONLINE is displayed: **SJ7 (DIFFERENT INSTALLATION, MVLS)**.
- 6 Press •F8" to write the changes to the vehicle order.
- 7 Press •F12" ('Next') button to skip the displays containing information on vehicle description and colors/materials.
- 8 For PR numbers under '**Steering column systems**' family, check whether the value **2C7** (STEERING AX.,VERT. ADJ. +MEMORY) is selected.
If not and instead the value 2C5 (MECH STEERING COLUMN AX.,VERT.ADJUSTB) is selected, the value 2C5 must be replaced by the value **2C7**.
- 9 The data is then synchronized and the PIWIS Tester automatically checks which control units must be re-coded. Confirm the displayed overview of control units with •F12" ('Next') and re-code it.

When coding is complete, the message "Coding has been completed successfully" is displayed and a tick appears in the relevant 'Status' box.
- 10 Read out and erase the fault memories of all control units.

**Information**

Once the relevant control number has been written to the vehicle order, all fault memories that were active due to lack of electric steering column adjustment are deactivated. As a result, fault memories must no longer be active in connection with the absence of electric steering column adjustment.

- 10.1 In the control unit selection (Overview menu) press •F7" to call up the Additional menu.
- 10.2 Select the function "Read all fault memories and erase if necessary" and press •F12" ('Next') to confirm.
- 11 Press •F11" ('Back') to return to the control unit selection screen.
- 12 End Readiness for operation (switch off ignition).
- 13 Disconnect the PIWIS Tester from the vehicle.
- 14 Switch off and disconnect the battery charger.
- 15 Enter the campaign in the Warranty and Maintenance booklet.

Matching vehicle order in the instrument cluster (Macan)

Work
Procedure:

**Information**

To rule out any campaign allocation errors, check the installation status of the steering column adjustment system at the beginning.

- 1 Check installation status of steering column adjustment.
 - The vehicle is equipped with **mechanical** steering column adjustment: Continue with Step 2.
 - The vehicle is equipped with **electric** steering column adjustment:

– End of action –
Continue with ⇒ *Technical Information 'warranty processing'*, Scope 1.
- 2 Follow the general preliminary work for control unit programming or coding as described in the Workshop Manual. In this connection, see ⇒ *Workshop Manual 'Basic instructions and procedure for control unit programming using the PIWIS Tester'*.

**Information**

To carry out the campaign, the PIWIS Tester must be online and logged into the Porsche Partner Network (PPN).

- 3 In the control unit selection (**Overview** menu) press •F7" to call up the Additional menu.
- 4 Select **'Maintenance of vehicle data with PIWIS ONLINE'** and press •F12" ('Next') to confirm. The guided Tester procedure starts and the vehicle data between the vehicle and PIWIS ONLINE is compared.
- 5 Once the comparison has been completed and the message that significant differences were found is displayed, press •F12" ('Next') to continue.
The following new PR number (control number) from PIWIS ONLINE is displayed: **SJ7 (DIFFERENT INSTALLATION, MVLS)**.
- 6 Press •F8" to write the changes to the vehicle order.
- 7 Press •F12" ('Next') button to skip the displays containing information on vehicle description and colors/materials.
- 8 For PR numbers under **'Steering column systems'** family, check whether the value **2C4** (STEERING COLUMN AX., VERT. ADJ. + MEMORY) is selected.
If not and instead the value 2C5 (MECH STEERING COLUMN AX., VERT. ADJUSTB) is selected, the value 2C5 must be replaced by the value **2C4**.
- 9 The data is then synchronized and the PIWIS Tester automatically checks which control units must be re-coded. Confirm the displayed overview of control units with •F12" ('Next') and re-code it.

When coding is complete, the message "Coding has been completed successfully" is displayed and a tick appears in the relevant 'Status' box.
- 10 Press •F11" ('Back') to return to the control unit overview.
- 11 In the control unit selection screen (**'Overview'** menu) select **Front end electronics** and press •F12" ('Next') to confirm your selection.
- 12 Once the control unit for Front-end electronics has been found, call up the **'Codings/adaptations'** menu.
- 13 Select the **'Automatic coding'** function and press •F12" ('Next') to start control unit coding.

When coding is complete, the message "Coding has been completed successfully" is displayed and a tick appears in the 'Status' box.
- 14 Once coding is completed successfully, press •F12" ('Next').
- 15 Press •F11" ('Back') to return to the control unit overview.
- 16 Read out and erase the fault memories of all control units.

**Information**

Once the relevant control number has been written to the vehicle order and the front-end electronics control unit has been re-coded, all fault memories that were active due to lack of electric steering column adjustment are deactivated. As a result, fault memories must no longer be active in connection with the absence of electric steering column adjustment.

- 16.1 In the control unit selection (Overview menu) press •F7" to call up the Additional menu.
- 16.2 Select the function "Read all fault memories and erase if necessary" and press •F12" ('Next') to confirm.
- 17 Press •F11" ('Back') to return to the control unit selection screen.
- 18 Switch off ignition.
- 19 Disconnect the PIWIS Tester from the vehicle.
- 20 Switch off and disconnect the battery charger.
- 21 Enter the campaign in the Guarantee and Maintenance booklet.

Matching vehicle order in the instrument cluster (718)**Information**

To rule out any campaign allocation errors, check the installation status of the steering column adjustment system at the beginning.

- Work Procedure: 1 Check installation status of steering column adjustment.
- The vehicle is equipped with **mechanical** steering column adjustment: Continue with Step 2.
 - The vehicle is equipped with **electric** steering column adjustment:
- End of action –**
Continue with ⇒ *Technical Information 'warranty processing', Scope 1.*
- 2 Follow the general preliminary work for control unit programming or coding as described in the Workshop Manual. In this connection, see ⇒ *Workshop Manual 'Basic instructions and procedure for control unit programming using the PIWIS Tester'.*

**Information**

To carry out the campaign, the PIWIS Tester must be online and logged into the Porsche Partner Network (PPN).

- 3 In the control unit selection (**Overview** menu) press •F7" to call up the Additional menu.
- 4 Select **'Maintenance of vehicle data'** and press •F12" ('Next') to confirm your selection.
- 5 Press •F12" ('Next') to skip the displays containing information about vehicle description, colors/materials and X numbers.
- 6 Under M numbers and the 'Steering column systems' family, check whether the value **648** (STEERING COLUMN EL. ADJUSTED WITHOUT ELV) or correspondingly the value **656** (STEER. COLUMN, EL. ADJUSTED WITH ELV) is selected.
If not and instead the value 647 (STEER. COLUMN, MECH. ADJUST. WITHOUT ELV) or the value 655 (STEER. COLUMN, MECH. ADJUST. WITH ELV) is selected, the value 647 must be replaced by the value **648** or the value 655 must be replaced by the value **656**. Press •F12" ('Next') to confirm.
- 7 In the second M-numbers overview, add the coding value **S7J (DIFFERENT INSTALLATION OF MVLS)** to the vehicle data. To do this, for the relevant coding value, click on the tick in the "Installed" field to select the value.
- 8 Press •F12" ('Next') to end the process and then press •F8" to save the change.
- 9 Press •F12" ('Next') twice to end the process and then press •F8" to save the change.
- 10 Press •F11" ('Back') to return to the control unit selection screen.
- 11 **If the M number is changed under the 'Steering column systems' family**, the front-end electronics control unit must then be re-coded. To do this, select the front-end electronics control unit in the control unit overview and perform 'Automatic coding' under 'Codings/adaptations'.
- 12 Read out and erase the fault memories of all control units.



Information

Once the relevant control number has been written to the vehicle order, all fault memories that were active due to lack of electric steering column adjustment are deactivated. As a result, fault memories must no longer be active in connection with the absence of electric steering column adjustment.

 - 12.1 In the control unit selection (Overview menu) press •F7" to call up the Additional menu.
 - 12.2 Select the function "Read all fault memories and erase if necessary" and press •F12" ('Next') to confirm.
- 13 Press •F11" ('Back') to return to the control unit selection screen.
- 14 Switch off ignition.
- 15 Disconnect the PIWIS Tester from the vehicle.

- 16 Switch off and disconnect the battery charger.
- 17 Enter the campaign in the Warranty and Maintenance booklet.

Warranty processing



Information

The specified working time was determined specifically for carrying out this campaign and includes all necessary preliminary and subsequent work.
The working time may differ from the working times published in the Labor Operation List in the PCSS.

Scope 1: Checking installation status of steering column adjustment

- The vehicle is equipped with **electric** steering column adjustment.

Labor time:

Checking installation status of steering column adjustment

Labor time: **11 TU**

⇒ **Damage code WME3 066 000 1**

Scope 2: Checking installation status of steering column adjustment

- The vehicle is equipped with **mechanical** steering column adjustment.
- Valid for **Cayenne (9YA/ 9YB)**

Labor time:

Checking installation status of steering column adjustment

Labor time: **11 TU**

⇒ **Damage code WME3 066 000 1**

Scope 3: Matching vehicle order in the instrument cluster

- Valid for **Cayenne (9YA / 9YB), Panamera (971) and 718 (982)**

Labor time:	
Matching vehicle order in the instrument cluster	Labor time: 46 TU
Includes:	<ul style="list-style-type: none"> Checking installation status of steering column adjustment Connecting and disconnecting battery charger Connecting and disconnecting PIWIS Tester Reading out and erasing fault memories
⇒ Damage code WME3 066 000 1	

Warranty processing

Scope 1: Checking installation status of steering column adjustment

- The vehicle is equipped with **electric** steering column adjustment.

Labor time:	
Checking installation status of steering column adjustment	Labor time: 11 TU
⇒ Damage code WME3 066 000 1	

Scope 2: Not relevant for this vehicle type.

Scope 3: Matching vehicle order in the instrument cluster

- Valid for **Cayenne (9YA / 9YB), Panamera (971) and 718 (982)**

Labor time:	
Matching vehicle order in the instrument cluster	Labor time: 46 TU
Includes:	<ul style="list-style-type: none"> Checking installation status of steering column adjustment Connecting and disconnecting battery charger Connecting and disconnecting PIWIS Tester Reading out and erasing fault memories
⇒ Damage code WME3 066 000 1	

Warranty processing**Information**

The specified labor time was determined specifically for carrying out this campaign and includes all necessary preliminary work and rework.

The labor time may differ from the working times published in the Labor Operation List in the PCSS.

Scope 1: Checking installation status of steering column adjustment

- The vehicle is equipped with **electric** steering column adjustment.

Labor time:

Checking installation status of steering column adjustment

Labor time: **11 TU**

⇒ **Damage code WME3 066 000 1**

Scope 2 - 3: Not relevant for this vehicle type.

Scope 4: Matching vehicle order in the instrument cluster

- Valid for the **Macan (95B)**

Labor time:

Matching vehicle order in the instrument cluster

Labor time: **50 TU**

Includes:

- Checking installation status of steering column adjustment
- Connecting and disconnecting battery charger
- Connecting and disconnecting PIWIS Tester
- Re-coding front-end electronics
- Reading out and erasing fault memories

⇒ **Damage code WME3 066 000 1**

Warranty processing



Information

The specified labor time was determined specifically for carrying out this campaign and includes all necessary preliminary work and rework.

The labor time may differ from the working times published in the Labor Operation List in the PCSS.

Scope 1: Checking installation status of steering column adjustment

- The vehicle is equipped with **electric** steering column adjustment.

Labor time:

Checking installation status of steering column adjustment	Labor time: 11 TU
--	--------------------------

⇒ **Damage code WME3 066 000 1**

Scope 2 - 4: Not relevant for this vehicle type.

Scope 5: Matching vehicle order in the instrument cluster

- Valid for **911 (992)** and **Taycan (Y1A/Y1B/Y1C)**

Labor time:

Matching vehicle order in the instrument cluster	Labor time: 49 TU
--	--------------------------

Includes:

- Checking installation status of steering column adjustment
- Connecting and disconnecting battery charger
- Connecting and disconnecting PIWIS Tester
- Reading out and erasing fault memories

⇒ **Damage code WME3 066 000 1**

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.