

Technical product information

Topic	Bentayga - Outside Air Temperature - Incorrect reading in Fahrenheit
Market area	Bentley: worldwide (2WBE)
Brand	Bentley
Transaction No.	2060102/3
Level	EH
Status	Approval
Release date	

New customer code

Object of complaint	Complaint type	Position
information, navigation, communication, entertainment -> driver information system (DIS, MFI, MMI) -> ambient temperature display	functionality -> without function / defect	
information, navigation, communication, entertainment -> driver information system (DIS, MFI, MMI) -> ambient temperature display	functionality -> faulty display	
information, navigation, communication, entertainment -> driver information system (DIS, MFI, MMI)	functionality	

Vehicle data

Bentayga

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V*	2021	E		*	*	*

Documents

Document name
master.xml

Customer statement / workshop findings

Outside air temperature reading within the Driver Instrument Panel (DIP) is incorrect when reading in Fahrenheit

Technical background

Incorrect outside air temperature displayed, the issue relates to an incorrect algorithm

NOTE: The temperature is not displayed correctly in Fahrenheit only, the temperature is correct when displayed in Celsius

Please refer to the instructions within the Measure section of this TPI in the event the symptom is as described

Production change

-

Measure


The PDI MUST be completed prior to running the following software updates

Transferring software from the Bentley Hub to a USB-C stick

NOTE: The USB-C stick MUST be a minimum of 32 GB

1) Access the Bentley Hub

- The applicable Zip file can be found in - Aftersales - TPI's – MIB3 Kombi (zip) (Figure 1)



2) Copy the ZIP file onto the USB-C stick (Figure 2)

VERY IMPORTANT – The USB-C Stick MUST be a minimum of 32 GB



Figure 2

3) Extract the ZIP file (Figure 3)




Figure 3

4) Select the USB-C stick as the destination (Figure 4)

- Select extract




Figure 4

5) Referring to Figure 5 - The operative MUST wait until the file has completely extracted, Do Not remove the USB-C stick or stop the copying of files until 100% extracted




Figure 5

6) When the file has fully extracted, the files on the USB stick will be as shown in Figure 6




Figure 6

7) Delete the ZIP file (only) from the USB stick leaving the files shown in Figure 7




Figure 7

[Software update with USB-C stick and ODIS diagnostic tool](#)

- The closed-circuit voltage of the vehicle must be at least 12.5 V during the update. Connect a suitable battery charger to the vehicle. For further information refer to the Repair manual
- During the update switch off all unnecessary consumers (ventilation, seat heater, interior illumination etc)
- Because of the highest transmission stability you **MUST** use the diagnosis interface VAS 6154 (WiFi diagnostic tool) **ONLY** in USB operation or the cable-connected VAS 5055 for the reprogramming (updating) of control units. If these units are not available, the diagnosis interface VAS 5054 (A) can also be used in USB mode
- Do Not under any circumstances use a Bluetooth connection to conduct the reprogramming (updating) of any control units

NOTE: During the updates the system may reboot several times

Software update to address 17

1. Insert the USB-C stick into USB 1 socket (Figure 1)



Figure 1

2. Press the home screen button (Figure 2)



Figure 2

3. Using two fingers, press and hold the MMI screen in the area's highlighted by the red circles (Figure 3) until the red engineering menu appears (Figure 4). select 'Update'.



Figure 3




Figure 4

5. Select the suggested update. (Figure 5)



Figure 5

6. A summary of the proposed changes will then appear (Figure 6), scroll down and select 'Start update' (Figure 7).




Figure 6




Figure 7

7. On the following screen

- Select 'Start update' again. (Figure 8)




Figure 8

8. The software update will then begin (Figure 9)



Figure 9

9. Once the update is complete a summary screen will be displayed. (Figure 10) Scroll down and press 'Resume' (Figure 11)




Figure 10




Figure 11

10. On the next screen select 'Quit' (Figure 12), the system will then reboot. Once the home screen is displayed, remove the USB-C stick and carry out an ignition cycle.



Figure 12

11. On completion carry out the following Software version management update instructions

[Software version management update](#)

12. Select and run Guided fault finding.

- Referring to Figure 13 - Within the Special functions tab select SVM – Code Input (A) then select Perform test (B)




Figure 13

13. On the next screen enter the SVM code 4V0DCL02 and select Adopt (Figure 14)




Figure 14

14. On the following screen, confirm the code then select Yes.

- All control modules will be interrogated.
- The SVM action will then take place (Figure 15)



Figure 15

15. Once complete a summary screen will appear (Figure 16), this confirms successful completion. Follow any on screen prompts until program end



Figure 16

Warranty accounting instructions

Warrantytype 110 or 910

Damage service number 91 10

Damage code 02 02

Labour

Labour operationcode 01510000

Time As per ODIS log – Maximum of 50 Time units

Parts information

USB-C Stick (MUST be a minimum of 32 GB) - Source locally