



# Technical Service Bulletin

<b>Technical Service Bulletin:</b> TSB190091	<b>Released Date:</b> 04-Aug-2022
<b>Incorrect Pressure/Temperature Sensor: Fault Code 125, 743, 2191, 2973, 1664, 5989</b>	

## Incorrect Pressure/Temperature Sensor: Fault Code 125, 743, 2191, 2973, 1664, 5989

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

#### Product Affected

- B6.7 CM2350 B121B
- B6.7 CM2450 B155B
- ISB6.7 CM2150 (EPA 2007)
- ISB6.7 CM2250 (EPA 2010)
- ISB6.7 CM2350 B101
- ISC CM2150
- ISC CM2250
- ISL CM2150
- ISL CM2250
- ISL CM2350 L101
- ISM CM876
- ISX11.9/12 CM2250
- ISX12 CM2350 X102
- ISX15 CM2250
- ISX15 CM2350 X101
- ISX15 CM871
- L9 CM2350 L116B
- L9 CM2350 L119B
- L9 CM2450 L126B
- QSB6.7 CM2250
- QSB6.7 CM2350 B105
- QSL9 CM2250
- QSL9 CM2350 L102

- QSX15 CM2250
- QSX15 CM2350 X105
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

**Issue**

Symptom:

- Fault Codes 125, 222, 743, 2191, 2973, 1664, 5989
- Low power
- White smoke
- Engine misfire
- Aftertreatment performance complaints

Root Cause:

- Incorrect pressure/temperature sensor installed in the incorrect location on the engine.

**Verification**

- Remove the pressure/temperature sensor in question and verify pressure/temperature sensor part number.
- View pressure/temperature sensor values in a key on engine off condition using INSITE® electronic service tool or equivalent, an incorrect pressure/temperature sensor can give an incorrect value.
- At key ON engine off, the barometric air pressure should read the local barometric air pressure, and the intake manifold pressure should read 0.0 in-hg.

**Resolution**

Refer to QuickServe Online parts catalog on to determine the correct sensor to use in the correct location for a given engine.

Install correct pressure/temperature sensor. See Table 1 below for part numbers.

<b>Table 1, Sensor Part Number and Application</b>			
<b>Part Number</b>	<b>Pressure Sensing Rangemm- hg [ in-hg ]</b>	<b>Application</b>	<b>Alternate Part Numbers</b>

**Table 1, Sensor Part Number and Application**

<b>Part Number</b>	<b>Pressure Sensing Rangenm- hg [ in-hg ]</b>	<b>Application</b>	<b>Alternate Part Numbers</b>
2897332	330 mm-hg [ 13 in-hg ] to 838 mm-hg [ 33 in-hg ]	Barometric air pressure and/or turbocharger compressor intake pressure	4921850
2897333	330 mm-hg [ 13 in-hg ] to 1574.8 mm-hg [ 62 in-hg ]	Intake manifold pressure on 6.7L or smaller engines	4921322
2897334	330 mm-hg [ 13 in-hg ] to 3810 mm-hg [ 150 in-hg ]	Intake manifold pressure on 8.3L or larger engines	4921324, 2872784

**Part Identification**

- Pressure/temperature sensor part number is located on underside of pressure/temperature sensor body.
- Pressure/temperature sensor **must** be removed to verify part number. See Figure 1 for part number location. See Figure 2 for pressure/temperature sensor similarity examples.



Figure 1, Pressure/Temperature Sensor Part Number Location.



Figure 2, Pressure/Temperature Sensor Similarity Example.

## Document History

Date	Details
2019-6-5	Module Created
2019-12-20	Non-Product Problem Solving (PPS)
2021-9-20	Updated Product Affected. Added Fault Code 743.
2022-8-4	Added Fault Code 5989.

---

**Last Modified: 04-Aug-2022**

---

<https://cst.cummins.com> <http://edsprod.cummins.com> <https://gpst.cummins.com>  
<https://quickserve.cummins.com> <https://parts.cummins.com> <https://store.cummins.com>  
<https://wwsps.cummins.com> <https://access.cummins.com> <https://commerce.cummins.com>  
<https://qsservices.cummins.com> <https://webparts.cummins.com> <https://qsservices.cummins.com>  
<https://adminportal.cummins.com> [0sp4N000000PGNq https://cumminscommerce.force.com](https://cumminscommerce.force.com)  
<https://mylogin.cummins.com/web/idp/login>