

Reference	SSM75869
Models	Defender / L663 Discovery / L462 New Range Rover / L460 New Range Rover Sport / L461 Range Rover / L405 Range Rover Sport / L494 Range Rover Velar / L560
Title	"Coolant Low" warning displayed in the Instrument Cluster
Category	Engine
Last modified	24-Nov-2022 00:00:00
Symptom	402000 Cooling System Concerns
Content	<p><u>Issue:</u> Customers reporting "Coolant Low" warning displayed in the Instrument Cluster (IC) message center. Please note: Only Ingenium I63.0L Diesel/Petrol and V8 4.4L T/C Petrol</p> <p><u>Cause:</u> Unknown</p> <p><u>Action:</u></p> <ol style="list-style-type: none"> 1. Pressure test the coolant system as detailed in TOPIx section 303-03 Diagnosis and Testing Engine Cooling 2. Please ensure the following components are investigated as part of the cooling system pressure testing diagnosis: <ul style="list-style-type: none"> o Coolant expansion tank/Coolant expansion tank filler cap interface following the In-line Cooling System Pressure Test routine in TOPIx Section 303-03 o Turbo coolant and drainpipe o Thermostat housing, feed and return connections o Auxiliary water pump connections o Radiators and coolers o Water charge air coolers external & internal 3. If this is a repeat return for the customer, then conduct overnight pressure test and check level/pressure. 4. If no faults are found, please return to customer – Roadside assistance, please refer the vehicle to retailer for further investigation. 5. If a fault is found, please raise an EPQR detailing the component replaced and exactly where the leak was found. 6. If there is a loss of pressure but no leak is found, then contact TA quoting PTS_500 - Cooling.

Thank you in advance for your assistance with this matter

anBhdHRlcnM7MjAyMj0xMj0wNDoyNDor1OS4zMTRaOzEzNi4yMjYyNTUuMT10w==