

Technical Service Bulletin

01 MIL on, gasoline quality (DTC P0300 or P030x, lean condition DTCs)

01 13 09 2014753/8 June 21, 2013. Supersedes Technical Service Bulletin Group 00 number 10-01 dated February 5, 2010 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All Audi	2000 – 2015	All	Gasoline engines only

Condition

REVISION HISTORY				
Revision	Date	Purpose		
8	-	Revised header data (Added model years) Revised Service (Updated list of retailers)		
7	2/5/2010	Revised header data (Added model years, specify gasoline engines) Revised Service (Added part number)		
6	4/20/2009	Revised Condition Revised Service (Decreased additive ratio in example)		
5	1/21/2009	Revised title to add DTC codes Moved content from Warranty to Service Added tip to contact Technical Assistance Center		
4	12/18/2008	Revised Title to change Repair Group		
3	11/24/2008	Revised Title to include Repair Group		

- The use of contaminated gasoline or gasoline with a low content of deposit control additives may result in one or more of the following conditions:
 - Excessive accumulation of deposits on intake valves, intake manifold, fuel injectors and combustion chambers.
 - · Engine runs rough after cold start.
 - Excessive engine cranking time.
 - · Hesitations while driving.
 - · Rough engine idle.
 - · Reduced engine performance.
 - Poor fuel economy.

Audi

Technical Service Bulletin

 Conditions may be severe enough to illuminate the MIL in conjunction with storage of DTCs for misfire (example: P0300, P030x) and / or lean fuel system (example: P0171, P0174, P1128, P1130, P1136, P1138) in the engine control module (ECM).

Technical Background

- Condition may be caused by use of contaminated gasoline.
- · Condition may be caused by use of gasoline with a low content of deposit control additives.

Production Solution

Not applicable.

Service

If use of contaminated gasoline is suspected:

Consider advising the customer to change gasoline source (brand/gas station). Contaminated gasoline may exhibit one or more of the following characteristics:

- May have unique color and odor.
- May contain undissolved water.
- May contain sediments and suspended matter.
- May appear cloudy and (after settling) may show signs of separation.

If use of gasoline with a low content of deposit control additives is suspected:

Recommend to the customer the exclusive use of TOP TIER Detergent Gasoline, which provides improved deposit control performance. At the time of this publication, retailers in the USA providing TOP TIER Detergent Gasoline in all grades of their gasoline include:

•	76	Stations

Holiday Stationstores, Inc.

Rebel Oil

Aloha Petroleum

• Kwik Trip / Kwik Star

Road Ranger

Chevron

MFA Oil Co.

Severson Oil

Conoco

Mileage Stations

Shell

CountryMark

Mobil

Texaco

Entec Stations

Ohana Fuels

Tri-Par Oil Co.

Exxon

• Phillips 66

U.S. Oil

Hawaii Fueling Network

Quik Trip

For the most up-to-date list of TOP TIER retailers, visit www.toptiergas.com.

Audi

Technical Service Bulletin

Repair:

Gasoline additive **G 001 700 03** or **G 001770 A2** can be used for removal of existing carbon deposits from:

- Injectors (MPI and FSI engines)
- Combustion chambers (MPI and FSI engines)
- Intake valves (MPI engines only)

Mix the additive with gasoline directly in the **full** fuel tank following the mix ratio. For example, 60 ml per 30 liters gasoline, 150 ml per 20 gallons of gasoline.



Tip: For removal of carbon deposits from intake valves of FSI engines, refer to TSB 2019948.

Warranty

This TSB is informational only and not applicable to any Audi warranty. The use of gasoline additive **G 001 700 03** or **G 001770 A2** is not reimbursed under warranty.

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.