

# Technical Service Bulletin



## 01 MIL on (DTC P0087, P0088, P0192, or P119A)

01 14 01 2027306/4 October 30, 2014. Supersedes Technical Service Bulletin Group 01 number 14-83 dated July 17, 2014 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3	2008 - 2012	All	CBFA, CCTA
A4	2009 - 2012	All	CAEB
A5	2009 - 2012	All	CAEB
A5 cabriolet	2010 - 2012	All	CAEB
Q5	2011 - 2012	All	CAEB
TT	2009 - 2012	All	CCTA, CETA

## Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Updated header data (Added customer code for Elsa display)
3	7/17/2014	Updated Service (ODIS MVB adjustments)
2	10/26/2011	Updated Service (Added kPa units and MVB numbers)
1	9/28/2011	Original publication

- MIL on.
- One or more of the following DTCs may be stored in the engine control module (ECM), J623 (address word 01):
  - **DTC P0087** (Fuel Rail/System Pressure - Too Low)
  - **DTC P0088** (Fuel Rail/System Pressure - Too High)
  - **DTC P0192** (Fuel Rail Pressure Sensor "A" Circuit Low Input)
  - **DTC P119A** (Fuel Pressure Sensor -G247- Malfunction)

## Technical Background

Assistance to properly diagnose a fuel pressure sensor -G247- concern.

## Production Solution

Not applicable.

## Service

Perform Fuel Pressure Sensor Test. In Elsa, select: *Repair Manual >> Engine >> Fuel Injection and Ignition >> 24 Multiport Fuel Injection >> Diagnosis and testing >> Fuel Pressure SensorG247, Checking.*

If the difference between test gauge and MVB 106/2 *fuel pressure* (for transverse engine) or IDE00589 *regulator valve* (for longitudinal engine) on the vehicle diagnostic tester is **greater than 500 kPa**:

- Test the wiring to the fuel pressure sensor using Guided Fault Finding in the vehicle diagnostic tester.
- If the difference remains greater than 500 kPa after wiring test, replace the fuel pressure sensor.

If the difference between test gauge and MVB 106/2 *fuel pressure* (for transverse engine) or IDE00589 *regulator valve* (for longitudinal engine) on the vehicle diagnostic tester is **less than 500 kPa**:

- In Elsa, select: *Repair Manual >> Engine >> Fuel Injection and Ignition >> 24 Multiport Fuel Injection >> Diagnosis and testing >> Fuel Holding Pressure, Checking with High Pressure Pump.*
- Consider mechanical failure of the high pressure fuel pump or intake camshaft. The Technical Assistance Center (TAC) can assist with further diagnosis.

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

## Additional Information

All parts and service references provided in this TSB (2027306) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.