

Technical Service Bulletin



47 Vibration/noise from brake pedal area - pedal feels different - DTC P05FF00

47 22 22 2068205/3 December 19, 2022. Supersedes Technical Service Bulletin Group 47 number 22-20 dated November 8, 2022, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2021 – 2023	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Service</i> (Revised Procedure) Revised <i>Warranty</i> (Revised Labor Operation)
2	11/08/2022	Revised <i>Service</i> (Revised Procedure) Revised <i>Parts and Tools</i> (Added table) Revised <i>Warranty</i> (Added Labor Operation)
1	10/10/2022	Initial publication

Customer states:

During braking at low speeds, a vibration/pulsation is felt at the brake pedal, and/or the brake pedal feels “different”.

Workshop findings:

The following DTC may be stored in the ABS/ESC Control Module -J104- (address word 0003):

- **DTC P05FF00** – *Brake pressure sensor / Sensor for brake pedal travel deviation.*

The complaint can be reproduced.

Technical Background


Not applicable.

Production Solution

Under analysis.

Service

Technical Service Bulletin



1. Read out the measured value "Adaption value offset wheel brake stiffness" and upload the log to GFF Paperless.
2. Bleed the brake system fully according to *ELSA>>Workshop Manual>>Chassis>>Brake System>>47 Hydraulic Components>>Hydraulic System>>Bleeding*.
3. Clear DTCs in the J104 ABS/ESC control unit.
4. Re-evaluate the vehicle for improvements concerning noises and brake pedal feel. If the issue has been solved, release the vehicle. If the complaint is still present, repeat the bleed procedure.



Note:

For noise complaints, please upload a video/audio file to DOC-IT with the respective VIN number.

Warranty

Claim Type	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4708		
Damage Code:	0011		
Labor Operations:	Bleed brake system	4701 0750	See SRT
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 70 TU)
	Road test prior to the service procedure	0121 0002	10 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB 2068205/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2068205**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may



these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.