

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922



Subject: CONNECTED VEHICLE SYMPTOM TROUBLESHOOTING	Service Alert No.: SA-009/23
	Last Issued : 03/01/2023

BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

Previous TSBs:	Date(s) Issued:
SA-009/23	02/06/23
SA-017/22	12/13/22, 10/10/22, 08/25/22, 05/06/22, 04/04/22
SA-013/21	12/22/21, 10/13/21, 09/14/21, 05/11/21, 04/27/21, 03/15/21, 02/22/21, 02/08/21 and 02/02/2021
SA-031/20	12/09/20, 11/30/20, 11/06/20, 10/28/20, 06/16/20, 06/05/20, 06/01/20, 05/18/20, 04/14/2020, 04/02/20, 03/11/20 and 02/27/20

APPLICABLE MODEL(S)/VINS:

2019-2023 Mazda3
2020-2023 CX-30
2021-2023 CX-5
2021-2023 CX-9
2022-2023 MX-30
2023 CX-50

DESCRIPTION

Some customers may complain about any of the following:

1. Infotainment Center Display does not provide the Authorization Code (OTP) during the MyMazda App Connected Vehicle enrollment.
2. Remote function(s) inoperative.
 - Engine Start / Stop
 - Door Lock / Unlock
 - Lights ON / OFF
3. MAZDA CONNECT connected vehicle reception strength icon shows "X" or "\".










CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Index








- MAZDA CONNECT Indication
- Remote Engine Start Will Not Function
- Remote Engine Start Function Will turn engine OFF
- Deactivation Mode

MAZDA CONNECT Indication





Indication	Explanation
Mazda3, CX-30, CX-50, MX-30 	Radio waves are not being received. Move to a location with good reception.
	Weak reception.
	Good Reception
	Strong reception.
	Currently conducting an operation check of the communication unit. If this condition continues, consult an Authorized Mazda Dealer.
	Currently conducting an operation check of the onboard communication unit. NOTE: Communication is not possible during this display.
CX-5, CX-50, CX-9, MX-30 Mazda3, CX-30 built July 1, 2021 and later 	The communication function is temporarily disabled due to infotainment system setting. 
Mazda3, CX-30, CX-50, MX-30 	<ul style="list-style-type: none"> • Connected Service contract has ended (Subscription expired) • TCU has not been initialized, go to SA-004/21

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



<p>CX-5, CX-9</p> 	<ul style="list-style-type: none"> • Deactivation Mode (some models)
<p>Vehicles built before July 1, 2021</p> 	<p>Customer deactivated Connected Services (Opt-Out)</p> <ul style="list-style-type: none"> • eMDCS Warranty Vehicle Inquiry will show Campaign CSP04 Status Open
<p>Vehicles built after July 1, 2021</p> 	
<p>CX-5, CX-50, CX-9, MX-30 Mazda3, CX-30 built July 1, 2021 and later</p> <p>Connected Services Disabled message appears at engine start up</p> 	<p>Connected Services disabled (box unchecked)</p>  <p>Enable Connected Services (box checked) to prevent message appearing at engine start up.</p>  <p>Note: If customer Opted-Out (CSP04), advise customer to keep Connected Services box checked. The vehicle will not transmit data.</p>
<p>Connected Vehicle Maintenance Mode</p> 	<p>Connected Vehicle Maintenance Mode enabled. Go to MGSS SERVICE CAUTIONS FOR VEHICLES WITH TELEMATICS COMMUNICATION SYSTEM to disable Maintenance Mode.</p>

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Remote Engine Start Will Not Function under the following conditions

Item	Condition
1	Vehicle battery voltage low
2	Automatic Transmission shift position except "P"
3	Vehicles equipped with manual transmission
4	Vehicle speed above 3 mi/h (5 km/h)
5	Brake pedal switch malfunction
6	Engine has been running by remote engine start function
7	Engine started by remote engine start more than 2 consecutive times while the vehicle is not driven. The vehicle must be driven 1-mile or 24-hours must pass from the last successful Remote Engine Start for the use count to reset.
8	2021 Mazda3, 2021 CX-30, CX-50, MX-30: Vehicle's electrical control area network (CAN) is in "Sleep Mode" 
9	A registered key is detected in the vehicle
10	Brake pedal switch detects brake application
11	Low fuel warning 
12	Engine starts, then turns OFF due to abnormal high engine rpm detected. (Engine rotation over 3000 rpm continued for more than 0.2[s])
13	No engine rpm detected after sending engine start request. (Engine rotation 0 rpm continued for more than 0.2[s])
14	When the CAN data signal for engine shut off is present (e.g.: door ajar signal)
15	After 10 second maximum cranking time
16	Burglar alarm status is "Alarm" and "Alarm stand by" (CAUTION - DO NOT enable, see Theft-Deterrent System section in SA-012/20)
17	Room fuse blown/missing
18	Connected Vehicle Maintenance Mode enabled (Restricted Transmitting Mode in MDARS)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	
19	Vehicle is parked (stored) for approximately 1 week or longer or in deep sleep mode. Drive the vehicle for a few miles to recover.
20	DTC Stored 
21	Aftermarket Remote Engine Start accessory installed.
22	Mazda Remote Engine Start (BCKA-V7-620) accessory installed (No MyMazda app remote engine start function). Mazda Remote Engine Start (RES) Removal a. Remove the Mazda Remote Engine Start (RES) accessory module. b. Deactivate and activate Advanced Key(s). Refer to MGSS IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING [(US)]
23	First remote control attempt fails, second attempt works fine. Go to TSB 16-002/20 .
24	CSP04 Status Open

Remote Engine Start Function Will turn engine OFF under the following conditions

Item	Condition
1	Vehicle door(s) opened
2	Vehicle trunk opened
3	Vehicle hood opened
4	Ignition switch push button "ON" detected
5	Remote engine STOP request
6	Brake pedal switch detects brake application
7	DTC Stored
8	Engine will stop running automatically after 15 minutes for safety, security and emissions.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Deactivation Mode

Some new owners may chose not to enroll into Connected Vehicle (CV) Services. If this happens, the Telematics Communication Unit (TCU) will switch to Deactivation Mode.



Any of the following conditions will initiate Deactivation Mode:

- Customer does not enroll into CV services within 5 days from Retail Date (RDR/Warranty Start Date).
- Customer unsubscribed from CV services.
- Free trial period has expired.


NOTE:

- Customer/Dealer can activate CV services anytime via MyMazda app (there just might be a slight delay in making the backend connection since it was temporarily deactivated).
- When TCU is in Deactivation Mode, infotainment Over-the-Air (OTA) Connectivity Master Unit (CMU) software update is not possible (disabled).
- Prior to Retail Date, the TCU is active.

Mazda Connected Vehicle Viewer (MCVV) Deactivation Mode Status:

<p>1. Go to Mazda Connected Vehicle Viewer (MCVV)</p>	
<p>2. Select "Vehicle Communication Line Status Reference" 3. Enter VIN and then select "Search"</p>	
<p>Deactivation Mode Status</p>	<ul style="list-style-type: none"> • TCU Active (Status -> Opened)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Vehicle Communication Line Status Search Screen


Search Condition

VIN: JM1DRAB64P0

Search Clear

VIN	Vehicle Communication Line Status			Year and Model	Body Color
	Status	Request Date	Status Detail		
JM1DRAB64P0	Opened	02/08/2023 18:25	Open Completed 02/08/2023 18:25	2023 EV FWD W/ PREMIUM PLUS PKG	MACHINE GRAY METALLIC

- TCU in Deactivation Mode (Status -> Closed)



Vehicle Communication Line Status Search Screen

Search Condition

VIN: JM1DRAB64P0

Search Clear

VIN	Vehicle Communication Line Status			Year and Model	Body Color
	Status	Request Date	Status Detail		
JM1DRAB64P0	Closed	02/08/2023 18:25	Close Completed 02/08/2023 18:25	2023 EV FWD W/ PREMIUM PLUS PKG	MACHINE GRAY METALLIC

REPAIR PROCEDURE

CAUTION: DO NOT swap TCU with another vehicle as the TCU is VIN locked after activation. A TCU swap with another vehicle will disable Connected Services on both vehicles.

REPORATION:

1. Confirm that the TCU is at the latest software level. Go to [Telematics Communication Unit \(TCU\) Updates](#)
2. Go to [eMDCS Vehicle Inquiry](#) and confirm the following campaigns are not shown or closed:

- CSP06
- CSP07
- SSPC7
- DRW41

3. Go to [eMDCS Vehicle Inquiry](#) and confirm CSP04 is not shown.

4. Confirm the customer's phone and vehicle have good to strong reception during the concern as shown in the table below.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


- If the reception is weak, move the vehicle to a location where the reception is good to strong as shown in the table, then try to get the Authorization Code and/or operate the remote functions before proceeding to the Repair Procedure if there is still an issue.
- If the reception is good to strong, proceed to Connected Vehicle Troubleshooting below.

NOTE: Vehicles stored for long periods may loose GPS clock sychronization. If the vehicle is stored for a long period, test drive the vehicle to give the GPS clock time to sychronize before enrolling or testing connected vehicle functions.




Index

1. [Unable to create a MyMazda account](#)
2. [Remote function\(s\) inoperative](#)
3. [No One Time Pass Code \(OTP\)](#)
4. [Connected vehicle reception strength icon shows "X" or "\"](#)
5. [MyMazda App displays incorrect tire pressures \(Except CX-5 and CX-9\)](#)
6. [Unable to activate Connected Services \(2019 Mazda3\)](#)
7. [Software Update Error \(2020 Mazda3\)](#)
8. [Functions inoperative \(2021-> CX-30, CX-50, Mazda3 and MX-30\)](#)
9. [First remote control attempt fails, second attempt works fine](#)
10. [Engine turns off when opening door](#)
11. [Low Tire pressure will not clear after correcting tire pressue](#)
12. [MyMazda App does not display tire air pressures \(CX-5, CX-9\)](#)


[Educational Videos](#)
[Resources](#)

Connected Vehicle Troubleshooting		
Symptom	Cause	Action
<p>1</p> <p>The customer is not able to create a MyMazda account. The customer receives the following error:</p> <p>MyMazda App - Internal Usher SDK error.</p>	<p>Customer inadvertently texted "Stop" to 1-949 518-0058 (Twilio SMS for Mazda)</p>	<p>1. Text "Start" to 1-949 518-0058 (Twilio SMS for Mazda)</p> <p>2. Retry to create a MyMazda account.</p> <p>NOTE: USA and Canada only</p> 


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

 <p>Verify Your Phone</p> <p>Please enter and verify your mobile phone number to continue.</p> <p>Error</p> <p>Internal Usher SDK error.</p> <p>OK</p> <p>MyMazda will send an SMS to verify your mobile phone number (carrier charges may apply).</p> <p>NEXT</p> <p>MyMazda Website - ERROR! Unable to send one-time password.</p>  <p>CONFIRM MOBILE PHONE NUMBER</p> <p>ERROR!</p> <p>Unable to send one-time password. Please try again. If this persists, please contact Mazda Customer Experience Center at 800-222-5500.</p> <p>OK</p>		
<p>2</p> <p>Remote function(s) inoperative.</p> <ul style="list-style-type: none"> • Engine Start / Stop • Door Lock / Unlock • Lights ON / OFF 	<p>Go to the MyMazda App to view the reason for remote function failure.</p>	<p>Push Notification</p>  <p>OS Lock Home Inbox</p>

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		<p>Screen Tap the push notification</p>	<p>Tap the alert card</p>	<p>Detail Tap "check vehicle status"</p>	
		<p>Activity History</p>	<p>Go to the MyMazda App INBOX -> ACTIVITY HISTORY -> to view reason for remote function failure.</p> 		
	<p>Campaign Status</p>	<p>Go to eMDCS Vehicle Inquiry and confirm the following campaigns are not shown or closed:</p> <ul style="list-style-type: none"> • CSP06 • CSP07 • SSPC7 • DRW41 <p>1. Use MDARS to ID the vehicle and check for DTC's stored. Are DTC(s) stored?</p> <ul style="list-style-type: none"> • Yes - Go to MGSS and perform normal DTC diagnostics. • No - Go to next step. <p>2. Confirm TCU software version is at the following using TCU Software Version Check</p> <ul style="list-style-type: none"> • Mazda3 - 10006 or later • CX-30 - 10006 or later • CX-5 - 10023 or later • CX-9 - 10023 or later • MX-30: 10019 or later • CX-50: 10003 or later <p>3. Disconnect battery for 30 seconds and then reconnect (KAM reset). NOTE: Test drive vehicle after battery disconnect to allow the GPS clock to synchronize before retrying Authorization Code.</p> <p>4. Perform one of the following:</p>			



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		<ul style="list-style-type: none"> • Customer: Un-enroll Connected Services, then re-enroll into Connected Services as a new primary user. • Dealer: Perform customer take-over enrollment for test confirmation, then at customer pick-up, inform customer to re-enroll into Connected Services as a new primary user. <p>5. Contact Hotline for additional technical support if needed.</p>
	Only a single remote request can be made per 60-second period	Customer needs to wait 60 seconds for the initial request cycle to be completed to make the second request.
	Remote Transmitter Key(s) in the vehicle	Do not leave keys in vehicle.
	<p>1. Aftermarket Remote Engine Start accessory installed.</p> <p>2. Mazda Remote Engine Start (BCKA-V7-620) accessory installed.</p> 	<p>1. Remove the aftermarket accessory.</p> <p>2. The customer can use either the Mazda Remote Engine Start accessory or the MyMazda app function. Cannot use both.</p> <p>Mazda Remote Engine Start (RES) Removal</p> <p>a. Remove the Mazda Remote Engine Start (RES) accessory module.</p> <p>b. Deactivate and activate Advanced Key(s). Refer to MGSS IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING [(US)].</p>
	TCU in "deep sleep" mode due to vehicle being parked for a long period.	Advise customer to drive the vehicle as normal (at least several miles) and the Connected Services should start working again.
	Low fuel	Advise customer that Remote Engine Start may start vehicle temporarily, but vehicle will turn off automatically when the fuel level is low to conserve the remaining fuel.
	Vehicle is equipped with Manual Transmission	Advise customer that vehicles with a manual transmission do not have the Remote Engine Start/ Stop function capability.
	Engine started	Advise customer they will see an error message when

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		with key transmitter instead of MyMazda App.	attempting to make a Remote Engine Off request if they initially turned on vehicle with a physical key (instead of through their MyMazda app).
3	No One Time Passcode (OTP) (Vehicle infotainment center display does not provide the Authorization Code during the MyMazda App enrollment)	Campaign Status	<p>Go to eMDCS Vehicle Inquiry and confirm the following campaigns are not shown or closed:</p> <ul style="list-style-type: none"> • CSP06 • CSP07 • SSPC7 • DRW41
		Customer deactivate Connected Services (Opt-Out))	<p>Go to eMDCS Vehicle Inquiry. Does eMDCS show CSP04 status closed?</p> <ul style="list-style-type: none"> • Yes - Customer opt-out. No action needed. • No - CSP04 is not shown. Go to next Action below.
		Troubleshooting needed	<ol style="list-style-type: none"> 1. Use MDARS to ID the vehicle and check for DTC's stored. Are DTC(s) stored? <ul style="list-style-type: none"> • Yes - Go to MGSS and perform normal DTC diagnostics. • No - Perform ODR Data Collection Procedure, then go to step 2. 2. Confirm TCU software version is at the following using TCU Software Version Check. <ul style="list-style-type: none"> • Mazda3 - 10006 or later • CX-30 - 10006 or later • CX-5 - 10023 or later • CX-9 - 10023 or later • MX-30: 10019 or later • CX-50: 10003 or later 3. 2019 Mazda3 Only - Confirm CMU software version is at 11012 or later. 4. Retrieve MAZDA CONNECT CMU log data. Go to MGSS -> Infotainment -> MAZDA CONNECT CMU Data Retrieval 5. Perform "Activating Remote Control by Smart Phone" (links TCU to BCM) 6. Clear DTC(s). <p>NOTE: If DTC 2050:55 is stored, go to SA-003/20 to clear DTC.</p> <ol style="list-style-type: none"> 7. Perform KAM reset. <p>NOTE: Test drive vehicle after a KAM reset to allow the GPS clock to synchronize before retrying</p>


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

			Authorization Code. 8. Contact Hotline for additional technical support if needed.
4	MAZDA CONNECT connected vehicle reception strength icon shows "X" or "\". Mazda3, CX-30, CX-50, MX-30  CX-5, CX-9 	Campaign Status	Go to eMDCS Vehicle Inquiry and confirm the following campaigns are not shown or closed: <ul style="list-style-type: none"> • CSP06 • CSP07 • SSPC7 • DRW41
		Customer deactivate Connected Services (Opt-Out))	Go to eMDCS Vehicle Inquiry . Does eMDCS show CSP04 status closed? <ul style="list-style-type: none"> • Yes - Customer opt-out. No action needed. • No - CSP04 is not shown. Go to next Action below.
		No reception	1. Check for DTCs. Are there any DTC's stored? <ul style="list-style-type: none"> • Yes: Go to MGSS for normal DTC diagnosis. • No: Go to next step. 2. Confirm TCU software version is at the following using TCU Software Version Check . <ul style="list-style-type: none"> • Mazda3 - 10006 or later • CX-30 - 10006 or later • CX-5 - 10023 or later • CX-9 - 10023 or later • MX-30: 10019 or later • CX-50: 10003 or later 3. 2019 Mazda3 Only - Confirm CMU software version is at 11012 or later. 4. Disconnect battery terminal for 30 seconds, then test drive the vehicle. Is the reception strength signal normal? <ul style="list-style-type: none"> • Yes: Repair complete. • No: Go to next step. 5. Perform TCU activation. Go to SA-004/21 . Is the reception strength signal normal? <ul style="list-style-type: none"> • Yes: Repair complete. • No: Go to next step. 6. Compare Tel antenna No. 1 signal strength with good known vehicle near by. Go to DIAGNOSTIC


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]
 Functional Inspection / Adjustment -> Navigation System Inspection


Good - Contact Hotline for technical support



No Good - Swap Tel antenna No. 1 with known good vehicle



5
 Except CX-5 and CX-9
 MAZDA CONNECT and/or MyMazda App displays incorrect tire pressures after battery disconnect and/or infotainment CMU software update.



Incorrect calendar entry (month/day/year) after a battery disconnect or infotainment system software update.

Go to [SA-002/21](#)




6
 2019 Mazda3 only

- The customer is not able to activate Connected Services via the MyMazda app after CSP06 completion.
- MAZDA CONNECT connected vehicle reception strength icon is missing or shows unsubscribed


Improper telematics communication unit (TCU) software.

Go to [CSP07](#) Repair instructions.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.




	<p>after CSP06 completion.</p> 		
<p>7</p>	<p>2020 Mazda3 only</p> <ul style="list-style-type: none"> • Infotainment center display does not provide the Authorization Code • Infotainment center display “Software Update Error” message 	<p>Enrollment error</p>	<p>Go to SSPC1</p>
<p>8</p>	<p>2021 Mazda3, CX-30, CX-50, and MX-30 functions inoperative</p> <ul style="list-style-type: none"> • Vehicle Status Alert • Remote Engine Start / Stop • Remote Door Lock / Unlock • Remote Hazard Lights ON / OFF • Vehicle Finder (vehicle location mapping function is available) 	<p>Vehicle's electrical control area network (CAN) is in "Sleep Mode"</p>	 <p>or</p> <p>No dealer visit is required. Sleep Mode can be reset by starting the engine and idling or driving for 5 minutes or longer.</p> <p>Go to 09-010/22.</p>
<p>9</p>	<p>First remote control attempt fails, second attempt works fine.</p> <ul style="list-style-type: none"> • Engine Start / Stop 	<p>Improper telematics communication unit (TCU) software.</p>	<p>Go to TSB 16-002/20.</p>

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	<ul style="list-style-type: none"> • Door Lock / Unlock • Lights ON / OFF 		
10	Engine turns off when customer opens vehicle door.	Normal Operation	Advise that, for customer's safety and security, vehicle is designed to shut-off automatically when the vehicle door is opened.
11	<ul style="list-style-type: none"> • Low Tire pressure will not clear after correcting tire pressure. • Vehicle status is inaccurate. 	MyMazda App is not real time.	<ul style="list-style-type: none"> • Customer must go to MyMazda app's Inbox and read/open all the messages related to the low tire pressure alert, then the "Low tire pressure" alert will clear from MyMazda app's Health Report • Message will clear after next drive cycle.
12	<p>CX-5, CX-9 The MyMazda App does not display tire air pressures</p> 	CX-5 and CX-9 Normal Operation	No action Needed


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

ODR Data Collection Procedure


<p>1. ID the vehicle using MDARS</p> <p>2. Select "Toolbox"</p>	 <p>The screenshot shows the Mazda diagnostic software interface. At the top, there is a navigation bar with 'Quick Check' and 'Toolbox' buttons. The 'Toolbox' button is circled in red, and a red arrow points to it. Below the navigation bar is a grid of diagnostic tool buttons for various systems: ABS, AFS/ALM, AM, BSML, BSMR, CMU, DSM, EATC, EPB, EPS, F_BCM, FSC, GWU, HUD, IC, PCM, PLG, R_BCM, RCM, SBS/MRCC, SSU, TCM, TCJ, and VMC. A legend at the bottom indicates the status of DTCs: green for 'No DTCs', red for 'Communication Error', blue for 'No Communication or Not Equipped', orange for 'DTC(s) exist', and grey for 'DTC Not Supported'.</p>
<p>3. Select Vehicle Icon</p>	 <p>The screenshot shows the Mazda diagnostic software interface. The 'Toolbox' button is circled in red, and a red arrow points to it. Below the navigation bar, there is a section for 'Activating or deactivating flexible setting for Maintenance Monitor' with 'Not Run' and 'Run' buttons.</p>
<p>4. Expand "Collect Diagnostic Information"</p>	 <p>The screenshot shows the Mazda diagnostic software interface. The 'Collect Diagnostic Information' option is expanded, and a red circle and arrow point to it. The expanded list includes: ENGINE (SKYACTIV-D), DRIVELINE/AXLE, BRAKES, RESTRAINTS, SECURITY AND LOCKS, LIGHTING SYSTEMS, ENTERTAINMENT, POWER SYSTEMS, i-ACTIVSENSE, Mazda Connect, and Collect Diagnostic Information. Below the list, there are 'Vehicle History', 'Not Run', and 'Run' buttons.</p>

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


5. Select Collecting diagnostic information "Run".



6. Turn the ignition ON, then select "Next"




7. Wait for collection to complete.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


8. Confirm that the ODR collection has been successful. Select "Next" to exit.



Activating Remote Control by Smart Phone (links TCU to BCM)

NOTE: This procedure cannot be performed if the key transmitter power saving function is enabled. See [SA-040/20](#).

1. Connect MDARS.



2. Use MDARS to verify if the Telematics Control Unit (TCU) is at the latest software level (Toolbox > Software Update > Run > TCU).


Is the TCU at the latest software level?

- **Yes:** Go to step 3.
- **No:** Update TCU software, then go to step 3.

3. Select the following:

- a. Toolbox
- b. Repair icon
- c. MAZDA CONNECT
- d. Activating Remote Control by Smart Phone
- e. RUN.


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



4. Follow the on-screen instructions and wait for process to complete.

NOTE: If the Activating Remote Control by Smart Phone shows "Incomplete", the possible causes are:


- The advanced key is not in the vehicle.
- The connected Vehicle Maintenance Mode is enabled.
- The Key transmitter power saving function is enabled.
- The pacemaker radio wave interference prevention function is enabled.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

5. Select Quick Check (A), then start the engine and select the DTC Clear icon (B).


CAUTION: If the engine is not started, DTC P2610 is stored and cannot be erased.




TCU Software Version Check

1. Press and hold the Volume knob, then press and hold the Entertainment and Favorite buttons at the same time for 3-5 seconds and the Factory/Service Inspection screen will appear.


CX-5 and CX-9




CX-30, CX-50, Mazda3 and MX-30



2. Select Service Information.



3. Select TCU Linked information.




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

4. Scroll down to TCU Software Version and confirm the software version is at:

- Mazda3 - 10006 or later
- CX-30 - 10006 or later
- CX-5 - 10023 or later
- CX-9 - 10023 or later
- MX-30: 10019 or later
- CX-50: **10003 or later**

Is the TCU software version correct?

- **Yes:** TCU Software Version Check is complete.
- **No:** Go to [Telematics Communication Unit \(TCU\) Updates](#) to update the TCU software version.



Educational Videos

[Overview](#)
[Using MyMazda App](#)
[In-car Wi-Fi hotspot](#)
[MyMazda remote](#)
[Notifications](#)
[Safety features](#)

Resources

[SA-019/22 - MAZDA CONNECTED SERVICES - FREQUENTLY ASKED QUESTIONS \(FAQ\)](#)
[Connected Services Owner's Manual](#)
[MAZDA CONNECT and MAZDA CONNECTED SERVICES USER GUIDE](#)
[MAZDA CONNECTED VEHICLE VIEWER \(MCVV\) USER GUIDE](#)
[MAZDA CONNECT ESSENTIALS WBT \(30076\)](#)
[MAZDA CONNECT & CONNECTED SERVICES FOCAL POINT \(30093FOC\)](#)
[MAZDA CONNECTED SERVICES SMART CARDS](#)
[MAZDA CONNECTED SERVICES: CUSTOMER OUTREACH](#)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.