



<b>Subject:</b>  WATER, SOAP, OR WASHER FLUID ENTERING THE HVAC SYSTEM	<b>Service Alert No.:</b> SA-012/23
	<b>Last Issued :</b> 03/01/2023

## BULLETIN NOTES

### APPLICABLE MODEL(S)

2013-2023 CX-5	2016-2023 CX-3	2020-2023 CX-30
2014-2023 Mazda3	2016-2023 CX-9	2022-2023 MX-30
2014-2021 Mazda6	2016-2023 MX-5	2023 CX-50
2016-2023 Mazda2 (PR and Mexico spec)		

## DESCRIPTION

Some customers may report an odor or water in the HVAC system and upon inspection, the cabin air filter may be found to be wet.

## REPAIR PROCEDURE

1. Verify the HVAC and cowl drains are not restricted by debris or have hoses detached.
  - a. Pour some water onto the cowl and make sure the water drains correctly. If the water drains out slowly, verify the drains are not restricted.
  - b. Verify all drain hoses are attached to the HVAC unit and not restricted. If the cabin air filter is wet, replace it.
2. Because some car washes may use too much soap or have the water pressure set too high, instruct the customer to do the one of the following before entering a car wash
  - Set the HVAC system to recirculate with the blower at the lowest setting.
  - Turn off the HVAC system (until they exit the car wash).

**NOTE:** If water continues to enter the HVAC system after following the instructions in step 2, contact Mazda Technical Hotline.

## WARRANTY INFORMATION

If the drains are disconnected this is covered under warranty, otherwise customer pay. Use DSA if blocked by debris, CAF replacement.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.