

TECHNICAL SERVICE BULLETIN

Classification: Reference: Date:

AN23-006 ITB23-010 March 8, 2023

SOFTWARE UPDATE FOR INFOTAINMENT ISSUES

APPLIED VEHICLES: 2016-2023 Q50 (V37)

2017-2022 Q60 (CV37) 2018-2019 Q70 (Y51) 2017-2019 QX30 (H15) 2019-2023 QX50 (J55) 2022-2023 QX55 (FJ55) 2015-2020 QX60 (L50) 2022-2023 QX60 (L51) 2015-2023 QX80 (Z62)

SERVICE INFORMATION

When diagnosing an infotainment issue or after replacement of the AV Control Unit, it is necessary to verify the current software version of the AV Control Unit to determine if a software version update is required.

Use the vehicle tables in this bulletin to determine the current software version, if the AV Control Unit requires a software version update, and which procedure to use to update the AV Control Unit.

The software updates in this bulletin are to address stability improvements and "bug" fixes.

IMPORTANT: If the client is experiencing a software related concern, refer to ITB21-011 to verify if the client concern is a hardware or software related issue. If the concern is a software related issue, review the information in this bulletin to update the AV Control Unit as needed.

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.

REQUIRED SPECIAL TOOL

- One of special tool USB drive J-52727-1 (new tool number NI-52727-1) has been previously shipped to each retailer (Figure 1).
- Do not use any other USB drive to perform the procedure in this bulletin.
- Additional USB drives may be purchased from Tech•Mate: www.techmatetools.com or 1-833-397-3493.

HINT:

- The update-software only needs to be downloaded once and can then be used continuously on multiple APPLIED VEHICLES.
- o The update-software <u>must be</u> the only file on the USB drive.



Figure 1

2/29

ITB23-010

HOW TO READ THE VEHICLE TABLES

Model Name			
Model Code			
Model Year	Vehicle identification section		
Grade			
Notes			
Applicable Campaign	Refer to Service Comm to check if the campaign applies to your VIN. Perform applicable campaign before proceeding.		
Software Version Check Procedure	Refer to the procedure listed in this section to check for the current AV Control Unit software version.		
AV Control Unit Software Install Procedure	Refer to the procedure listed in this section to install the new AV Control Unit software version, if applicable.		
Software Version Update Confirmation Procedure	Refer to the procedure listed in this section to verify the new AV Control Unit software version was installed properly.		
Software History	Software version history is listed from oldest to newest version. HINT: Software version numbers may not always increase with a newer version. In some cases, the newer software version may have a lower numerical number from the previous version.		
Latest Software Version	This is the latest software version. If more than one version is listed, all versions are equivalent. Do not update the AV Control Unit if the current version number is listed in this box		
Infotainment Update- Software	This is the update-software package needed from ASIST.		
Update Method	This shows if the update is performed via USB or OTA (Over-The-Air).		
Claims Information Identifier	Refer to this Claims Information section for the correct labor operation for the vehicle.		
Last Updated	Date of when each column was last updated.		

2016-2019 Q50 (V37)

Model Name		Q	50	
Model Code		V:	37	
Model Year	2016	2017	2018	2019
Grade	All	All	All	All
Notes				
Applicable Campaign			ITB19-033	ITB19-033
Software Version Check Procedure AV Control Unit Software Install Procedure Software Version Update Confirmation Procedure Oldest Software History Latest Software Version	Refer to ITB18-040	Refer to ITB18-040	Refer to ITB18-040	No Software Updates Available
Infotainment Update- Software Update Method Claims Information Identifier				
Last Updated	3/8/23	3/8/23	3/8/23	3/8/23

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

2020-2023 Q50 (V37)

Model Nar	me	Q50					
Model Cod	de	V37					
Model Yea	ar	2020			2023		
Grade		All	All	All	All		
Notes							
	e Campaign						
Software \ Procedure	Version Check	SW Check 1	SW Check 1	SW Check 1	SW Check 1		
AV Contro Install Pro	ol Unit Software cedure	Install 1	Install 1	Install 1	Install 1		
	Version Update ion Procedure	N/A	N/A	N/A	N/A		
	Oldest	2913	2950	2993	4823		
		2916	2959	4710			
		2922	2992	4803			
		2950	2993	4823			
0-4		2959	4710				
Software		2992	4803				
History		2993	4823				
		4710					
		4803					
	7	4823					
	V						
Latest Sof	tware Version	3192	3192	3192	3192		
Infotainme Software	ent Update-	PIVI21_3192	PIVI21_3192	PIVI21_3192	PIVI21_3192		
Update Me	ethod	USB	USB	USB	USB		
	ormation Identifier	CL1	CL1	CL1	CL1		
Last Upda	ted	3/8/23	3/8/23	3/8/23	3/8/23		

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

2017-2022 Q60 (CV37)

Model Name	Q60					
Model Code	CV37					
Model Year	2017	2018	2019	2020	2021	2022
Grade	All	All	All	All	All	All
Notes						
Applicable Campaign		ITB19-033	ITB19-033			
Software Version Check Procedure				SW Check 1	SW Check 1	SW Check 1
AV Control Unit Software Install Procedure				Install 1	Install 1	Install 1
Software Version Update Confirmation Procedure				N/A	N/A	N/A
Oldest				2913	2950	2993
				2916	2959	4710
				2922	2992	4803
			N 0 6	2950	2993	4823
Coffware	Refer to	Refer to	No Software	2959	4710	
Software History	ITB18-040	ITB18-040	Updates Available	2992	4803	
Flistory			Available	2993	4823	
				4710		
				4803		
				4823		
V						
Latest Software Version				3192	3192	3192
Infotainment Update-				PIVI21_3192	PIVI21_3192	PIVI21_3192
Software						
Update Method				USB	USB	USB
Claims Information Identifier	0 /0 /00	0/0/00	0/0/00	CL1	CL1	CL1
Last Updated	3/8/23	3/8/23	3/8/23	3/8/23	3/8/23	3/8/23

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

2018-2019 Q70 (Y51)

Model Name	Q7	0	
Model Code	Y51		
Model Year	2018	2019	
Grade	All	All	
Notes			
Applicable Campaign		ITB19-033	
Software Version Check Procedure			
AV Control Unit Software Install Procedure			
Software Version Update Confirmation Procedure			
Software History	Refer to ITB18-040	No Software Updates Available	
Latest Software Version			
Infotainment Update-			
Software			
Update Method			
Claims Information Identifier			
Last Updated	3/8/23	3/8/23	

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

2017-2019 QX30 (H15)

Model Name		QX30			
Model Code	H15				
Model Year	2017	2018	2019		
Grade	All	All	All		
Notes					
Applicable Campaign		ITB19-033	ITB19-033		
Software Version Check Procedure					
AV Control Unit Software Install Procedure					
Software Version Update					
Confirmation Procedure					
Oldest					
Software History	Refer to ITB18-040	Refer to ITB18-040	No Software Updates Available		
Latest Software Version					
Infotainment Update-Software					
Update Method					
Claims Information Identifier					
Last Updated	3/8/23	3/8/23	3/8/23		

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

2019-2023 QX50 (J55)

Model Na	me	QX50				
Model Co	de	J55				
Model Yea	ar	2019	2020	2021	2022	2023
Grade		All	All	All	All	All
Notes						
Applicab	le Campaign	ITB19-033				
Software 'Procedure	Version Check		SW Check 1	SW Check 1	SW Check 1	
AV Contro Install Pro	ol Unit Software ocedure		Install 1	Install 1	Install 1	
	Version Update ion Procedure		N/A	N/A	N/A	
	Oldest		2922	2950	2993	
			2950	2959	4710	
0 "		D () ITD (0.044	2959	2992	4803	No Software
Software		Refer to ITB18-041	2992	4710	4821	Updates Available
History			4710	4823	4823	
	7		4823			
Latest Sof	ftware Version		3192	3192	3192	
Infotainme Software	ent Update-		PIVI21_3192	PIVI21_3192	PIVI21_3192	
Update M	ethod		USB	USB	USB	
Claims Inf	formation Identifier		CL1	CL1	CL1	
Last Upda	ated	3/8/23	3/8/23	3/8/23	3/8/23	3/8/23

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

2022-2023 QX55 (FJ55)

Model Name		QX55				
Model Code		FJ55				
Model Year		2022	2023			
Grade		All	All			
Notes						
Applicable Can	npaign					
Software Versio Procedure	n Check	SW Check 1				
AV Control Unit Install Procedure		Install 1				
Software Versio Confirmation Pro		N/A				
	Oldest	2992				
		2993	No Coftwore Hedeter			
Software		4710	No Software Updates Available			
		4803	Available			
History		4823				
Latest Software Version		3192				
Infotainment Update-Software		PIVI21_3192				
Update Method		USB				
Claims Informati	ion Identifier	CL1				
Last Updated		3/8/23	3/8/23			

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

2015-2020 QX60 (L50)

Model Name			QX60		
Model Code			L50		
Model Year	2015-2016	2017	2018	2019	2020
Grade	All	All	All	All	All
Notes					
Applicable Campaign			ITB19-033	ITB19-033	
Software Version Check Procedure AV Control Unit Software Install Procedure Software Version Update Confirmation Procedure Oldest Software History Latest Software Version Infotainment Update- Software	No Software Updates Available	Refer to ITB18-040	Refer to ITB18-040	No Software Updates Available	No Software Updates Available
Update Method Claims Information Identifier					
Last Updated	3/8/23	3/8/23	3/8/23	3/8/23	3/8/23

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

2022-2023 QX60 (L51)

Model Name		QXI	60
Model Code		L5	1
Model Year		2022	2023
Grade		All	All
Notes			
Applicable Cam	npaign		
Software Version Procedure	n Check	SW Check 2	SW Check 2
AV Control Unit		Install 2	Install 2
Software Version Confirmation Pro		N/A	N/A
	Oldest	283C3 1420B	283C3 1420B
	_	283C3 1480B	283C3 1480B
0 - 44		283C3 1570B & 1580B	283C3 1570B & 1580B
Software			
History			
Latest Software	Version	283C3 1890B	283C3 1890B
Infotainment Upo	date-Software	PIVI31_1890	PIVI31_1890
Update Method		USB & OTA	USB & OTA
Claims Informati	on Identifier	CL1	CL1
Last Updated		3/8/23	3/8/23

IMPORTANT for 2022 and 2023 ONLY: The current AV Control Unit software version must be 283C3 1570B or 283C3 1580B before the AV Control Unit can be updated to 283C3 1890B. If the current AV Control Unit software version <u>is not</u> 283C3 1570B or 283C3 1580B, the AV Control Unit must be updated to 283C3 1570B (PVI_1570) first, and then updated to 283C3 1890B.

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

2015-2020 QX80 (Z62)

Model Name			QX	(80		
Model Code		Z62				
Model Year		2015-2017	2018	2019	2020	
Grade		All	All	All	All	
Notes						
Applicable Campaign)		ITB19-033	ITB19-033		
Software Version Chec Procedure	ck				SW Check 1	
AV Control Unit Softwa Install Procedure	are				Install 1	
Software Version Update Confirmation Procedure					N/A	
Old	lest				2922	
					2950	
0.4		No Software Updates	D (ITD (0 0 (0	No Software Updates	2959	
Software		Available	Refer to ITB18-040	Available	2992	
History					4823	
	7					
	\checkmark					
Latest Software Version					3192	
Infotainment Update-						
Software					PIVI21_3192	
Update Method					USB	
Claims Information Ide	ntifier				CL1	
Last Updated		3/8/23	3/8/23	3/8/23	3/8/23	

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

2021-2023 QX80 (Z62)

Model Name)		QX80	
Model Code			Z62	
Model Year		2021	2022	2023
Grade		All	All	All
Notes				
Applicable (
Software Ve Procedure	rsion Check	SW Check 1	SW Check 2	SW Check 2
AV Control Unstall Proce	Jnit Software dure	Install 1	Install 2	Install 2
Software Ve Confirmation	rsion Update n Procedure	N/A	N/A	N/A
	Oldest	2922	283C3 1310B	283C3 1510B
		2950	283C3 1480B	
Coffuers		2959	283C3 1570B & 1580B	
Software		2992		
History		4823		
	7			
	V			
Latest Softw	are Version	3192	283C3 1890B	283C3 1890B
Infotainment Software	Update-	PVI_v4823	PIVI31_1890	PIVI31_1890
Update Meth	nod	USB	USB & OTA	USB & OTA
Claims Infor	mation Identifier	CL1	CL1	CL1
Last Update	d	3/8/23	3/8/23	3/8/23

IMPORTANT for 2022 ONLY: The current AV Control Unit software version must be 283C3 1570B or 283C3 1580B before the AV Control Unit can be updated to 283C3 1890B. If the current AV Control Unit software version <u>is not</u> 283C3 1570B or 283C3 1580B, the AV Control Unit must be updated to 283C3 1570B (PVI_1570) first, and then updated to 283C3 1890B.

HINT: Technician notes should include claims information identifier. Example: "Performed **CL1**"

SOFTWARE VERSION CHECK

SW Check 1

1. Press and hold the **AUDIO** button while, at the same time, rotating the volume knob left-right-left.



Figure 2

2. Select Confirmation/Adjustment.




Figure 3

3. Select Version Information.



Figure 4

SW Check 1 (continued)

- 4. Confirm the **Software Version**.
 - If the Software Version
 (characters 6-9, as shown in Figure 5) is not the latest software version listed in the vehicle table, select the back icon and continue to step 5.
 - If the Software Version is the latest software version listed in the vehicle table, an update is not available. Select the back icon and skip to CLAIMS INFORMATION on the last page.



Figure 5

5. Download the infotainment update-software from ASIST to the special tool USB drive.

IMPORTANT:

- Refer to steps 36 44 on pages 26 28 for instructions on how to download the infotainment update-software from ASIST.
- For step 39 on page 27, refer to the vehicle table to determine the correct infotainment update-software for your vehicle.
- When steps 36 44 on pages 26 28 have been completed, refer to the vehicle table to determine the correct AV CONTROL UNIT SOFTWARE Install Procedure to perform.

SW Check 2

6. Starting from the HOME screen (Figure 6), select **Info**.



Figure 6

7. Select **System Information**.



Figure 7

8. Select Version Information.



Figure 8

SW Check 2 (continued)

- 9. Confirm the **Software Version**.
 - If the Software Version is not the latest software version listed in the vehicle table, select the back icon and continue to step 10.
 - If the Software Version is the latest software version listed in the vehicle table, an update is not available. Select the back icon and skip to CLAIMS INFORMATION on the last page.



Figure 9

10. Download the infotainment update-software from ASIST to the special tool USB drive.

IMPORTANT:

- Refer to steps 36 44 on pages 26 28 for instructions on how to download the infotainment update-software from ASIST.
- For step 39 on page 27, refer to the vehicle table to determine the correct infotainment update-software for your vehicle.
- When steps 36 44 on pages 26 28 have been completed, refer to the vehicle table to determine the correct AV CONTROL UNIT SOFTWARE Install Procedure to perform.

AV CONTROL UNIT SOFTWARE INSTALL

Install 1

- 11. Set the parking brake.
- 12. Start the engine, and then wait 60 seconds for the system to load.


HINT: The engine needs to idle for the duration of the update to retain battery charge.

- 13. Insert the USB drive with the infotainment update-software into the vehicle's <u>USB</u> media port (Figure 10).
 - Do not remove the USB drive during the update to the vehicle until instructed to.

NOTICE

<u>Do not insert the USB drive into a charging port</u>. If used, the update-software and/or USB drive may become damaged. Only insert the USB drive in a USB media port.

HINT: Charging ports are marked in the vehicle with a "lightning bolt" symbol.






Figure 10

Figure 11

- 14. Wait for the update to complete.
 - Follow the on-screen instructions while waiting.

HINT: The update lasts 15-25 minutes.



Figure 12

Install 1 (continued)

15. Once the update is complete (Figure 13), remove the USB drive; the system will reboot (restart).

HINT: The system will not reboot until the USB drive is removed.




Figure 13

NOTICE

Steps 16 - 23 must be completed. If they are not completed, the update may become corrupted.

- 16. Allow the reboot to complete (approximately 30 seconds).
 - The Infiniti logo will be displayed during the reboot.



Figure 14

17. Turn the ignition OFF.

The steps below will fully reboot the infotainment system twice.

- 18. Open and close the driver (LH) door, and then ensure that all doors are closed.
- 19. Wait 5 minutes.

NOTICE

Ensure that all doors remain closed during the 5-minute wait period. If a door is opened during the 5-minute wait period, the update may not complete and the AV Control Unit may become inoperable.

HINT: The engine does not need to be running for the next steps.

- 20. Turn the ignition ON (engine OFF) and wait for the Infiniti logo to appear (Figure 14).
 - If the Infiniti logo does not appear (this might take up to 30 seconds), start over from step 17.

Install 1 (continued)

- 21. After the Infiniti logo appears, wait about 1 minute.
 - The MENU (Home) screen in Figure 15 will be displayed.
- 22. Turn the ignition OFF.



Figure 15

23. Repeat steps 18 - 22 on pages 20 and 21 one more time (for a total of 2 times) to complete the update.

Install 2

- 24. Set the parking brake.
- 25. Start the engine, and then wait 60 seconds for the system to load.


HINT: The engine needs to idle for the duration of the update to retain battery charge.

- 26. Insert the USB drive with the infotainment update-software into the vehicle's <u>USB</u> media port (Figure 16).
 - Do not remove the USB drive during the update to the vehicle until instructed to.

NOTICE

<u>Do not insert the USB drive into a charging port</u>. If used, the update-software and/or USB drive may become damaged. Only insert the USB drive in a USB media port.

HINT: Charging ports are marked in the vehicle with a "lightning bolt" symbol.



- 27. Wait for the update to complete.
 - Follow the on-screen instructions while waiting.

HINT: The update lasts 20-30 minutes.



Figure 18

Install 2 (continued)

28. Once the update is complete (Figure 19), remove the USB drive; the system will reboot (restart).

HINT: The system will not reboot until the USB drive is removed.




Figure 19

NOTICE

Steps 29 - 34 must be completed to reinitialize the AV Control Unit. If they are not completed, the update may become corrupt.

29. Press and hold the **MENU** button on the IT Commander (Figure 20) and turn the AV Control Unit volume knob (Figure 21) left-right-left at the same time.





Figure 20 Figure 21

Install 2 (continued)

30. Select Confirmation/Adjustment.




Figure 22

31. Select Initialize Settings.




Figure 23

32. Select User Data Initialization.




Figure 24

Install 2 (continued)

33. Select Yes.




Figure 25

34. Select Yes.



Figure 26

- 35. Instruct the client to go into their Bluetooth phone settings and perform the actions below.
 - a. Delete/erase the vehicle from the phone's Bluetooth menu.
 - b. Re-pair the phone.

IMPORTANT: If step 35 is not completed, the phone may not connect with the vehicle while attempting to pair the phone to the vehicle.

Download Update-Software from ASIST

IMPORTANT: Before starting, make sure:

- The CONSULT PC is connected to the internet.
- ASIST has been synchronized (updated) to the current date.
- 36. Insert the special tool USB drive into the CONSULT PC.

HINT:

- The special tool USB drive is the only USB drive approved for use with this procedure.
- The update-software <u>must be</u> the only file on the USB drive.
- The update-software is estimated to take 10-15 minutes to download to the USB drive.
- The update-software only needs to be downloaded once and can then be used continuously on multiple Applied Vehicles.
- 37. Open ASIST.
- 38. Select Specialty Tools, and then select Infotainment Software Updates.




Figure 27

- 39. Select the check box next to the infotainment update-software (Figure 28).
 - Refer to the appropriate vehicle table to determine the correct infotainment update-software for your vehicle.
- 40. Use the drop-down menu and select the location of the USB drive that was inserted in step 36 on page 26.




Figure 28

41. Select **Download**, and then wait for the download to complete.

HINT: The update-software is estimated to take 10-15 minutes to download to the USB drive.

42. Select **OK** when the message in Figure 29 is displayed.




Figure 29

- 43. Once the transfer is complete, safely remove the USB drive from the CONSULT PC.
 - a. From the PC toolbar, select the **Safely Remove Hardware** icon.
 - The icon is on the toolbar, or can be found after selecting the arrow.
 - b. Select the USB drive to be removed, and then remove the USB drive from the CONSULT PC.

NOTICE

Follow the steps to safely remove the USB drive. If not followed, the USB drive may corrupt the infotainment update-software.

 If you are not familiar with the process of safe USB drive removal, ask for assistance at your retailer.




Figure 30

44. Close all ASIST Infotainment Software Update screens.

The **Download Update-Software from ASIST** procedure is complete, refer to the vehicle table to determine the correct **AV Control Unit Software Install** procedure to perform.

CLAIMS INFORMATION

Submit a Primary Part (PO) type line claim using the following claims coding:

CLAIM IDENTIFIER	DESCRIPTION	OP CODE	SYM	DIA	FRT
CL1	Perform Software Check and Update the AV Control Unit	RX9JAA	ZE	32	0.3

HINT: Refer to appropriate model for the Claims Information Identifier Code

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 8, 2023	ITB23-010	Original bulletin published