Subject: Engineering Information – Information on Selective Battery Pack Replacement for Analysis

Attention:

Proceed with this EI ONLY if the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the EI does not show in GWM/IVH, disregard the PIE and proceed with diagnostics found in published service information. THIS IS NOT A RECALL. Refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
BrightDrop	EV600	2022	2022	_	_	_	_
	Zevo 600	2023	2023				
Cadillac	LYRIQ	2023					
Chevrolet	Bolt EUV	2022					
	Bolt EV	2017					
GMC	HUMMER EV	2022					
	HUMMER EV SUV	2024	2024				

Involved Region or Country	U.S. Dealers ONLY
Condition	GM recovers a small number of electric vehicle battery packs from customer-owned vehicles in the field each year for further engineering study and analysis. This program helps GM improve future EV products, analyze the performance of the battery packs in customer-driven EVs, and proactively identify and correct potential issues before they can impact battery or vehicle performance. GM selects batteries for participation in this program based on various engineering criteria, including manufacturing data, vehicle location, vehicle mileage, and battery charging behavior. The customers involved will be contacted proactively by GM to visit a GM EV certified dealer for a battery pack replacement under warranty.

Correction

Important: This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

If you have been contacted by with the above concern, perform the following:

- 1. Verify that this PIE0753 appears in IVH for this vehicle's VIN.
- 2. Verify the warranty coverage.
 - If the vehicle does not have active high voltage battery warranty, DO NOT proceed with this El.
- 3. Contact GM Technical Assistance via DCM to start a case and reference PIE0753 to pre-authorize the battery pack replacement.
- **4.** Follow the appropriate document below to complete the battery order with the Battery Service Center (Speirs New Technologies). Reference **PIE0753** when ordering.
 - Bolt EUV and Bolt EV 19-NA-194
 - HUMMER EV/HUMMER EV SUV/BrightDrop latest version of PIT5857

LYRIQ - latest version of PIP5859

Important: The high voltage battery pack should be replaced following published SI procedures (Drive Motor Battery Replacement and Shipping Preparation).

- 5. Follow normal steps to determine if any hazards exist. If any of these conditions exist, contact TAC BEFORE proceeding.
 - If coolant/water is inside the battery pack. Refer to the *High Voltage System Inspection* document in SI and follow steps for Battery Coolant Level Low.
 - Any physical damage to the battery pack.
- 6. Record all DTCs present in any module on the repair order then follow published service procedures to replace the High Voltage Battery pack.
- 7. Follow published procedures to prepare the removed battery for return shipping:
 - Bolt EUV and Bolt EV Drive Motor Battery Replacement and Shipping Preparation
 - HUMMER EV/HUMMER EV SUV/BrightDrop 22-NA-005: Information on Opening / Closure Instructions for DDR and Hybrid/Electric
 Vehicle Battery Pack Replacement and Shipping Preparation
 - LYRIQ Hybrid/Electric Vehicle Battery Pack Replacement and Shipping Preparation
- 8. Follow the core return process outlined in one of the bulletins/PIs below:
 - Bolt EUV and Bolt EV 19-NA-194
 - HUMMER EV/HUMMER EV SUV/BrightDrop latest version of PIT5857
 - LYRIQ latest version of PIP5859

If DTCs are set or additional customer concerns are noted on the RO, proceed with diagnosis and repair using the published service procedures found in SI for those concerns.

Warranty Information

For vehicles repaired per this EI and under the EV Limited Component Warranty, use the following appropriate labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
5080368*	Engineering Information - Information on Selective Battery Pack Replacement for Analysis	0.2 hr
5031030	Drive Motor Battery Replacement and Shipping Preparation – Engineering Investigation – Bolt EV/EUV only	Use Published Labor Operation Time
5031630	Hybrid/Electric Vehicle Battery Pack Replacement and Shipping Preparation – BrightDrop, Hummer or LYRIQ	

This is a unique Labor Operation for bulletin use only.

Version	1
Modified	Released May 31, 2023