

GROUP	NUMBER	
AUTOMATIC TRANSMISSION	23-AT-007G	
DATE	MODELS	
JUNE 2023	G70 (IK), G80 (DH), G80 (RG3), G90 (HI), G90 (RS4), GV80 (JX1), GV70 (JK1)	

AUTOMATIC TRANSMISSION FLUID TEMPERATURE SENSOR

SUBJECT: AND INPUT/OUTPUT SPEED SENSOR

DTC P0711, P0712, P0713, P0717, P0721 & P0722

This TSB supersedes TSB 21-AT-002G to add GV70 (JK1) and G90 (RS4).

DESCRIPTION: When servicing an 8-speed automatic transmission vehicle with a "Check Engine light" and any of the DTCs listed below, follow the Service Procedure and, if necessary, replace the E-module.

APPLICABLE VEHICLES: EQUIPPED WITH AUTOMATIC TRANSMISSION

2019~ G70 (IK) 2021~ G80 (RG3) 2019~20 G80 (DH) 2021~ GV80 (JX1) 2019~22 G90 (HI) 2022~ GV70 (JK1)

2023~ G90 (RS4)

DTC LIST & PART NUMBER:

DTC	DESCRIPTION	PNC	PART NO.
P071100	Transmission fluid temperature sensor 'A' range/performance		46305-4***
P071200	Transmission fluid temperature sensor 'A' circuit low input		
P071300	Transmission fluid temperature sensor 'A' circuit high input	4620EC	
P071700	Input/turbine speed sensor 'A' circuit no signal	46305C	
P072100	Output speed sensor circuit range/performance		
P072200	Output speed sensor circuit no signal		

WARRANTY INFORMATION:

MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
G70 (IK) G80 (DH) G80 (RG3) G90 (HI) G90 (RS4) GV80 (JX1) GV70 (JK1)	46305R00	E-Module Assembly	Refer to WEBLTS for current LTS time	Refer to part number in table above	I3A	ZZ3

NOTE 1: Normal warranty applies.

NOTE 2: Submit claim on Claim Entry Screen as "Warranty" type.

NOTE 3: All claims must follow Hyundai standard warranty policy for photo capture of any component(s) or part(s) needing to be replaced as well as VIN and Mileage validation through VCI connection or photo capture (STUI or otherwise). **All claims submitted that have incomplete, illegible, or missing documentation are subject to debit.**

NOTE 4: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the parts requested are not returned.**


STUI



All claims require <u>VIN</u> and <u>Mileage</u> validation through VCI connection or photo capture (STUI or otherwise). Additionally, this TSB includes a <u>Repair</u> photo as a requirement if parts are replaced. **All claims submitted that have incomplete, illegible, or missing documentation are subject to debit.**

SERVICE PROCEDURE:

- Attach a GDS and select DTC Analysis and A/T menu. Record the DTC and description. Delete the DTC.
- 2. From the GDS home screen, select **Data Analysis** and **A/T** menu and the parameters shown below. If the parameters show:
 - Continuous and changing output while driving, the wiring **currently** has no open/short circuits. Go to Step 4.
 - No continuous and changing output, go to Step 3.



TSB #: 23-AT-007G Page 2 of 7


- 3. Visually check the wiring harness between the TCU and transmission for a damaged wire or connector. Check for an open/short circuit.
 - If so, repair or replace the control harness and drive the vehicle to confirm the repair.
 - If no damage is found, go to Step 4.
- 4. Record the audio preset stations and disconnect the negative battery terminal.
- 5. Lift the vehicle on a hoist.

Locate the harness connector on the passenger side of the transmission.

Press the tab in the center of the latch and push the latch upward.


Push the connector up to disconnect the connector from the valve body.

If additional clearance is needed to access the connector, place a support under the rear transmission support, loosen the bolts about ½ inch and lower the support about ½ inch.




Torque: 17~18 lb.ft (2.3~2.5 kgf.m, 22~24 N.m)


Remove bolts that secure oil pan and remove the oil pan.



Note the location of the 3 black bolts (shown with black arrows).

If the valve body is stuck in the transmission, insert a screwdriver between the valve body and case and carefully pull the valve body out of the transmission.







TSB #: 23-AT-007G Page 3 of 7


8. Remove 9 bolts and remove the E-module.

Install a <u>new</u> E-module and torque the bolts to specification.

Torque: 7~9 lb.ft (1.0~1.2 kgf.m, 10~12 N.m)


NOTE: Install the short bolt in the location

shown in the circle.



9. FOR SHIFT-BY-CABLE (SBC):

Confirm that 5 O-rings are seated in the case.



10. Place the valve body on a transmission jack.

Rotate the park switch lever in the direction of the arrow. Carefully raise the valve body and insert the manual valve into the lever.

Install the valve body fully into the transmission case.

NOTICE

Confirm the pin on the park switch lever faces outward from the valve body.

FOR SHIFT-BY-WIRE (SBW):

Confirm that 4 O-rings are seated in the case.






TSB #: 23-AT-007G Page 4 of 7

11. Install 3 black bolts in the locations shown (black arrows).

Install 7 brass bolts in the location shown (red arrows).

Torque the bolts to specification.


Torque: 7~9 lb.ft (1.0~1.2 kgf.m, 10~12 N.m)



12. Reconnect the harness connector.

Use a 90° pick or similar tool to pull the connector down into position on the valve body.


Pull the latch down until it clicks into the tab.



13. Confirm the O-ring is installed at the location shown.

Reinstall the valve body cover and torque to specification.

Torque: 10~12 lb.ft (1.4~1.6 kgf.m, 14~16 N.m)




TSB #: 23-AT-007G Page 5 of 7

14. With the engine off, lift the vehicle on a hoist.Use an 8mm or 5/16" hex wrench and remove

Torque: 25~32 lb.ft (3.4~4.4 kgf.m, 33~43

N.m)



15. Remove the overflow plug.


the fill plug and washer.

Use a fluid pump or suction gun to add **SPH-IV-RR** ATF through the fill plug until ATF flows from the overflow plug.

Reinstall the fill plug, washer and overflow plug.



Use only SPH-IV-RR ATF, P/N 00232-19052.



16. Lower the vehicle.

Reconnect the negative battery terminal.

Reset the audio preset stations.

17. Attach a GDS and select vehicle, **Data Analysis, A/T** menu and **Oil Temperature Sensor**.

Move the shift lever from P-R-D and back to P.

Drive the vehicle until the ATF is at the low end of the range of 122~140°F (50~60°C).

TSB #: 23-AT-007G Page 6 of 7

18. Start the engine, shift to Neutral and raise the vehicle on a hoist.

Remove the fill plug, washer and overflow plug.

Add **SPH-IV-RR** ATF through the fill plug until the ATF flows out the overflow.

Reinstall the overflow plug.


Torque: 17~18 lb-ft (2.3~2.5 kgf.m, 22~24

N.m)

Reinstall the fill plug and washer.

Torque: 25~32 lb.ft (3.4~4.4 kgf.m, 33~43

N.m)



ATF TEMPERATURE = 122~140°F (50~60°C) SHIFT LEVER IN "P" AND ENGINE RUNNING

19. FOR SBW PARK POSITION SWITCH:

If the shift cable was moved to add ATF:


Install the SST (09480-D2100) or 5mm bolt in the alignment hole of the park position switch.

Loosen the adjustment bolt shown.

Slide the adjustment bracket rearward to remove the slack in the park cable.

Tighten the bolt to specification.

Torque: 7~8 lb-ft (0.9~1.0 kgf.m, 9~10 N.m)



20. Test drive the vehicle for two driving cycles (two key-on to key-off driving cycles, including 1-2-3-4-5-6-7-8 upshifts and 8-7-6-5-4-3-2-1 downshifts). If the DTC returns, perform the following repairs:

DTC	DTC REPAIR PROCEDURE
P071100	Replace the control wiring harness between the TCU and transmission.
P071200	If the DTC does not occur again, return the vehicle to the
P071300	customer.
P071700	If the DTC returns again, replace the TCU.
P072100	
P072200	

21. Drive the vehicle to confirm the proper operation of the transmission.

TSB #: 23-AT-007G Page 7 of 7