



Technical Bulletin

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Routan	2009	All	All	All	All

Condition

96 14 03 May 19, 2014 2028820 Supersedes T.B. V961203 dated March 9, 2012 to update procedural steps using wiTECH™.

Vehicle Theft Alarm May Sound Intermittently or No Vehicle Start

Technical Background

The vehicle theft alarm intermittently sounds for no reason.
Multiple attempts are required to start the vehicle before the vehicle will start

Production Solution

Updated software as of May 9, 2011.

Service

Diagnosis:

- Using a wiTECH™ with Elsa and the appropriate Diagnostic Procedures, verify all engine systems are functioning as designed. If DTC's are present, record them on the repair order and repair as necessary before proceeding with this bulletin. If the customer describes the Symptom/Condition, or it can be reproduced, perform the Repair Procedure.
- From the vehicle view screen select TIPM-CWM, System Test, Record the "Last VTA Trigger" cause.

Was the "Last VTA Trigger" cause equal to (right rear door)?

YES: Perform this repair procedure.

NO: Check for DTC U0010 **AND** U0001 in the TIPM

Are DTCs U0010 **AND** U0001 present in the TIPM?

YES: Perform the repair procedure.

NO: This bulletin does not apply. Further diagnosis is required.



Technical Bulletin

Repair Procedure:

Note:

- **wiTECH™ UPDATE PROGRAMMING FILES FOR THIS BULLETIN MUST BE RETRIEVED FROM THE INTERNET.**
- **wiTECH™ SOFTWARE LEVEL MUST BE AT RELEASE VW13.04.13 FOR THIS BULLETIN.**

Note:

Install a battery charger to ensure battery voltage does not drop below 13.2V. **DO NOT** allow the charging voltage to climb above 13.5 V during the programming procedure.

If programming process is interrupted/aborted, programming should be restarted.

- Reprogram the TIPM using the wiTECH™ with the latest software.
- Clear any DTCs that may have been set in other control modules due to reprogramming.



Technical Bulletin

Warranty

All Routan pre and post road test, and wiTECH™ time units are included in the labor operation. Therefore, no road test time or wiTECH™ time units will appear in the designated area within the warranty table.

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Routan	2009	All	All	All	All
SAGA Coding					
Claim Type:			Use applicable Claim Type ¹⁾		
Service Number:	Damage Code	HST		Damage Location (Depends on Service No.)	
9035	0039	CWM2028820		Use applicable when indicated in ElsaWeb (L/R)	
Parts Manufacturer		Routan		USM ²⁾	
Labor Operation ³⁾ : Inspect TIPM			90350199 = 20 TU		
OR					
Labor Operation ³⁾ : Inspect and Reprogram TIPM			90352599 = 20 TU		
Causal Part:			Select labor operation 9035XXXX		
Diagnostic Time ⁴⁾					
GFF Time expenditure	01500000 = 00 TU max.			NO	
Road Test	01210002 = 00 TU 01210004 = 00 TU			NO	
Technical Diagnosis	01320000 = 00 TU max.			NO	



Technical Bulletin

Claim Comment: Input "As per Technical Bulletin 2028820" in comment section of Warranty Claim.

- 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only**
- 2) Code per warranty vendor code policy.**
- 3) Labor Time Units (TUs) are subject to change with ELSA updates.**
- 4) Documentation required per Warranty Policy Procedures Manual.**

Required Parts and Tools

No special parts required.

Tool Description	Tool No:
Midtronics Battery Tester/Charger	InCharge 940 (INC-940)
StarMOBILE® hand held tool	CH9401
StarMOBILE® vehicle cable	CH9404D
StarMOBILE® documentation kit	N/A
StarMOBILE® Ethernet cable, 12ft.	CH9410
TechCONNECT PC or equivalent with wiTECH™ version 13.04.13 desktop client installed	SW13.04.13 available from Service Net/workshop equipment/service information

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.