



Technical Service Bulletin

Technical Service Bulletin: TSB230127

Released Date: 21-Jun-2023

Vehicle Speed Sensor Fault Code 241 Causing OEM Speedometer Inaccuracy

Vehicle Speed Sensor Fault Code 241 Causing OEM Speedometer Inaccuracy

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- L9 CM2450 L126B

Issue Summary

Symptom:

- Fault Code 241 for vehicle speed sensor leading to customer complaint that vehicle speedometer maxes out or reads inaccurately.

Root Cause:

- Engine control module (ECM) calibration code issue leading to false occurrences of FC241 during normal operation.

Verification

- Verify if there have been speedometer issues with the operator.

- Confirm active or multiple inactive counts of FC241.

Resolution

- Compare the ECM code and revision number in the ECM to the calibration revision listed in the ECM Calibration Revision History Database on QuickServe® Online (QSOL) for applicable changes.
- If an ECM calibration code update for this fault code is available, the ECM calibration code revision **must** be that revision or higher.

Document History

Date	Details
2023-6-15	Module Created

Last Modified: 21-Jun-2023
