

Engine Control Module (EMS) Software (MSW) Information - Improvement List, Through June 2023 - US21+OBD2020 Emissions



Vehicles equipped with Variable Geometry Turbocharger will be referred to as VGT. Vehicles equipped with Turbo Compound will be referred to as TC.

Software Release Table (Latest information at top)

Date Available Via PTT	VGT MSW Part #	TC MSW Part #
June 2023 (Current)	24419463	24419468 - Gen 1
		24419471 – Gen 2
November 2021	23958948	23958968
August 2020	23783118	23783119
January 2020	23820138	23841271

EMS software improvements with MSW Part Number 24419463 / 24419468 / 24419471 Available from June 2023.

All Vehicles

VGT and TC EMS Software

Reduces fault frequency of following fault codes

- P02FA00 Intake Throttle Valve Calibration error
- P220164 NOx Sensor Bank 1 Sensor 1
- P04DB00 Crankcase Ventilation System Disconnected
- P205B00 Reductant Tank Temperature Sensor Circuit

Range/Performance

• P009400 - Fuel System Leak Detected - Small Leak

6/30/23, 1:59 PM Article

Improved 2589-08-03-18, Exhaust aftertreatment system analysis test, to include evaluation of SCR Efficiency.

13L VGT EMS Software Only

Improve Engine Misfire Detection. Reduction of following misfire faults.

P030000 - Random Misfire Detected

TC EMS Software Only

Reduces fault frequency of following fault codes

- P047164 Engine Exhaust Back Pressure Circuit Range/Performance
- P055B64 Piston Cooling Oil Pressure Sensor Range/Performance

Added 2589-08-03-18, Exhaust aftertreatment system analysis test, to evaluate NOx sensors and DEF dosing valve (no capability to evaluate SCR efficiency).

EMS software improvements with MSW Part Number 23958948/23958968.

Available from November 2021.

All Vehicles

VGT and TC EMS Software

The diagnostic for small fuel system leak (P009400) will not cause Malfunction Indicator lamp (MIL) after this update.

P009400 - Fuel System Leak Detected - Small Leak

Reduction of false faults on the following NOx Sensor faults:

- P225C00 NOx Sensor Performance Signal Stuck High Bank 1 Sensor 1
- P225E00 NOx Sensor Performance Signal Stuck High Bank 1 Sensor 2

Improved diagnostic function routines for EGR System Checks

Live UI

6/30/23, 1:59 PM Article

 2939-08-03-01 Exhaust Gas Recirculation Function has been replaced with 2939-08-03-03 Exhaust Gas Recirculation System Analysis.

- New diagnostic is more capable in detecting issues with EGR system.
- Use TT2.8.51 or newer and update product information to run this operation with new engine ECU software.

Improved diagnostic function routines for Exhaust Aftertreatment **System Checks**

- 2549-08-03-03 NOx Conversion has been replaced by 2589-08-03-18 Exhaust Aftertreatment System Analysis (only NOx sensor and DEF dosing valve tests available before update).
- 2589-08-03-05 Aftertreatment Selective Catalytic Reduction (SCR) System, Test B, Option 4 is improved to run as expected. This test when run heals P103B fault codes, after the repair.

Reduction of intake throttle ice formation in extreme cold weather (less than 20 degrees Celsius Ambient) and extended idling.

Reduction of faults

 P040100 - Engine Exhaust Gas Recirculation 1 Valve Position Flow Insufficient Detected

New fault code has been added to detect EGR temperature pin fretting.

 P040B00 - Exhaust Gas Recirculation Temperature Sensor "A" Circuit Range/Performance

Reduction of false faults

- P026B00 Injection Timing Performance
- P042000 Catalyst System Efficiency Below Threshold
- P260900 Intake Air Heater System Performance
- P20DC00 Exhaust Aftertreatment Fuel Supply Control Stuck Closed
- P008A00 Low Pressure Fuel System Pressure Too Low
- P20D000 Exhaust Aftertreatment Fuel Injector "A" Stuck Closed
- P20CF7A Exhaust Aftertreatment Fuel Injector "A" Stuck Open
- P20DE00 Exhaust Aftertreatment Fuel Pressure Sensor Circuit

Range/Performance

Reduction of faults in cold ambient temperatures

Live UI C00 - Cold Start Engine Coolant Temperature Performance

6/30/23, 1:59 PM Article

EMS software improvements with MSW Part Number 23783113/23783119.

Available from August 2020.

All Vehicles

VGT and TC EMS Software

Add Dedicated Fuel Filter Pressure Sensor. Reintroducing dedicated fuel pressure sensor and improved diagnostic to allow for early dash cluster warning of fuel filter clogging.

Two Non-MIL fault codes added for pressure sensor electrical faults.

- P253913 Low Pressure Fuel System Circuit
- P254200 Low Pressure Fuel System Sensor Circuit High

Performance Bonus Broadcasting Fix

 Driver gets a road speed limit increase upon meeting idle speed and fuel efficiency targets. Function corrected so that trophy indicator, fuel efficiency, and sweet spot are properly displayed on the instrument cluster. Requires cluster software to complete corrections.

The diagnostic for small fuel system leak (P009400) will not cause Malfunction Indicator lamp (MIL) after this update.

P009400 - Fuel System Leak Detected – Small Leak



*IJ*_

p253913	p254200	p009400	p0401-00
intake throttl	e ice volve	o mack	ems software
p0094-00	p225c-00	p225e-00	p0420-00
Live UI 9-00	p008a-00	p20cf-7a	p02fa-00

6/30/23, 1:59 PM Article

p02fa p2201 p2201-64 p04db p04db-00
p205b p205b-00 p0094 p0300 p0300-00
p0471 p0471-64 p055b p055b-64 p04db00

Categories *

Make and Model > Mack > CXU/CHU/PI - Pinnacle

Make and Model > Mack > LR

Make and Model > Volvo > VNL

Make and Model > Volvo > VNR

Make and Model > Volvo > VNX

Make and Model > Volvo > VAH

Make and Model > Volvo > VHD

Emission Standard > US21 > US21+OBD20

Make and Model > Mack > MRU/TE - TerraPro

Vehicle System > Control Systems

Make and Model > Mack > AN - Anthem

Make and Model > Mack > GU/GR - Granite

Related links and attachments

No content available



Give feedback

to help improve the content of this article