

9x1 - Interior Door Panel Warps Along the Top Surface

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
911	2012 - 2019	991	N/A	N/A
Boxster/ Cayman	2013 - 2016	981	N/A	N/A

Revision History

Revision	Release Date	Changes
0	June 30, 2023	Original document

Condition

The customer complains that the interior door panel is deformed along the top surface. This condition is possible on both the driver and the passenger door panels.



Figure 1

Technical Background

Over time, it is possible that the glue that secures the door panel trim will deteriorate. This deterioration is accelerated with prolonged or frequent exposure to heat.

Service Information

1. Please document the affected door panel(s) with pictures, and attach the pictures to the PCSS job.
2. Replace the affected door panel(s) with the most recent available parts. Updated parts to address this issue have been in production since June 10, 2016.

NOTE: If this failure is identified under a prevailing warranty (New Vehicle, CPO) then this failure would be considered as it is deemed an operational defect vs. cosmetic.

Warranty

If the issue is identified under a valid Warranty (New Vehicle or Certified Pre-Owned), please document the repair completely in PCSS and encode to the following:

Cause location: 7059 Front door panel
Cause symptom: 1051 Bond faulty

Use the following labor operations only as needed:

70591901	Front door panel remove and reinstall (left)
70591902	Front door panel remove and reinstall (right)
70592000	2 Front door panels remove and reinstall (only if both door panels are replaced simultaneously)

Search Items

911, 991, Carrera, door panel, warp, peel

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.