Reference	SSM75999
Models	Defender / L663
	Discovery / L462
	Discovery Sport / L550
	New Range Rover / L460
	New Range Rover Evoque / L551
	New Range Rover Sport / L461
	Range Rover Velar / L560
Title	Startup Battery Reduced State of Charge (SOC)
Category	Electrical
Last modified	10-Jul-2023 00:00:00
Symptom	206000 Warning Indicators
Content	L663, L462, L460, L461, L550, L551, L560 23MY onwards

Issue:

MHEV vehicles only

Customers are reporting 'Stop Safely' and 'Electric Charging fault' warning messages displayed on the Instrument

Panel Cluster. The following Diagnostic Trouble Codes (DTC)s may also be stored in the Battery Energy Control Module (BECM):

- U0120-00
- P0DA8-62
- U0064-87.

Cause:

The cause is currently unknown and is under investigation. The information gathered from this SSM will assist the investigation.

Action:

Upon a vehicle entering the retailer with 'Stop Safely' and 'Electric Charging fault' warning messages displayed on the Instrument Panel Cluster, continue diagnosis using the TOPIx workshop manual and TOPIx Cloud, as required. Extra care must be taken to make sure all BISG electrical connections and connector pins are secure and correctly installed.

If no fault is found by continuing further diagnosis, and the same warning messages and DTCs become present again within 2 days:

• Collect the Power Mode Zero (PMZ) logs with the existing Belt Intergrated Starter Generator (BISG) installed.

For guidance on collecting the PMZ logs, on TOPIx, go to, Browse All > Documents > Diagnostics > General > CAN logger > Open 'VCI_CAN_Logger_1 - JLR VCI CAN Logger'

- Raise an Electronic Product Quality Report (EPQR) with the following information:
 - This SSM reference (SSM 75999)
 - Engineering reference: PTS_100
 - The PMZ logs
 - The serial number located on the existing BISG
- Renew the BISG

If the same warning messages and DTCs become present again within 2 days, after renewing the BISG:

- Collect the PMZ logs again, this time with the new BISG installed
 For guidance on collecting the PMZ logs, on TOPIx, go to, Browse All > Documents > Diagnostics > General > CAN logger > Open 'VCI_CAN_Logger_1 JLR VCI CAN Logger'
- Raise a Technical Assistance (TA) with the following information:
 - This SSM reference (SSM 75999)
 - Engineering reference: PTS_100
 - The PMZ logs for the new BISG
 - The serial number located on the new BISG

anBhdHRlcnM7MiAvMv0wOC0wMlQxMiovOToxMC41MDhaOzEzNi4vMiYuNTAuMTEzOw=