



# Technical Service Bulletin

---

## 91 Audi connect: Remote locking/unlocking not possible

91 23 27 2071297/1 August 24, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2019 – 2024	All	Not Applicable

## Condition

### Customer states:

The customer attempts to lock or unlock the vehicle via the myAudi app and receives one of the messages below, all other remote services work:

- RLU.PA.100 (iOS - figure 1).
- or
- PA.RLU.2 (Android - figure 2).




Figure 1: Message for IOS devices




Figure 2: Message for Android devices

### Workshop findings:

The issue can be duplicated when the vehicle is locked or unlocked in the myAudi app and the message specified above is displayed.

## Technical Background

There is a functional issue in the onboard supply control unit (address word 0009).



# Technical Service Bulletin

## Production Solution

Software optimization is planned.

## Service

If the customer description and message above are present, reset the electronic central electrics module -J519- (address word 0009).

To reset the module, perform the replacement test plan for the -J519- using the following steps:

1. Perform the guided function “Replace control module”
2. When prompted whether the data should be carried over from the old control unit, select “no”.
3. Continue in test plan as normal.



**Note:** Parts replacement does not solve this issue. Claims for replaced parts will be subject to review.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• 110 Up to 48 Months/50,000 Miles.</li> <li>• G10 for CPO Covered Vehicles – Verify Owner.</li> <li>• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
<b>Service Number:</b>	9710		
<b>Damage Code:</b>	0039		
<b>Labor Operations:</b>	GFF – Scan vehicle, perform module replacement test plan, clear DTC’s	0150 0000	Time stated on the diagnostic protocol (Max 100 TU)
<b>Diagnostic Time:</b>	GFF – Checking and clearing fault codes included in existing labor operations	No allowance (included above)	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB 2071297/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



# Technical Service Bulletin

---

## Additional Information

All part and service references provided in this TSB (**2071927**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.