

Technical product information

Topic	DTC C10BCF6 and/or DTC C12E2F2 stored in address 0003 - Parking brake warning in DIP
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2071166/1
Level	EH
Status	Approval
Release date	

Event memory entries

Diagnostic address	Event memory entry	Fault type	Fault status
0003 - Brake Electronics	C10BCF6: Left parking brake motor Engine speed implausible		static
0003 - Brake Electronics	C12E2F2: Right parking brake motor Engine speed implausible		static

New customer code

Object of complaint	Complaint type	Position
running gear -> brakes, brake control -> electronic parking brake (EPB)	functionality -> without function / defect	
information, navigation, communication, entertainment -> symbolic warning indicators -> parking brake warning indicator	functionality -> activates	

Vehicle data

New Continental GT/GTC and New Flying Spur

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S4*	2019	E		*	*	*
3S4*	2020	E		*	*	*
3S4*	2021	E		*	*	*
3S4*	2022	E		*	*	*
3S4*	2023	E		*	*	*
3S4*	2024	E		*	*	*
ZG2*	2020	E		*	*	*
ZG2*	2021	E		*	*	*
ZG2*	2022	E		*	*	*
ZG2*	2023	E		*	*	*
ZG2*	2024	E		*	*	*

Documents

Document name
master.xml

Customer statement / workshop findings

Customer statement

Parking brake warning light evident within the DIP (See example shown in Figure 1)



Figure 1

NOTE: Please also refer to the Owner's Handbook regarding the applicable red warning light and description (Figure 2)




Figure 2

Workshop findings

One or a combination of the following DTC's maybe evident within the Diagnostic address 0003 - Brake electronics control unit

- C10BCF6 - Left parking brake motor Engine speed implausible
- C12E2F2 - Right parking brake motor Engine speed implausible

Technical background

NOTICE

Do Not conduct any further work including diagnosis work

NOTICE

Do Not remove or replace any parts unless instructed via DISS

NOTICE

Refer to the instructions within the Measure section of this TPI

Production change

Not applicable

Measure

- 1) Raise a technical DISS query ensuring a current ODIS log is attached



IMPORTANT NOTE FOR PRODUCT SUPPORT:

On receipt of a qualifying DISS query Product Support **MUST** second level the DISS query and await feedback before responding to the retailer

Warranty accounting instructions

Warranty type - 110 or 910

Damage Service Number 46 63

Damage Code 00 40

ODIS diagnostic time

Labour Operation Code 01 50 00 00

Time As per ODIS log (Must not exceed 20 TU)