

Description: This bulletin provides instructions on how to service the panoramic sunroof on certain G80 (RG3) vehicles that experience creaking or rattling noises while driving on uneven roads.



Applicable Vehicles (Certain):

2021 - 2023MY G80 (RG3) vehicles produced from 07/25/2020 - 04/06/2023

Parts Information:

Parts Name	Part Number		Contents		Remarks
Panoramic Sunroof Noise Assembly Kit – Type A	81684- T1200FFF	12 mm length bolt	10 mm length bolt	Teflon tape	For vehicles produced before 3/3/2021. Quantity included: 12mm length bolt – 8 EA 10mm length bolt – 8 EA Teflon tape – 10 EA
Panoramic Sunroof Noise Assembly Kit – Type B	81684- T1400FFF	15 mm length bolt	10 mm length bolt	Teflon tape	For vehicles produced on and after 3/3/2021. Quantity included: 15mm length bolt – 8 EA 10mm length bolt – 8 EA Teflon tape – 10 EA

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
G80	81684F01	Roof Trim Removal and Panoramic Sunroof Assembly Kit Replacement (Type A)	1.6 M/H	81684-T1200FFF	Q55	<i>77</i> 7
(RG3)	81684F02	Roof Trim and Panoramic Sunroof Mechanism Removal and Assembly Kit Replacement (Type B)	2.2 M/H	81684-T1400FFF	QJJ	ZZ1

NOTE 1: Normal warranty applies.

NOTE 2: Submit claim on Claim Entry Screen as "Warranty" type.

NOTE 3: This TSB includes Repair validation photos. Op times including VIN, Mileage, and Repair validation photos as outlined in the Digital Documentation Policy.

NOTE 4: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**

NOTE 5: If a part is found in need of replacement while performing this TSB and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

TSB #: 23-BD-014G Page 2 of 12

Service Procedure:

STUI




This TSB includes Repair validation photos. Refer to the latest Digital Documentation Policy for requirements.

Assembly Kit – Type A (Vehicles produced before 3/3/2021)

Disconnect the negative (–) battery terminal (A).

Tightening Torque:

lb-ft	6.5
lb-in	78
N.m	9




2. Lower the head lining (B) and place it over the front seats.

Refer to the shop manual:

Body (Interior and Exterior) >
 Roof Trim > Roof Trim Assembly >
 Repair procedures

NOTICE

It is not necessary to remove the head lining from the vehicle. Be careful not to damage or crease the head lining.



TSB #: 23-BD-014G Page 3 of 12

3. Remove the 8 lower bolts of the front roller blind support bracket (C).

Tightening Torque:

lb-ft	5.9
lb-in	71
N.m	8


4. Attach the Teflon tape to the 4 bolt holes of the front roller blind support bracket as shown on the right.

STUI



Using STUI, take a photo of the support bracket with the Teflon tape attached and the last 6 digits of the VIN and date of repair on a piece of paper.

Upload the photo to STUI.







Example STUI photo

5. Reinstall the front roller blind support bracket.




Information


Use the new bolts when reinstalling the front roller blind support bracket. Do not reuse the previous bolts.

6. Remove the 8 lower bolts of the rear roller blind support bracket (D).

Tightening Torque:







TSB #: 23-BD-014G Page 4 of 12

7. Attach the Teflon tape to the 4 bolt holes of the rear roller blind support bracket as shown on the right.

STUI



Using STUI, take a photo of the support bracket with the Teflon tape attached and the last 6 digits of the VIN and date of repair on a piece of paper.

Upload the photo to STUI.






Example STUI photo

8. Reinstall the rear roller blind support bracket.

i

Information

Use the new bolts when reinstalling the rear roller blind support bracket. Do not reuse the previous bolts.



Reinstall all components in the reverse order of removal.

i

Information

Before reinstalling the head lining, replace any damaged head lining clips and add new foam tape underneath all clips. This will reduce the possibility of noise from the head lining, which could be misinterpreted as originating from the sunroof.

10. Verify that the panoramic sunroof operates normally (open, close, and tilt).

TSB #: 23-BD-014G Page 5 of 12

Assembly Kit – Type B (Vehicles produced on or after 3/3/2021)


1. Remove the panoramic sunroof movable glass (A).

Refer to the Shop Manual:

Body (Interior and Exterior) >
 Panorama Sunroof > Movable
 Glass > Repair procedures


NOTICE

Place the movable glass on a workbench with a soft surface to prevent damage.



Tightening Torque:

lb-ft	6.5
lb-in	78
N.m	9





Refer to the shop manual:


Body (Interior and Exterior) >
 Roof Trim > Roof Trim Assembly >
 Repair procedures

NOTICE

It is not necessary to remove the head lining from the vehicle. Be careful not to damage or crease the head lining.







TSB #: 23-BD-014G Page 6 of 12

SUBJECT:

PANORAMIC SUNROOF NOISE REPAIR

4. Remove the 4 lower bolts of the front roller blind support bracket.

Tightening Torque:


lb-ft	5.9
lb-in	71
N.m	8


5. Remove the 4 lower bolts of the rear roller blind support bracket.


Tightening Torque:


lb-ft	5.9
lb-in	71
N.m	8


6. Remove the panoramic sunroof movable glass motor (D).













TSB #: 23-BD-014G Page 7 of 12

8. Remove the curtain airbag (CAB) (F) on both sides.

Refer to the shop manual:

- Restraint > Airbag Module >
 Curtain Airbag (CAB) Module >
 Repair procedures
- 9. Remove the curtain airbag (CAB) mounting bracket (G) on both sides.





10. Remove the upper bolts (H) of the sunroof mechanism rail assembly.

NOTICE

Be careful not to damage the Torx bolts as they will be reused.



TSB #: 23-BD-014G Page 8 of 12

SUBJECT:

PANORAMIC SUNROOF NOISE REPAIR

11. Remove the lower mounting bolts and nuts of the sunroof mechanism rail assembly (I).

NOTICE

Be careful not to damage the Torx bolts and nuts as they will be reused.

Tightening Torque (nuts):

lb-ft	2.9
lb-in	35
N.m	4



Tightening Torque (Torx bolts):

lb-ft	5.1
lb-in	61
N.m	7

12. Remove the sunroof mechanism rail assembly (I) from the vehicle by lifting it through the sunroof.





TSB #: 23-BD-014G Page 9 of 12

13. Remove the upper bolts (J) of both roller blind support brackets.

Tightening Torque:

lb-ft	5.9
lb-in	71
N.m	8









Example STUI photo

STUI



Using STUI, take a photo of the support brackets with the Teflon tape attached and the last 6 digits of the VIN and date of repair on a piece of paper.

Upload the photo to STUI.


TSB #: 23-BD-014G Page 10 of 12

15. Reinstall both roller blind support brackets onto the sunroof mechanism rail assembly.

i

Information

Use the new bolts when reinstalling both roller blind support brackets. **DO NOT** reuse the previous bolts.



 Reinstall all components in the reverse order of removal.



Information


Use the new bolts when reinstalling both roller blind support brackets. **DO NOT** reuse the previous bolts.



Information

Before reinstalling the head lining, replace any damaged head lining clips and add new foam tape underneath all clips. This will reduce the possibility of noise from the head lining, which could be misinterpreted as originating from the sunroof.






TSB #: 23-BD-014G Page 11 of 12

17. Ensure the sunroof movable glass (A) is properly aligned after reinstallation.

Refer to the Shop Manual:

 Body (Interior and Exterior) > Panorama Sunroof > Repair procedures



18. Perform the panoramic sunroof reset procedure.

i

Information

Refer to the owner's manual for the complete panoramic sunroof reset procedure.



- 19. Verify that the panoramic sunroof operates normally (open, close, and tilt).
- 20. The service procedure is now complete.

TSB #: 23-BD-014G Page 12 of 12