



Bulletin No.: PIT6044

Published date: N/A

## Preliminary Information

### PIT6044 Service High Voltage with MIL and/or DTCs

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
BrightDrop	EV 600 eLCV	2023	ALL	All	All	All
Cadillac	EV LYRIQ	2023	ALL	All	All	All
Chevrolet	Blazer EV	2023	ALL	All	All	All
Chevrolet	Silverado EV	2023	ALL	All	All	All
GMC	HUMMER EV	2023	ALL	All	All	All
GMC	HUMMER EV SUV	2023	ALL	All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	Some customers may comment the MIL is illuminated or Service High Voltage Message displayed on the IPC. A technician may find any of the following DTCs; U2220, U2221, U2222, U2223, U2224, U2225, U2226, U2227, U2228, U2229, U222A, U222B, U222C, U222D, U222E, U222F, U2230, U2231, U2232, U2233, U2234, U2235, U2236, U2237 set as current or history.
<b>Cause</b>	A potential software anomaly may be present that will be fixed in a future OTA update.

#### Correction:

**Note: Updated Software and Calibrations will be released at a later date in the form of an OTA update. Please inform the customer to accept any future OTA updates for their vehicle.**

1. **Verify the vehicle has one or more of the following DTCs set; U2220, U2221, U2222, U2223, U2224, U2225, U2226, U2227, U2228, U2229, U222A, U222B, U222C, U222D, U222E, U222F, U2230, U2231, U2232, U2233, U2234, U2235, U2236, U2237 set as current or history.**
2. **Perform the Battery Negative Cable Disconnection and Connection procedure outlined in Service Information.**

**Warning: Always ensure the Battery Maintenance Mode is inactive before disconnecting the 12-volt battery. This mode can be active with the ignition off, regardless of whether the vehicle charging cord is plugged in or not. When this mode is active, the on-board high voltage battery charger will energize the 12-volt battery cables and charge the 12-volt battery. Disconnecting the battery cables while this mode is active may result in an electrical shock or a burn from hot battery cable leads.**

3. **Wait 15 mins, then reconnect the 12v following the Battery Negative Cable Disconnection and Connection procedure outlined in Service Information.**
4. **Place the vehicle in Propulsion “Ready” mode, then turn the vehicle “OFF” and remove the keyless transmitter from the vehicle and place the transmitter in a safe location approximately 10ft away. Wait 15 mins. Perform this two times.**
5. **Place the vehicle in Service mode and use GDS2 and clear all DTCs.**

**If any of the following DTCs: U2220, U2221, U2222, U2223, U2224, U2225, U2226, U2227, U2228, U2229, U222A, U222B, U222C, U222D, U222E, U222F U2230, U2231, U2232, U2233, U2234, U2235, U2236, and/or U2237 return, start a TAC case, and reference this P.I.**

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
5080388	CMU Loss of Communication Manual Reset	1.5 Hr.
<b>*This is a unique Labor Operation for Bulletin use only</b>		

### Version History

Version	<b>1</b>
Modified	08/03/2023 - Created on.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.