

# **Technical Service Bulletin**

**93 Vehicle does not start. DTC P0A9500 High Voltage Fuse stored in Battery Manager (008C)** 93 23 30 2071488/1 September 14, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2022 – 2024	All	Not Applicable

### Condition

#### **Customer states:**

- The drive system cannot be activated.
- The red electrical system warning lamp is illuminated.

#### Workshop findings:

The following DTC may be stored in the Battery Manager Control Unit (BMC), -J840- (address word 008C):

• DTC P0A9500 (High Voltage Fuse) with symptom code 1310729 (active/static)

Other faults may also be stored.

#### **Technical Background**

Not applicable.

## **Production Solution**

Not applicable.

#### Service

If the above condition has been confirmed and the fault is stored static/active replace the following parts according to the Repair Manual and ODIS test plans:

- High-Voltage Battery Control Module (SX6). Also known as the Battery Junction Box or Battery Isolator
- Power Output Protection with Boost Function (J1178). Also known as DC/DC Converter 2.
- Recheck for proper operation.

#### Warranty

© 2023 Audi of America, Inc.

Claim Type: • 110 up to 48 Months/50,000 Miles.

Page 1 of 3

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



# **Technical Service Bulletin**

	<ul> <li>G10 for CPO Covered Vehicles – Verify Owner.</li> <li>If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li> </ul>				
Service Number:	9327				
Damage Code:	0040				
Labor Operations:	Replace switching unit for high-voltage battery	9327 5550	See SRT		
	Replace DC/DC converter	9319 5555	See SRT		
	<b>Note:</b> The above labor operations have multiple predecessor and addition operations which can be different based on vehicle equipment. Claim the predecessor operations for the vehicle.				
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 400 TU)		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	No allowance	0 TU		
Claim Comment:	As per TSB 2071488/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## **Required Parts and Tools**

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.					
Part Number	Part Description	Quantity			
See ETKA	Fasteners, Bolts, Coolant, Nuts and Screws as needed per the Repair Manual	See ETKA/ELSA			
9J1915251 *	Battery isolator (SX6) Order to VIN	01			
9J1915539 *	Voltage Transformer Order to VIN	01			

### **Additional Information**

© 2023 Audi of America, Inc.

Page 2 of 3

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



## **Technical Service Bulletin**

All parts and service references provided in this TSB (2071488) are subject to change and/or removal.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.