

GENUINE MOTOR PARTS AND MOTOR ACCESSORIES BULLETIN

MOTOR PARTS

PAB1146

2023-12-21

PAB1146: 68193-95 BULB WEDGE, FENDER TIP LAMP

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Rev	Revision (Rev) Description
2023-12-21	-	Initial release

Purpose for Parts and Accessories Bulletin

To inform dealers of an issue with the bulb wire terminals not being to specification. The light bulbs were used in numerous front and rear fender tip light assemblies for domestic and international applications.

Vehicles Affected

1999-2017: Touring and Softail models

Markets Affected

All markets affected.

Summary

Harley-Davidson has found an issue with the wire terminals on the light bulb (Part No. 68193-95) not being folded and molded back into the housing. The bulb style has been corrected by working with our supplier.

Shipments of the incorrect bulb (1) started in March 2022 and ended in August 2023 with the following packages dates March 25, 2022 and October 24, 2022. Inspect your inventory of this part and dispose of the defective stock. Submit a warranty claim for reimbursement. Refer to Credit Procedure.




Figure 1. Incorrect vs Correct Bulb



Credit Procedure

NOTE

Enter bulletin number into comment section of claim.

Submit a warranty claim per Table 2 for all parts in dealer stock.

Table 2.

ITEM	DATA
Claim Type	DFS/PAM stock
Problem Part Number	68193-95
Quantity	Could vary
Customer Concern Code	9203
Condition Code	1506
(1) Download may be required	

NOTE

Enter PAB1146 in Event Comments section of the claim.

Hold all claimed parts for 60 days from date of credit issued for possible field inspection and/or request to return to factory. After 60 days, destroy and discard the parts.

Questions

Contact Technical Service with any concerns regarding application. Direct all other questions to the Dealer Services Representative.