

Technical product information

Topic	DTC B187A00 Park steer assist cancellation is logged in the Front Sensor Driver Assistance Control Unit - Address 00A5
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2072499/1
Level	EH
Status	Approval
Release date	

Event memory entries

Diagnostic address	Event memory entry	Fault type	Fault status
00A5 - Front sensor for drivers assistant systems	B187A00: Park steer assist cancelation		Intermittent
00A5 - Front sensor for drivers assistant systems	B187A00: Park steer assist cancelation		static

New customer code

Object of complaint	Complaint type	Position
driver assist systems, convenience features -> Park Assist, parking aid	concept	
vehicle service -> service, maintenance -> general inspection	service: process -> with determination of concern	
vehicle service -> vehicle diagnosis -> guided fault finding	control units, services -> with event log entry	

Vehicle data

Bentayga

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2024	E		*	*	*

Documents

Document name
master.xml

DTC B187A00 Park steer assist cancellation is logged in the Front Sensor Driver Assistance Control Unit - Address 00A5

Customer statement / workshop findings

Workshop findings

- DTC B187A00 Park steer assist cancellation is evident within diagnostic address 00A5 - Front Sensor Driver Assistance System control unit

Technical background

In the event that DTC B187A00 is evident within diagnostic address 00A5 - Front Sensor Driver Assistance System control unit, the operative must raise a technical DISS query ensuring the following is attached

- Current ODIS log
- Photographs of any warning symbols which are evident within the Drivers Information panel (DIP)

NOTICE

IMPORTANT NOTICE: DO NOT CONDUCT ANY FURTHER WORK UNTIL A RESPONSE HAS BEEN RECIVED FROM PRODUCT SUPPORT VIA THE OPEN DISS QUERY

Production change

-

Measure

Refer to the Technical background section