



Technical Service Bulletin

15 Engine: Cylinder head cover - oil residue Q5 (inline 4-cyl., 2.0 ltr. TFSI)

15 24 47 2072716/1 January 18, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5, and Q5 Sportback	2021 – 2023	All	DPVA Engine

Condition

Customer states:

- There is oil residue on the cylinder head cover.

Workshop findings:

- The cylinder head cover is leaking in the area around the threaded connection on one or multiple bolts (Figure 1).




Figure 1: Oil on the threaded connection.



Technical Service Bulletin

Technical Background

In cases, burrs on the cylinder head cover bolts can cause the bolts to become loose. This can cause oil residue in the area around the threaded connection.

Production Solution

Burrs in the screw are caused in the threading process. Adjustment and verification of the tool for material feeding by screw supplier.

Service

- Please replace the affected bolt(s).
- Please ensure that replacing the bolts remedies the leaking.

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 Up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1570		
Damage Code:	0050		
Labor Operations:	Remove and install engine cover	1083 1900	See SRT with associated operations
	Secure camshaft housing	1503 1399	20 TU
	Engine Clean	1001 2999	20 TU
Diagnostic Time:	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2072716/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information



Technical Service Bulletin

All part and service references provided in this TSB (**2072716**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.