Polestar		Service and Parts Business			
Technical Journal					
TITLE:					
	BEV High Voltage Battery Replacement				
REF NO:	ISSUING DEPARTMENT:	CARM	ARKET:		
TJ 36418.3.0	Technical Service	United States and Canada			
	PARTNER:	ISSUE DATE:	STATUS DATE:		
3 US	3 7515 Polestar	2024-02-08	2024-02-21		
FUNC GROUP:	FUNC DESC:]			

Page 1 of 6

Attachment

File Name	File Size	
TJ_36418_1.pdf	0.1184 MB	

Rows beginning with * are modified

3113

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Battery, high voltage

DESCRIPTION:

In the event of complete high-voltage battery replacement, the battery being installed may not have the same cell chemistry as the battery being removed.

The replacement battery will always have the same or higher capacity compared to the original battery.

To be able to use another cell chemistry you need to download a unique SP (Software Product).

This TJ will guide you on which SP to use in the event of high-voltage battery replacement where the battery is replaced with new cell chemistry and also explains the sequence for downloading the SP and update software.

Please follow the instructions under "Service."

CSC Customer Symptom Codes

Code	Description
7B	Starting/Engine does not start/Engine does not turn/No clicking sound at start attempt

Technical Journal 36418.3.0

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534	ED	E400V6					2021-2023		-	202007-202316
534	EG	E400V9					2022-2023		-	202122-202316

SERVICE:

*When a new battery is installed and the cell chemistry is different a unique SP is necessary, see attachment "TJ_36418_1.pdf."

The SP changes the Variant Attribute in the vehicle to match that of the replacement battery.

The information of what battery is installed in the vehicle could be found in VIDA, Vehicle details, Variant Attribute, and search for VDN code CKxx. The part number label is placed on the rear left side of the HV battery.

Use the following sequence when installing the SP, BECM reload, and software upgrade.

- 1. Software product to change from one CK to another. See attachment "TJ 36418 1.pdf."
- 2. Perform BECM reload
- 3. Perform a total upgrade

If the wrong SP is used, the car will not start after the battery replacement.

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, please use the following data:

VST OP number: 36004-2

Note: TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support needed Polestar," use function group 3113.

To view TJ attachment continue to next page. This TJ has one attachment.

Page 2 of 6 2024-02-21

Software Product list BEV VDN code CK06 27 modules

Current part number	replacing part number	SP number for VDN update	replacing part number	SP number for VDN update
СК06	CK25	ω	CK28	ω
32290433	32361092	SP 32397478	32441006	SP 32436199
36051298	36051303	3P 974	36051451	361
	32336733	78	32441007	99
	36051304		36051452	

Software Product list BEV VDN code CK25 27 modules

Current part number	replacing part number	SP number for VDN update
CK25	CK28	ω
32361092	32441006	S 243
36051303	36051451	SP 32436199
32336733	32441007	99
36051304	36051452	

Software Product list BEV VDN code CK23 24 modules

Current part number	replacing part number	SP number for VDN update	replacing part number	SP number for VDN update
СК23	СК24	ω	СК29	ω
32290433	32361091	SP 32397476	32441008	SP 32436199
36051298	36051292	;P)74:	36051450	3P 361
		76		99

Software Product list BEV VDN code CK24 24 modules

Current part number	replacing part number	SP number for VDN update
CK24	СК29	ω
32361091	32441008	SP 32436200
36051292	36051450	P 620
		00