

WRB6 - Replacing Gateway Control Unit (Stop Delivery)

Model Line: **Cayenne (9YA / 9YB)**

Model Year: **As of 2023 up to 2024**

Country / Market: **USA (C02), Puerto Rico (COA), Canada (C36)**

Concerns: **Gateway control unit**

Cause: **A gateway control unit that does not meet the required market-specific requirements was installed in the affected vehicles.**

Action: **Replace the gateway control unit.**



Information


Affected Vehicles: **Every vehicle is assigned to exactly one campaign scope.**

⇒ To find out the scope assigned to the relevant vehicle, see PCSS Vehicle Information.

Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Installation

Position:



Installation position of gateway control unit

Required parts

The **part numbers** of the **required parts** for the respective vehicle can be seen in the **assigned scope**.
For an overview of the campaign scopes, see: ⇒ *Technical Information 'Warranty processing'*

Required tool

- Battery charger with a current rating of **at least 90 A**, e.g., **VAS 5908 - battery charger 90 A**
- **P90999 - PIWIS Tester 4**
- Torque screwdriver, 1.5-3 Nm (1-2 ftlb.), e.g., **VAS 6494 - torque screwdriver, 1.5-3.0 Nm (1-2 ftlb.)**
- Torque wrench, 2-10 Nm (1.5-7.5 ftlb.), e.g., **V.A.G 1783 - Torque wrench, 2-10 Nm (1.5-7.5 ftlb.)**
- Torque wrench, 6 – 50 Nm (4.5 – 37 ftlb.), e.g., **V.A.G 1331A - Torque wrench, 6-50 Nm (4.5-37 ftlb.)**

Replacing gateway control unit

- Work Procedure: 1 Replace the gateway control unit.
 For procedure, see:
 ⇒ *Workshop Manual '903519 Removing and installing gateway control unit'*
 ⇒ *Workshop Manual '903555 Replacing gateway control unit'*
- 2 Enter the campaign in the Warranty and Maintenance logbook.

Warranty processing



Information

The specified labor times were determined specifically for carrying out this campaign and include all necessary preliminary and subsequent rework. The labor times may differ from the Labor times published in the Labor Operation List in PCSS.

Scope 1-5: **Not relevant for this vehicle type.**

Scope 6: **Replacing gateway control unit**

Valid for vehicles during the production period **until 15/05/2023**

Labor time:		
Replacing gateway control unit		Labor time: 142 TU
Includes:	Disconnecting and connecting battery	
	Removing and installing the left front seat.	
	Loosening and fastening the lower part of the left front center console	
	Coding gateway control unit	
Required parts:		
PAD907468B	Gateway control unit	1 piece
N 91205201	Cheese head bolt with multiple-tooth head (instrument cluster)	4 pieces
⇒ Damage Code WRB6 066 000 2		

Scope 7: **Replacing gateway control unit**

Valid for vehicles during the production period **from 16/05/2023** and with the following equipment:

- **with LED headlights (M-No. 8IT)**

Labor time:

Replacing gateway control unit

Labor time: **142 TU**

Includes: Disconnecting and connecting battery
 Removing and installing the left front seat.
 Loosening and fastening the lower part of the left front center console
 Coding gateway control unit

Required parts:

PAD907468B	Gateway control unit	1 piece
N 91205201	Cheese head bolt with multiple-tooth head (instrument cluster)	4 pieces

⇒ **Damage Code WRB6 066 000 2**Scope 8: **Replacing gateway control unit**Valid for vehicles during the production period **from 16/05/2023** and with the following equipment:

- **with LED headlights with variable light distribution (M-No. 8IU)**

or

- **with LED headlights with variable light distribution, darkened (M-No. 8JU)**

Labor time:

Replacing gateway control unit

Labor time: **142 TU**

Includes: Disconnecting and connecting battery
 Removing and installing the left front seat.
 Loosening and fastening the lower part of the left front center console
 Coding gateway control unit

Required parts:

PAD907468C	Gateway control unit	1 piece
N 91205201	Cheese head bolt with multiple-tooth head (instrument cluster)	4 pieces

⇒ **Damage Code WRB6 066 000 2**

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2024 Porsche Cars North America, Inc.