



Technical Service Bulletin

GROUP BODY ELECTRICAL	NUMBER 24-BE-002H
DATE JANUARY 2024	MODEL(S) SEE BELOW

SUBJECT: AVN SOFTWARE UPDATE FOR RADIO APP CRASH AND UNEVEN ROAD WARNING

Description: Some vehicles equipped with the AVN 5th Gen Wide system may exhibit a condition where the radio app crashes frequently when entering radio mode and/or a message that reads “Uneven Road Ahead, Drive carefully” on the cluster along with a warning sound. Follow the procedure outlined in this bulletin to update the AVN software to resolve this condition.

- Applicable Vehicles (Certain):**
- 2023MY Elantra (CN7a) equipped with AVN 5th Gen Wide produced from 12/06/2022 - 05/26/2023.
 - 2023MY Santa Fe (TMa) equipped with AVN 5th Gen Wide produced from 11/17/2022 - 08/09/2023.
 - 2023MY Tucson (NX4a) equipped with AVN 5th Gen Wide produced from 11/29/2022 - 07/18/2023.

Parts Information:

Model	Part Name	Part Number	Figure	Remarks
Elantra (CN7a) Santa Fe (TMa)	AVN S/W UPDATE A FOR RADIO APP FIX	RADIOSWUPDATEA		Use this USB drive for the models listed at left. Each dealer has been shipped one stick free of charge; USB can be used for multiple vehicles.
Tucson (NX4a)	AVN S/W UPDATE B FOR RADIO APP FIX	RADIOSWUPDATEB		Use this USB drive for the model listed at left. Each dealer has been shipped one stick free of charge; USB can be used for multiple vehicles.

Warranty Information:

Model	Op. Code	Operation	Op. Time	Casual Part	Nature Code	Cause Code
All	30DA22R0	AVN Software Update	0.3 M/H	96560-AA250TVN (Elantra) 96560-N9520 (Tucson) 96560-S2630RET (Santa Fe)	M73	ZZ3

NOTE 1: Submit claim on Claim Entry Screen as “Campaign” type.

NOTE 2: This TSB includes Repair validation photos. Op times include VIN, Mileage, and Repair validation photos as outlined in the Digital Documentation Policy.

NOTE 3: If a part is found in need of replacement while performing this TSB and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

Service Procedure:

STUI



This TSB includes Repair validation photos. Refer to the latest Digital Documentation Policy for requirements.

i Information


- Ensure that the battery is sufficiently charged and that the power is switched to “ON” to prevent a battery drain during the update.
- Do not remove the USB drive, or turn off the ignition switch during the update. This will prevent the update from completing.
- Verify that the AVN system is a genuine Hyundai part (not aftermarket) before performing the update.

AVN Software Update

1. Turn the ignition switch ‘ON’.



2. Select the **'Setup'** button and enter the SETUP menu.



3. Select **'General'**.



4. Check the Software Version that's currently installed.
If software version is one of the versions listed below, the AVN needs to be updated.

Current Software Version:

- 221011
- 221025
- 221115
- 221220
- 221228




5. Insert the USB drive into the USB slot.




6. Select **'Update'** at the bottom of the screen to proceed with the software update.

i Information

Do not remove the USB drive or turn off the ignition switch during the update. This will prevent the update from completing.




7. Select 'OK'.



8. Select 'Start'.


NOTICE

Do not turn off power or remove the USB device. It may cause data loss or system failure.



Information

There will be multiple occurrences where the Hyundai logo will appear, or the display will be black during the update process. This is normal.



9. Confirm the S/W version has been correctly updated by referring to the 'SW Info/Update' screen.

The updated S/W version should be **230203**.



10.

STUI



Take a screenshot of the 'SW Info/Update' screen using your particular tablet's screenshot save method and upload to STUI.

