



# Technical Service Bulletin

## 91 ConBox: Wireless Audi Smartphone Interface (CarPlay / AndroidAuto) inop

91 24 85 2073333/1 March 12, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7, SQ7, Q8, SQ8, and RS Q8	2023 - 2024	All	Not Applicable
A4, A4 allroad, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, RS 5 Sportback, A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, e-tron GT, RS e-tron GT, Q7, SQ7, Q8, SQ8, RS Q8, Q8 e-tron, Q8 Sportback e-tron, and SQ8 e-tron	2024		

## Condition

### Customer states:

- The Audi Smartphone Interface [ASI] (Apple CarPlay [ACP] / AndroidAuto [AA]) cannot be paired to the phone wirelessly.
- The phone tiles under the ASI menu are grayed out (see Figure 1).



# Technical Service Bulletin

---



**Figure 1:** wASI connections grayed out.

- When using a wired ASI connection, the system works as expected.
- The 5GHz WiFi network is not broadcast by the vehicle.

## Workshop findings:



# Technical Service Bulletin

- No Relevant DTCs are stored.

## Technical Background

The wireless Audi Smartphone Interface requires the 5GHz WiFi network in the vehicle to communicate and stream its content from the phone to the MMI.

Due to a configuration issue, the 5GHz WiFi may not be available in some vehicles, preventing wASI from functioning.


A wired Audi Smartphone Interface connection is not affected by this issue.

## Production Solution

Not applicable.

## Service

Please execute the “*Check control module configuration*” test plan under Guided Functions for the Emergency Call Module and Communication Unit (ConBox) -J949- (address word 0075).

 <b>NOTICE</b>
<b>Parts replacement does not solve this issue. Claims for replaced parts will be subject to review.</b>

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• 110 Up to 48 Months/50,000 Miles.</li> <li>• G10 for CPO Covered Vehicles – Verify Owner.</li> <li>• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
<b>Service Number:</b>	9145		
<b>Damage Code:</b>	AC39		
<b>Diagnostic Time:</b>	GFF	0150 0000	Time stated on the diagnostic protocol (Max 75 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU



# Technical Service Bulletin

---

<b>Claim Comment:</b>	As per TSB 2073333/1
-----------------------	----------------------

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

### Additional Information

All part and service references provided in this TSB (**2073333**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.