Release Date 03/21/2024	
---------------------------------	--

49A4 UPDATE

Brake System Software Update – (NVLW)



Applicable Vehicles							
Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count			
USA	2022	2024	E-TRON GT	5,278			
USA	2022	2024	RS E-TRON GT	1,676			
CAN	2022	2024	E-TRON GT	501			
CAN	2022	2024	RS E-TRON GT	211			

Revision History

Notion motory							
Revision	Date	Purpose					
1	03/21/2024	Original publication					

Condition/Technical Background

This Update h	This Update has been proactively released to prevent the following condition(s) from occurring in the vehicle:					
Criteria	Technical Background					
01	The operating noises made by the hydraulic unit may be louder than usual and/or brake pedal travel may be higher at very low speeds.					

Remedy

Criteria	Remedy		
01 Update the brake electronics and bleed the brake system.			

This Update is in effect until removed.

Vehicle must meet all of the following criteria:

- Procedure is valid only for vehicles that show the **49A4** code in the Elsa Campaign/Action Information screen on the day of repair.
- Vehicle must be within the New Vehicle Limited Warranty.
- Procedure must be performed within the allotted time frame stated in this Technical Service Bulletin.
- Procedure must be performed on applicable vehicles in dealer inventory prior to sale.

Brake System Software Update – (NVLW)



Service

NOTE:

- Elsa is the only valid inquiry/verification source. Check Elsa on the day this vehicle UPDATE will be performed to verify vehicle eligibility for the UPDATE. Status must show "open". Attach an Elsa printout showing the "open" status to the repair order.
- If this UPDATE appears to have already been performed but the code still shows open in Elsa, contact Warranty before proceeding further. Another dealer may have recently performed this UPDATE but not yet entered a claim for it in the system.
- Elsa may also show additional open action(s); if so, inform your customer this work can be done while the vehicle is in for this UPDATE.
- Contact the Warranty Helpline (U.S.) or the Warranty Campaign Specialist (Canada) if you have any questions.



- All Safety Recalls must be completed prior to completing this campaign.
- Proceed to Section A

Brake System Software Update – (NVLW)



Section A – Brake Electronics Software Update

🕛 NC	DTE
Prior to	o launching the VAS Diagnostic Tester and starting an update, ensure the following conditions are met;
\checkmark	The ODIS software is completely up to date.
	 Refer to the "Current ODIS Service Version" document in the Service References section of Elsa2Go.
\checkmark	The battery charger is connected to the vehicle battery and remains connected for the duration of the software update.
	 Battery voltage must remain above 12.5 volts for the duration of the software update. Failure to do so may cause the update to fail, which could result in damage to the control module. Control modules damaged by insufficient voltage will not be covered.
\checkmark	The screen saver and power saving settings are off.
	• Failure to do so may result in the tester entering power save mode during the software update, which could result in damage to the control module.
\checkmark	The VAS Diagnostic Tester is plugged in using the supplied power adapters.
	 Under no circumstances should the tester be used on battery power alone during the software update. Failure to do so may result in the tester powering off during the update, which could result in damage to the control module.
\checkmark	Flash process through " <u>Audi Flashing</u> " not Guided Fault Finding (GFF).
	 DO NOT USE Guided Fault Finding (GFF) to perform this flash. Using GFF will cause the flash to take longer. Requests for additional time will not be considered.
\checkmark	The VAS Diagnostics Interface MUST ONLY be connected to the tester with a USB cable.
	 Performing a software update using a Bluetooth or WiFi connection increases the risk of losing connection during the update, which could result in damage to the control module. It also greatly increases the time required to perform the update. Requests for additional time or parts will be denied if the GFF log shows the update was performed using Bluetooth or WiFi.

i TIP

As a best practice, customer presets should be documented prior to performing any update in the event these settings are lost during the update.

Release Date	03/21/2024
--------------	------------

Brake System Software Update – (NVLW)



- All campaign software updates must be completed during a single, standalone ODIS Diagnostic Session. You must fully complete this campaign and send all logs before beginning any other campaigns or operations.
- If there are any ODIS "Hot-Fix" patches installed, they must be removed from the scan tool before beginning this operation. ODIS "Hot-Fix" patches may affect the update process.

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a serious risk that personal injury may result if contact is made with spinning fan blades. Keep hands and all objects away from Radiator Fan(s) during Update Process!

A IMPORTANT

To Update-Programming using SVM, review and follow instructions in Technical Bulletin 2011732: *Software Version Management (SVM) Operating Instructions* for the US, or 2037026: *Working with the Software Version Management (SVM)* for Canada.

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim.

49A4 UPDATE

Brake System Software Update – (NVLW)

- Switch off all consumers, air conditioning, heater blower motor, lights, heated seats, etc.
- Ensure the latest version of ODIS is downloaded.
- Ensure diagnostic head is connected to ODIS tester via USB cable.
- Move selector lever to P.
- Use operating mode, FLASH.
- Select "SVM Code Input".
- Enter SVM code **49A4A144** and follow the on screen prompts.
- When exiting the FLASH program, ensure the diagnostic log is sent to GFF Paperless.
- If the message pictured is present in the MMI after completing the SVM, follow the on-screen steps in the MMI to detect the parking brake position.

Proceed to section B







Iech

Technical Service Bulletin

49A4 UPDATE

Release Date

Brake System Software Update – (NVLW)



Section B – Brake System Bleeding

03/21/2024

							Guided Functions	×
Control moc Control moc Address 0003 0006 0008 0009 0013 0015	dules dule li Ev 3 0 1 4 1	Orders st (45 en rent	DISS tries) Name Brake Seat a Climate Electro Distant Airbag	TSB Electro djustm e Cont onic ce ce regi (0015	Test plan anics (0003 ent, passe rol Module ntral electri ulation (00 - Airbag) (f	Procedure - Brake Elect nger's side (0 (0008 - HVAK c (0009 - Elect 13 - Distance 992959655D	Brake Electronics 0003 - Break in service brakes 0003 - Service bleeding 0003 - Service brakes: Activate brake application mode 0003 - Indicate parking brake 0003 - Brake Button Initiation 0003 - Critecx control module configuration 0003 - Critecx control module 0003 - Identification 0003 - Indicator lamps 0003 - Reela measuring values 0003 - Replace control module	
0016	0		Steerin	ng colu	mn electro	nics systems	Run Ca	ncel
0017	1		Data R	hent di	D Interface	 Instrument (0019 - Data 	Bus On Board Diagnostic Interface) (4KR907468E 061)	2 Ga



Control modules	Orders	DISS	TSB	Test plan	Procedure	Special Functions		
Basic setting - /	ABS Con	trol Mor	dule - J	104 / parki	ing brake In	itiation		Yes
Preconditions	Preconditions							No
Were the rear b	ling forc bination age is p	e of the of brai	e parki ke pad	ng brake! is and brai	e pads repl	aced?	therwise personal injury or	

After the SVM update, the following fault may have been logged: C10E1F2 – "Parking brake motor position not plausible". This fault must be addressed before performing the brake system bleeding steps.

- Scan the vehicle using GFF.
- If the fault is not present or it is able to be cleared, continue with the brake bleed procedure.
- If fault code C10E1F2 is present and is not able to be cleared:
 - Perform the test plan "0003 Brake Button Initiation" through guided functions of DA 0003.
- Select option #1 for "Perform complete basic setting".
- Follow the on screen prompts.

🕛 NOTE

The test plan will state a road test is required. A road test is not required as there were not any parking brake components replaced.

- When asked if the rear brake rotors or parking brake pads were replaced, select the option for "No".
- Complete the remaining test plan steps.
- After the test plan has completed, cycle the ignition switch off and back on.
- Continue with the brake bleed procedure.

49A4 UPDATE

Brake System Software Update – (NVLW)

Component	Conventional bleeding	Bleeding using the Vehicle Diagnostic Tester	Bleeding the Brake Booster -NX6- using the Vehicle Diagnostic Tester
Brake Booster -NX6-	1	3	2
Brake line from Brake Booster -NX6- to the hydraulic unit	1	2	-
Hydraulic Unit	1	2	-
Suction Line	1	2	-
Brake line from hydraulic unit to brake caliper	1	-	
Brake Caliper	1	-	-

Risk of fluid overflow and paint damage

Portions of the brake bleeding procedure can use a significant amount of brake fluid. Make sure to monitor and empty the recovery container as required.

- The brake system will be bled in 3 steps: •
 - Conventional brake bleeding. 0
 - Bleeding of the NX6 Brake booster 0 via ODIS.
 - Perform service bleeding procedure 0 via ODIS.

While performing brake bleeding steps, there will be several warnings that appear in the instrument cluster and MMI, these can be ignored.

Conventional brake bleeding:

- Perform conventional bleeding of the brakes per the ELSA Repair Manual, referencing the "Conventional bleeding" section of the instructions:
 - Repair manual > Chassis > Brake 0 System > 47 Hydraulic Components > Hydraulic System > Hydraulic System, Bleeding.
- Proceed to next brake bleeding step once the conventional brake bleeding is complete.



A47-1037





Release Date 03/21/2024

ontrol modules Orders DISS TSB Test plan Procedure Spect Guided Function

Airbag (0015 - Airbag) (992959655D 330

Steering column electronics systems (0016 -

instrument cluster (0017 - Instrument Clus

Data Bus OBD Interface (0019 - Data Bus

Brake boost (0023 - Brake Boost) (9J19071

Seat adjustment, driver side (0036 - Drive

Lane change assistance (003C - Lane Cha

ontrol module list (43 entries)

Event

2

0

6

10

0

1

0

0

Address

0015

0016

0017

019

0023

0036

003C

042

Name

49A4 UPDATE Brake System Software Update – (NVLW)

Brake boost

6

0023 - Brake Boost / brake bleeding 0023 - Brake Boost / Function test 0023 - Check control module configuration

0023 - Component Locations

0023 - Identification 0023 - Read measuring values 0023 - Replace control module 0023 - Replace control module

0023 - Event memory check / erase 0023 - Identification

NX6 brake booster bleeding:

Technical Service Bulletin

- Bleed the NX6 brake booster per the ELSA repair manual, referencing the *"Bleeding the Brake Booster -NX6- using the Vehicle Diagnostic Tester"* section of the instructions.
 - Repair manual > Chassis > Brake System > 47 Hydraulic Components
 Hydraulic System > Hydraulic System, Bleeding.
- Select the appropriate test plan in ODIS:
 - Select DA 0023 and open guided functions.
 - Perform the test plan "0023 Brake Boost / brake bleeding".
 - Follow all test plan on screen prompts.

Driver's door electronics (0042 - Driver's Door Electronics) (4M0959793N 0390 15G FS)

Run Cancel

Le

	prompts.
Basic setting - Brake Booster Control Module - J539 / brake bleeding Bleeding routineHR	A CRITICAL REPAIR STEP
The second step of the basic setting brake bleeding (right rear) runs. Status:False result Result:Unknown status	<u>ᡂ STOP!</u> ᡂ
If the test program does not continue automatically, you can quit the basic setting by pressing the ► button.	While the test plan for bleeding the NX6 brake booster is running, the "Status" field may show "False result" and the "Result" field may show "Unknown status". This is normal and not a test plan failure.
	Do not press the complete/continue button! If used, the test plan will fail.
	The test plan will automatically continue once the step is completed.
	 Proceed to next brake bleeding step once the

The repair information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2024 Audi of America, Inc and Audi Canada All Rights Reserved.

 Proceed to next brake bleeding step once the NX6 brake booster bleeding is complete.



l'echnical Service

49A4 UPDATE Brake System Software Update – (NVLW)

03/21/2024



						Guided Functions	
						Brake Electronics	
Control mod	dules Orde	s DISS	TSB	Test plan	Procedure	0003 - Break in service brakes	
Control mor	dule list (45	entries)				0003 - Remove brake pads	
Address	Event	Name				0003 - Service brakes: Activate brake application mode	
0003	3	Brake	Electro	onics (0003	- Brake Elec	0003 - calibrate parking brake	
0006	0	Seat a	Seat adjustment, passenger's side (0 0003 - Brake Button Initiation 0003 - Check control module configuration				
8000	0	Climat	e Cont	rol Module	(0008 - HVA	0003 - Component Locations 0003 - Event memory check / erase	
0009	1	Electronic central electric (0009 - Elec 0003 - Identification 0003 - Indicator lamps	0003 - Identification 0003 - Indicator lamps				
0013	4	Distar	ice reg	ulation (001	13 - Distance	0003 - Read measuring values 0003 - Replace control module	
0015	1	Airbag	(0015	- Airbag) (§	992959655D		
0016	0	Steeri	ng colu	imn electroi	nics systems		
0017	1	instrur	nent d	uster (0017	- Instrument	Run Cancel	
0010		Data		D later da an	(0010 D-1	Due On Devel Discovering Interferent (AVD0074005, 0010, 0	

Service bleeding procedure:

- Bleed the brakes per the ELSA repair manual, referencing the "Bleeding using the Vehicle Diagnostic Tester" section of the instructions.
 - Repair manual > Chassis > Brake System > 47 Hydraulic Components
 Hydraulic System > Hydraulic System, Bleeding.
- Select the appropriate test plan in ODIS:
 - Select DA 0003 and open guided functions.
 - Perform the test plan "0003 Service Bleeding".
 - Follow all test plan on screen prompts.

CRITICAL REPAIR STEP



While the service bleeding test plan is running, the "Result" field may show "Unknown status". This is normal and not a test plan failure.

Do not press the complete/continue button! If used, the test plan will fail.

The test plan will automatically continue once the step is completed.

The test plan states to apply and release the brake pedal in cyclical periods. There is not a specified interval or number of times the pedal must be pressed and released. The test plan will continue automatically once the conditions have been satisfied.

- Perform a bus sleep on the vehicle.
- Erase the fault memory by exiting the GFF session.

To put the vehicle in bus sleep mode, disconnect the diagnostic tester, remove the key from the vehicle and lock the vehicle with the remote for 5 minutes.

Basic setting - ABS Control Module - J104 / service bleeding Bleeding routine HL

The basic setting Service bleeding (left rear) runs, note that the bleeding phase on the left rear wheel can take up to 5 minutes

Result: Unknown status

Release Date

- Apply and release the brake pedal now in cyclical periods until the respective bleeding phase is completed.

if the test program does not continue automatically, you can quit the basic setting by pressing the 🕨 button.

(-)

Brake System Software Update – (NVLW)



Warranty

Claim Entry Instructions

After Update has been completed, enter claim as soon as possible to help prevent work from being duplicated elsewhere. Attach the Elsa screen print showing action <u>open on the day of repair</u> to the repair order.

If customer refused campaign work or vehicle is out of the specified warranty parameter for this Update:

- ✓ <u>U.S. dealers:</u> Submit the request through Audi Warranty Online under the <u>Campaigns/Update</u> option.
- ✓ <u>Canada dealers:</u> Upload the repair order to Audi WIN/Operations/Campaign Closure.

Service Number	49A4				
Damage Code	0099				
Parts Vendor Code	002				
Claim Type	Sold vehicle: 7 10 Unsold vehicle: 7 90				
Causal Indicator	Mark labor as causal				
Vehicle Wash/Loaner	Do not claim wash/loaner under this action				
Criteria I.D.	01				
	LABOR				
	Labor Op	Time Units	Description		
	0151 00 10	SEE ELSA	Software update (setup + battery charger)		
	0151 00 60	Time stated on diagnostic protocol	Perform Software update		
	0150 00 60	Time stated on diagnostic protocol	GFF/Guided functions (perform necessary test plans)		
	0150 00 99	10	Bus sleep procedure		
	4701 07 50	SEE ELSA	Brake system bleed (initial bleed procedure, claim only once)		
	4701 07 70	SEE ELSA	Brake system bleed (additional bleed procedures, can be claimed up to 2 times)		
	PARTS				
	Quantity Part Number Description				
	Up to 45.00 B 000750S0 BRAKE FLUID (up to 4.5 L)				

Release Date	03/21/2024
	00/21/2021

49A4 UPDATE

Brake System Software Update – (NVLW)



Additional Actions	Some of the affected vehicles may be involved in additional Actions. Please check your Elsa Campaign/Action Information screen so that any <i>additional required work can be done simultaneously</i> .
Verifying Vehicle Eligibility	To verify vehicle eligibility for this Update, <i>always</i> check the Elsa Campaign/Action Information screen. The Elsa system is the <i>only</i> binding inquiry and verification system; other systems are not valid and <i>may result in non-payment</i> of a claim.
Help for Claim Entry	For questions regarding claim entry, contact Audi Warranty.
Required Customer Notification	Inform your customer in writing by recording on the Repair Order any and all work that was conducted on the vehicle, including any and all updates completed under this Update.

Required Parts

Parts Control Type: Free Order	Parts will be managed by Free Order		
Initial Allocation:	Please reference the Repair Projection Tool (below) to view your potential VIN		

Repair Projection Tool: (right click to open)	Q

Criteria	Quantity	Part Number	P.O.C. Part Description	Ordering Method
01	Up to 4.5 L	SEE ETKA/P.O.C.	BRAKE FLUID	Parts on Command

O IMPORTANT PARTS INFORMATION

Brake Fluid Ordering Information

Any DOT 4 brake fluid part number listed in Parts on Command can be used.

population.

I NOTE

Campaign parts should always be ordered as per the parts information in this circular. The ordering system will supersede the part, if applicable.

Properly store (retain), destroy, or dispose of removed parts in accordance with all state/province and local requirements, unless otherwise indicated and/or requested through the Warranty Parts Portal (WPP) for U.S. and the Part Destruction and Core Disposition Report for Canada.

Release Date	03/21/2024
Release Dale	03/21/2024

Brake System Software Update – (NVLW)



Required Special Tools

	Battery Tester/Charger capable of minimum 90 Amp continuous supply	Diagnostic Tester -VAS6150X/VAS6160X- (or equivalent)
	Brake Filling and Bleeding Equipment -VAS6860- (or equivalent)	Brake Bleeding Tool Set -VAS6564- (or equivalent)
a state	Wrench – Brake Bleeder Set -VAS5519- (or equivalent)	

Additional Information

All parts and service references provided in this Update are subject to change and/or removal. Always check Elsa for the most current version of this document.