

ARA2 - Checking and if Necessary Replacing Three-Point Belt on Rear Left and Right (Recall Campaign)

Model Line: **911 Targa (992)**

Model Year: **2023**

Country/Market: USA (C02)
Canada (C36)

Concerns: **Child safety function on the rear three-point belt and the left and right**

Cause: **On the rear three-point seat belt at the left and right, there is the possibility that the automatic seat belt extension lock for mounting a child seat does not work properly due to a manufacturing error on the seat belt retractor.**


If this is the case, the belt extension lock can be switched off in an undefined manner, and the belt can then continue to be unrolled and pulled out. As a result, the child seat is not fixed in accordance with the specifications.

Action: Check the rear three-point belt at the left and right and replace it if necessary.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Installation

Position:



Installation position for rear three-point belts (shown on 911 Targa)

Required parts



Information

No parts are required for checking the rear three-point belts.



Information

The forecast failure rate is only 0.5%.

Therefore, please order the parts required for replacing defective three-point belts only after a test and the actual need for replacing one or both three-point belts.

The **part numbers** of the **required parts** for the respective vehicle can be seen in the **assigned scope**. For an overview of the campaign scopes, see: ⇒ *Technical Information 'Warranty processing'*

Required tools

- Torque wrench, 2-10 Nm (1.5-7.5 ftlb.), e.g., **V.A.G 1783 - torque wrench, 2-10 Nm (1.5-7.5 ftlb.)**

- Torque wrench, 6-50 Nm (4.5-37 ftlb.), e.g. **V.A.G 1331A - torque spanner, 6-50 Nm (4.5-37 ftlb.)**
- **T10118 - Assembly tool**

Check the rear three-point belt at the left and right

Work

Procedure:



Information

The test procedure is shown as an example. The following test must be performed on both three-point rear left and right belts.

- 1 Insert the three-point belt into the belt buckle using the belt buckle and ensure that it locks ⇒ *Closing three-point belt.*




Closing three-point belt

- 2 Pull out the belt strap completely ⇒ *Pulling out belt strap* to activate the child safety function (ALR automatic locking retractor).



Pulling out belt strap

- 3 Slowly allow the belt to roll up, making sure that a click can be heard during retraction ⇒ *Rolling up belt strap*.
The belt strap must be held in place by hand.



Rolling up belt strap


- 4 As soon as the belt strap is retracted, check whether it can be pulled out again or is locked ⇒ *Pulling out belt strap and checking belt lock*.

If it is found during the inspection of a three-point belt that the **belt does not lock**, the affected three-point belt must be replaced. To do this, continue with:

- Replacing rear three-point belt at the left **and / or**
- replacing rear three-point belt at the right

See ⇒ *Technical Information 'Replacing rear three-point belt'*.

If the belt strap is locked and a click can be heard when the three-point belt is retracted:



Pulling out belt strap and checking belt lock



Information

The test must be carried out **ten times** on both three-point rear belts.

- **Repeat steps 1 to 5 ten times on both three-point belts.**



Information

If the child safety feature **does not** meet the specifications even once during the ten checks, the affected three-point belt must be replaced.

If it can be confirmed after ten checks that the child safety function of the rear three-point belts works according to specifications, they do **not** need to be replaced.

If **both rear three-point belts function according to specifications**, the action must be completed as follows:

- Entering campaign in Warranty and Maintenance logbook
- **Scope 1**

Replacing rear three-point belt

Work Procedure: 1 Replace the rear three-point belt at the left **and / or** right.

911 Coupé: Replace the rear three-point belt at the left **and / or** right.
 ⇒ *Workshop Manual '69121901 Removing and installing rear three-point belt (Coupé)'*

Scope 2 or 3

911 Cabriolet: Replace the rear three-point belt at the left **and / or** right.
 ⇒ *Workshop Manual '69121915 Removing and installing rear three-point belt (Cabriolet)'*

Scope 4, 5 or 6

911 Targa: Replace the rear three-point belt at the left **and / or** right.
 ⇒ *Workshop Manual '69121911 Removing and installing rear three-point belt (Targa)'*

Scope 7, 8 or 9

2 Enter the campaign in the Warranty and Maintenance logbook.

Warranty processing



Information

The specified labor times were determined specifically for carrying out this campaign and include all necessary preliminary and subsequent rework. The labor times may differ from the labor times published in the Labor Operation List in PCSS.

Scope 1: **Check the rear three-point belt at the left and right**

Labor time:

Check the rear three-point belt at the left and right Labor time: **28 TU**

⇒ **Damage Number ARA2 099 000 1**

Scope 2-6: **Not relevant for this vehicle type.**

Scope 7: **Checking and replacing rear three-point belt at the left**

Labor time:

Checking and replacing rear three-point belt at the left Labor time: **178 TU**
 Includes: Removing and installing rear backrest
 Removing and installing rear seat cushion
 Loosen and secure roll-over protection frame

Required parts:

992857805C XXX*	Rear three-point belt at the left	1 piece
N 98925801	Cheese head bolt with multiple-tooth head	1 piece
N 98926102	Cheese head bolt with multiple-tooth head	1 piece
N 91026201	M10 hexagon collar nut	2 pieces
PAF008845	M10 x 60 multiple-tooth flange screw	8 pieces
PAF008148	M8 x 30 collar screw	10 pieces
992880421	M10 x 40 countersunk screw with internal serration	4 pieces

*The color variant of the rear three-point belt or belts required for the respective vehicle can be seen using the vehicle ID No. in the PCSS vehicle information.

⇒ **Damage Number ARA2 99 000, Repair Code 2**

Scope 8:

Checking and replacing rear three-point belt at the right**Labor time:**

Checking and replacing rear three-point belt at the right Labor time: **178 TU**
 Includes: Removing and installing rear backrest
 Removing and installing rear seat cushion
 Loosen and secure roll-over protection frame

Required parts:

992857806C XXX*	Rear three-point belt at the right	1 piece
N 98925801	Cheese head bolt with multiple-tooth head	1 piece
N 98926102	Cheese head bolt with multiple-tooth head	1 piece
N 91026201	M10 hexagon collar nut	2 pieces
PAF008845	M10 x 60 multiple-tooth flange screw	8 pieces
PAF008148	M8 x 30 collar screw	10 pieces
992880421	M10 x 40 countersunk screw with internal serration	4 pieces

*The color variant of the rear three-point belt or belts required for the respective vehicle can be seen using the vehicle ID No. in the PCSS vehicle information.

⇒ **Damage Number ARA2 99 000, Repair Code 2**

Scope 9:

Checking and replacing rear three-point belt at the left and right

Labor time:

Checking and replacing rear three-point belt at the left and right Labor time: **218 TU**

Includes: Removing and installing rear backrest
 Removing and installing rear seat cushion
 Loosen and secure roll-over protection frame

Required parts:

992857805C XXX*	Rear three-point belt at the left	1 piece
992857806C XXX*	Rear three-point belt at the right	1 piece
N 98925801	Cheese head bolt with multiple-tooth head	2 pieces
N 98926102	Cheese head bolt with multiple-tooth head	2 pieces
N 91026201	M10 hexagon collar nut	2 pieces
PAF008845	M10 x 60 multiple-tooth flange screw	8 pieces
PAF008148	M8 x 30 collar screw	10 pieces
992880421	M10 x 40 countersunk screw with internal serration	4 pieces

*The color variant of the rear three-point belt or belts required for the respective vehicle can be seen using the vehicle ID No. in the PCSS vehicle information.

⇒ **Damage Number ARA2 99 000, Repair Code 2**

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.