

Technical Service Bulletin

93 Q4 e-tron: vehicle/HV battery does not charge, drive system unavailable 00C6; DTC P1A0800, P1A0F00, P0A9500, PA1600

93 24 49 2073560/1 April 3, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q4 e-tron quattro, Q4 e- tron RWD, Q4 Sportback e-tron	2024	All	Not Applicable

Condition

Customer states:

- The vehicle/high-voltage battery cannot be charged.
- The drive system cannot be activated.

Workshop findings:

• The customer statement can be reproduced.

In the control unit for high-voltage battery charging unit (diagnostic address 00C6), either one of the following DTC entries (intermittent/static) is stored for the **AC fuse**, or a DTC entry (intermittent/static) is stored for the **DC fuse**.

1. AC fuse:

- P1A0800: Charging unit 1 fuse blown Symptom: 397395
- P1A0F00: Charging unit 2 fuse blown Symptom: 397396
- P1A1600: Charging unit 3 fuse blown Symptom: 397397

OR

2. DC fuse:

P0A9500: Fuse for high-voltage system Symptom: 401501

Technical Background

Not applicable.

Production Solution

Not applicable.

Service



Technical Service Bulletin

1. AC fuse: Perform charge test, delete event memory entry, and reassess complaint / replace high-voltage battery charging unit - J1050 - (if necessary)

OR

2. DC fuse: Switch terminal 15 off and on again, delete event memory entry and check drive system can be activated / replace high-voltage battery charging unit - J1050 - (if necessary)



NOTICE

Depending on the fuse which has an event memory entry (AC or DC) logged, proceed as follows:

Regarding AC fuse:

Carry out an AC charge test, delete the DTC entry/entries and reevaluate the complaint:

- If the charge test is successful and the DTC entry/entries can be deleted:
 - The measures are completed and the vehicle can be returned to the customer.
- If the charge test is <u>not</u> successful and/or the event memory entry/entries <u>cannot</u> be deleted, then the highvoltage battery charging unit - J1050 - must be replaced as per the ELSA Workshop Manual.

OR

Regarding DC fuse:

Switch off and on terminal 15, delete DTC entry and check if the drive system can be restored:

- If the DTC entry can be deleted after terminal 15 has been switched off and on again, and the drive system can be restored:
 - The measures are completed and the vehicle can be returned to the customer.
- If the DTC entry <u>cannot</u> be deleted after switching terminal 15 off and on again and/or the drive system <u>cannot</u> be restored, then the high-voltage battery charging unit – J1050 - must be replaced as per the ELSA Workshop Manual.

Warranty

Claim Type:	• 110 Up to 48 Months/50,000 Miles.				
	G10 for CPO Covered Vehicles – Verify Owner.				
	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.				
Service Number:	9352				
Damage Code:	0040				
Labor Operations:	Replace high-voltage battery charging unit – J1050 (if necessary)	9352 5550	See SRT with associated operations		



Technical Service Bulletin

Diagnostic Time:	GFF	0150 0060	Time stated on the diagnostic protocol (Max 100 TU)
	Test drive before the service procedure	No allowance	0 TU
	Test drive after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2073560/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.				
Part Number	Part Description	Quantity		
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA		
See ETKA	High-voltage battery charging unit – J1050	01		

Additional Information

All parts and service references provided in this TSB (2073560) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.