

Condition

Applicable Vehicles						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	
Atlas	2018-2021	3.6L (CDVC)	All	All	All	
Atlas Cross Sport	2020-2021	3.6L (CDVC)	All	All	All	

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2073713/1	04/30/2024	01-24-04	Original Publication

The following fault code is stored in the Engine/Motor Control Module -J623- (ECM) Fault Memory:

DTC	Description
P148D	Evaporative Emission System Leak Detection Pump Implausible Frequency

NOTICE

Do NOT diagnose or replace components due to P148D fault before performing the update function as explained in this bulletin.



Technical Background

Updated programming of the Engine/Motor Control Module -J623- (ECM) software is based on most recent engineering experiences and makes this knowledge available for the monitoring strategies.

Production Solution

Updated Engine/Motor Control Module -J623- (ECM) software introduced in Model Year 2022 Production.

Service

Update-Programming Procedure:

<u>Critical Warning</u>: The VAS5908KIT battery charger <u>must</u> be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process and should monitor the voltage for the duration of the update.

The procedure may cancel itself if the hazard warning lights are not switched ON. The hazard warning lights prevent the system from switching to bus sleep mode during the update.

ODIS-Service tester should be updated to the latest GFF technical version 24.0.1 or higher and SW version 2.49.18 or higher.

Radiator Fan(s) may cycle ON high speed during the Update process! There is a risk that personal injury may result if contact is made with spinning blades. Keep hands and all objects away from the Radiator Fan(s) during the update process!

Prior to launching the ODIS Service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Diagnostic Device Hardware & Windows® - VHW-22-13 Change Power Options After Windows®10 Upgrade. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure. When using a VAS 6150/X or 6160/X tester in conjunction with a VAS6154A wireless transmitter head for a flash procedure, connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure. VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure

© 2024 Volkswagen Group of America, Inc.



NOTICE

To Update-Programming using Software Version Management (SVM), review and follow instructions in Technical Bulletin Instance 2014603 "Software Version Management". The SVM process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

• Update the Engine Control Module using the SVM Unit code as listed in the table below:

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code
MY 18	3.6L	03H.906.026.E	4744	03H.906.026.E	9974	4DB8
Atlas	CDVC		6024			
			6695			
			9970			
			9971			
			9972			
			9973			
		03H.906.026.F	4745	03H.906.026.F	9974	4DB8
			6025			
			6696			
			9970			
			9971			
			9972			
			9973			
		03H.906.026.J	4748	03H.906.026.J	9974	4DB8
			6026			
			6697			
			9970			

Page 3 of 7 Plus attachment

© 2024 Volkswagen Group of America, Inc.



			9971			
			9972			
			9973			
MY 19	3.6L	03H.906.026.R	6692	03H.906.026.R	9974	4DB8
Atlas	CDVC		9970			
			9971			
			9972			
			9973			
		03H.906.026.S	6693	03H.906.026.S	9974	4DB8
			9970			
			9971			
			9972			
			9973			
		03H.906.026.AA	6694	03H.906.026.AA	9974	4DB8
			9970			
			9971			
			9972			
			9973			
MY20	3.6L	03H.906.026.AH	9970	03H.906.026.AH	9977	4DB8
Atlas	CDVC		9971			
			9972			
			9973			
			9975			
			9976			
		03H.906.026.AG	9970	03H.906.026.AG	9977	4DB8
			9971			
			9972			
			9973			
			9975			

Page 4 of 7 Plus attachment

© 2024 Volkswagen Group of America, Inc.



			9976			
		03H.906.026.AF	9970	03H.906.026.AF	9977	4DB8
			9971			
			9972			
			9973			
			9975			
			9976			
MY20	3.6L	03H.906.026.AG	9970	03H.906.026.AG	9977	4DB8
Atlas Cross	CDVC		9971			
Sport			9972			
			9973			
			9975			
			9976			
MY21	3.6L	03H.906.026.AJ	0454	03H.906.026.AJ	3644	4DB8
Atlas	CDVC		0638			
			1017			
			1689			
			2666			
			3172			
MY21	3.6L	03H.906.026.AJ	1017	03H.906.026.AJ	3644	4DB8
Atlas Cross	CDVC		1689			
Sport			2666			
			3172			

NOTICE

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software. Ensure attached ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.

^{© 2024} Volkswagen Group of America, Inc.



Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾

Model(s)	Year(s)		Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To	
Atlas	2018-2021		3.6L (CDVC)	All	All	All	
Atlas Cross Sport	2020-2021		3.6L (CDVC)	All	All	All	
		-	SAGA	Coding			
Claim Type:		Use	applicable Claim	Type ¹⁾			
Service Number:			Damage Code	HST		Damage Location (Depends on Service No.)	
2470			0039				
Parts Manufacturer		Atlas / Atlas Cross Sport		WWO ²⁾			
Labor Operation ³⁾ : Preparation and battery charge			and battery	01500010 = See Elsa for latest time units			
Labor Operation ³⁾ : Update Programming Engine/Motor Control Module -J623-				24705599 = Actual GFF Print out, up to 50 TU max			
Causal Part:				24705599			
			Diagnos	tic Time ⁴⁾			
-		01500060 = Actual GFF print out		NO			
Road Test		(01210004 = 10 TL	U YES		S	
Technical Diagnosis 01320000 = 00 T			01320000 = 00 TL	J max.	NO		

^{© 2024} Volkswagen Group of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.

²⁾ Code per warranty vendor code policy.

³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.

⁴⁾ Documentation required per Warranty Policies and Procedures Manual.

Required Parts and Tools

No Special parts required.

Tool Description	Tool No:
Battery Tester/Charger	VAS5908KIT
	Or
	MTRMSP0702 battery maintainer/charger
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X and
	ODIS Service with current online updates

Additional Information


All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.



OWNER INFORMATION ABOUT CONTROL MODULE TUNING* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

*) "TUNING" is described as the addition of or modification of any component which causes a Volkswagen vehicle to perform outside the normal parameters and specifications approved by Volkswagen Group of America / Volkswagen Group Canada.

Date:	
Dealer Number:	_
Vehicle Identification Number:	
Repair Order Number:	



Dealer stamp

_____, owner or driver of the above identified Volkswagen, confirm:

"Tuning" as described above (especially power increasing modifications) has NOT been performed on my vehicle.

"Tuning" as described above has been performed on my vehicle and the following components were modified or installed:

<u>TUNING was performed by (Please provide Company name and telephone number, if you wish us to contact them):</u>

I understand that if my Control Module is determined to have been tuned, any damage caused by the tuning of the Control Module (including adverse emissions consequences) will not be covered by VWGoA / VGC warranties.

I am permitting an authorized Volkswagen Dealer to reflash (update) my Control Module, and by doing so, I understand that this process will automatically overwrite (destroy) and permanently delete any tuning program that was previously installed on the Control Module of my Volkswagen vehicle.

By signing below, I fully acknowledge and understand that the tuning program will not be restored and VWGoA / VGC, will not be liable in any way for the loss of tuning data.

Signature of Customer

^{© 2024} Volkswagen Group of America Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright intellectual groups rights of VGoA / VGCA inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.