# 1000(136



## Service Bulletin

File In Section: 04 - Driveline Axie

Bulletin No.: 03-04-17-001

Date: February, 2003









## TECHNICAL

Subject: Whine Noise From Rear Axie (Diagnose and Replace Rear Shaft With

A Tuned Torsional Damper Rear Propeller Shaft)

Modele: 2002-2003 Cadillac Escalade EXT ✓

2000-2003 Chevrolet Suburban / 2002-2003 Chevrolet Avalanche -

2000-2003 GMC Yukon XL, Yukon XL Denali 🗸

#### Condition

Some customers may comment on a slight exter whine heard only at certain speeds, typically between 72-98 km/h (45-60 mph).

#### Cause

"Inherent" ring and pinion gear whine.

All gear driven units, such as automotive rear axies, produce some level of noise that cannot be eliminated with conventional adjustments and repairs. "Inherent" axie noise can be described as a slight noise heard only at a certain speed (typically between 72-98 km/h (45-60 mph) on most General Motors® trucks). The presence of this noise is not indicative of a functional concern with the axie assembly. However, some customers may find that this "inherent" axie noise is unacceptable.

### Correction

Replace the rear propeller shaft with a tuned torsional damper shaft ONLY after diagnosis concludes that it is an "inherent" rear axle noise and no physical damage or incorrect adjustment exists.

Important: If the noise is not correctly diagnosed as "inherent" and having a peak in the narrow speed range of 72-96 km/h (45-60 mph), the addition of a tuned torsional damper propeller shaft can aggravate the perceptible noise level. It is extremely important to first diagnose the rear exic noise as "inherent" before installing a new tuned torsional damper propeller shaft.

## Diagnostic Information and Procedure for Rear Axie Noise

- Diagnostic Starting Point Rear Drive Axte. Refer to SI Document ID #696972.
- Symptoms Rear Drive Axle. Refer to SI Document ID #697220.
- Rear Drive Axle Noises. Refer to SI Document ID #700560.
- Noisy in Drive. Refer to Si Document ID #698120.

## Rear Propeller Shaft Replacement

- Raise the vehicle. Refer to Lifting and Jacking the Vehicle in General Information. Refer to SI Document ID #737171.
- Remove the boits and the yoke retainers from the rear axte pinion yoke.

**Notice:** When removing the propeller shaft, do not attempt to remove the shaft by pounding on the yoke ears or using a tool between the yoke and the universal joint. If the propeller shaft is removed by using such means, the injection joints may fracture and lead to premature failure of the joint.

 Silde the propeller shaft forward in order to disconnect the propeller shaft from the rear axie pinion yoke.

Bulletin No.: 03-04-17-001

- Slide the propeller shaft rearward in order to disconnect the propeller shaft from the transmission or transfer case.
- Remove the propeller shaft from the vehicle and discard.
- Install the new tuned torsional damper propeller shaft (see Parts Information below) into the transmission or transfer case.
- Install the propeller shaft to the rear axie pinion yoke.
- 8. Install the yoke retainers and bolts.

## Tighten

Tighten the yoke retainer botts to 25 N·m (19 to ft).

- 9. Lower the vehicle.
- Road test the vehicle.

#### Parts information

**Important:** Only small quantities of parts are available. Please DO NOT order for stock only.

Part Number	Description		
15075236	Rear Prop Shaft with Tuned Torsion Damper (2WD Suburban, Avalanche, Yukon XL)		
157 <b>67</b> 17B	Rear Prop Shaft with Tuned Torsion Damper (4WD Suburban, Avalanche, Yukon XL and 2003 only AWD Yukon XL Denali, Escalade EXT, with NR3 Transfer Case)		
15084596	Rear Prop Shaft with Tuned Torsion Damper (2001 and 2002 only AWD Yukon XL Denail, Escalade EXT with NP3 Transfer Case)		

Parts are expected to be available from GMSPO on February 17, 2003.

### Warranty Information

For vehicles repaired under warranty, use:

Lab		Description	Lebor Time
F12	80	Propeller Shaft Assembly (Rear) - Replace	Use published labor operation time
Add	A	Diagnosis Time	0.0-0.3 hr