



Service Bulletin

File In Section: 06 - Engine/Propulsion System

Bulletin No.:

07-06-02-006A

Date:

May, 2008

TECHNICAL

Coolant Leaking from Engine (Replace Coolant Crossover Pipe Gaskets) Subject:

Models:

2006-2007 Buick Terraza

2006-2007 Chevrolet Impala, Malibu, Monte Carlo, Uplander

2006-2007 Pontiac G6, Montana SV6

2006-2007 Saturn Relay

2007 Saturn AURA with 3.5L or 3.9L Engine (VINs N, K, I, R, W — RPOs LZ4, LZE, LZ9, LZ8, LGD)

This bulletin is being revised to update the labor code in the Warranty Information section. Please discard Corporate Bulletin Number 07-06-02-006 (Section 06 — Engine).

Condition

Some customers may comment on coolant leaking from the engine.

Cause

The gasket located between the coolant crossover pipe and the front of the right (rear side) cylinder head may be leaking.

Correction

Replace the coolant crossover pipe gaskets with current service replacement gaskets, P/Ns 12577704 and 12590668. Before installing the new gaskets, make sure that the mating surfaces on the crossover manifold and cylinder head are completely clean and that NO OIL or OIL RESIDUE exists.

Parts Information

Part Number	Description	Qty	
12577704	Gasket, Coolant Crossover Pipe	1	
12590668	Gasket, Coolant Crossover Pipe	1	

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
J3529	Engine Coolant Crossover Pipe Replacement	Use Published Labor Operation Time