



#### 94 Moisture accumulation in headlamps

94 12 68 2028277/2 March 1, 2012. Supersedes Technical Service Bulletin Group 94 number 11 – 62 dated December 20, 2011 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
	2010	All	Not Applicable	
Audi Q7	2011	All		
	2012	000001 – 021250		

#### Condition

REVISION HISTORY					
Revision	Date	Purpose			
2	-	Revised Service Revised Required Parts and Tools			
1	12/20/2011	Original publication			

#### **Customer Complaint:**

- Considerable moisture present in headlamp.
- The moisture disappears only after extended drives (greater than 10 minutes).

#### **Workshop Findings:**

 No external damage to headlamp which could introduce moisture.



Figure 1. Moisture in headlamp.

# Audi

## Technical Service Bulletin

### **Technical Background**

Humid air settles on the inside of the glass, causing moisture to appear on the inside of the headlamp lens. Because of the headlamp circulation system, outside air is allowed to flow through the headlamps. The open, water-protected ventilation system (needed for pressure compensation) creates different "climate zones" inside the headlamp, where the lens is either warmed up by the light or cooled down by passing air.

When high air humidity and temperature differences exist between the inside of the headlamps and the outside, condensation can form on the inside of the lens, especially in cold and wet weather. The moisture in the headlamps can be compared with condensation on the windshield, which is cleared by the "defroster vent". This moisture buildup can happen for example: after a car wash, after steam cleaning of the engine or the front end, or after overnight temperature changes.

This condition is more easily visible with headlamps made from clear glass. The moisture is an *optical condition* which *DOES NOT* affect the headlamp function (light performance) and does not lead to corrosion nor does it lead to damage of the internal headlamp parts.

This condition is common to all exterior vehicle lights, and can occur on every headlamp, fog lamp, or rear lamp.

#### **Production Solution**

Optimized headlamp ventilation hose placed in to production.

#### **Service**

- 1. Remove the headlamps and dry the inside using compressed air or hot air blower.
- Replace the headlamp ventilation hose for each headlamp with the new part number to help reduce any further humidity ingress into the headlamps (see Part information table below).
   The modified ventilation hose can be recognized by the integrated filter as seen in Figure 2.




Figure 2. Ventilation Hose with Integrated Filter

# Audi

## Technical Service Bulletin

- 3. Reinstall headlamps.
- 4. Please inform the customer the new ventilation hoses are only to help reduce this condition, but will not eliminate this condition completely. Moisture in the headlamp lens is normal and can occur even with the improved ventilation hose.

## **Warranty**

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.					
Service Number:	9415					
Damage Code:	0010					
Labor Operations:	Remove and reinstall both headlamps	9415 2001	50 TU			
	Modify both headlamps	9415 5099	20 TU			
Diagnostic Time:	GFF – Checking and clearing fault codes included in existing labor operations	No allowance	0 TU			
	Road test prior to service procedure	No allowance	0 TU			
	Road test after service procedure	No allowance	0 TU			
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online	e for DADP allowan	ce details)			
Claim Comment:	As per TSB #2028277/2					

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

### **Required Parts and Tools**

Part Number	Part Description	Quantity
4L0 941 717 A	Left Headlamp Ventilation Hose	1
4L0 941 718 A	Right Headlamp Ventilation Hose	1



# Technical Service Bulletin

## **Additional Information**

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.