



THIS SERVICE ACTION IS VALID FOR A LIMITED TIME ONLY AND WILL EXPIRE ON 31 MARCH 2014 ISSUE '2' CHANGES ARE HIGHLIGHTED IN GRAY

SECTION: 417

Service Action: Left-Hand Rear Lamp LED Failure

AFFECTED VEHICLE RANGE:

XF (X250)

VIN: R00001 - R61290

Model Year: 2009 - 2010

CONDITION SUMMARY:

Situation: On a limited number of 2009 – 2010 model year Jaguar XF vehicles within the VIN range above, the light emitting diode (LED) within the left-hand (LH) rear lamp assembly may fail due to corrosion of the silver lead frame.

NOTE: Lamps not being replaced must have the vent tubes replaced. New vent tubes are of a different material specification.

Action: Retailers are required to 'HOLD' all affected vehicles within their control and refrain from releasing the vehicles for onward distribution and sale pending completion of the rework actions detailed in this bulletin. Affected vehicles in the hands of owners should be repaired at the next available opportunity. At the time of customer appointment, ensure that all outstanding service campaigns for each individual vehicle are identified and allocate sufficient time and resources to complete all campaigns. Refer to the Repair Procedure outlined below.

PARTS:

Table with 4 columns: PART NO., DESCRIPTION, QTY, % OF VEHICLES REQUIRING PART**. Rows include C2Z16257 (Lamp cluster - LH) and C2Z22775 (Vent tube).

* Minimum order fulfillment is a package of six (6) vent tubes; vent tubes are only supplied in packs of six (6). Three (3) vent tubes are required only if the LH lamp is not replaced; new lamps do not require vent tubes.

** The majority of vehicles will only require vent tubes be installed and not a lamp replaced; the expected lamp replacement rate is inline with current retailer replacement rate.

TOOLS:

Refer to Workshop Manual for any required special tools

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time. Check DDW to ensure that the vehicle is affected by this Service Action prior to undertaking any rework action. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code 'K106' together with the relevant Option Code from the table. The SRO and part information listed have been included for information only.

The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

This Service Action is valid for a limited time only. Warranty claims with a repair date prior to the **31 March 2014** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NUMBER	QTY.
K106	B	Inspect LH rear lamp; if OK, fit vent tubes	05.10.30	0.30	C2Z22775	†
K106	C	Inspect LH rear lamp; if OK fit vent tubes Drive in / drive out	05.10.30 10.10.10	0.30 0.10	C2Z22775 -	† -
K106	D	Inspect LH rear lamp; if not OK, renew LH lamp	05.10.30	0.30	C2Z16257	1
K106	E	Inspect LH rear lamp; if not OK, renew LH lamp Drive in / drive out	05.10.30 10.10.10	0.30 0.10	C2Z16257 -	1 -

† retailers will be reimbursed for six (6) vent tubes

Normal warranty policies and procedures apply

REPAIR PROCEDURE

INSPECT LEFT-HAND REAR LAMP ASSEMBLY OPERATION

1. Turn the exterior lights 'ON'.
 - If the left-hand (LH) lamp assembly LEDs are functioning correctly, perform steps 2-4 below only.
 - If the LH rear lamp assembly LEDs are not functioning correctly, perform step 5 below only.
2. Refer to Workshop Manual, section 417-01: *Exterior Lighting*, and remove the LH rear lamp assembly.

△ NOTE: Lamps not being replaced must have the vent tubes replaced. New vent tubes are of a different material specification.

3. Replace the vent tubes:
 - Release and remove the three (3) vent tubes from the lamp assembly.
 - Install three (3) new vent tubes to the lamp assembly.

4. Refer to Workshop Manual, section 417-01: *Exterior Lighting*, and install the LH rear lamp assembly.

△ NOTE: New lamps do not require vent tube installation.

5. Refer to Workshop Manual, section 417-01: *Exterior Lighting*, and replace the LH rear lamp assembly.

