



Service Bulletin

File in Section: -

Bulletin No.: PI0746B

Date: October, 2012

PRELIMINARY INFORMATION

Subject: Malfunction Indicator Lamp (MIL) On, Poor Acceleration, Throttle Body Freezing, Multiple DTCs Set, Ice Deposits and/or Oil Deposits Present in Air Inlet Duct

Models: 2008-2011 Buick Enclave
 2007-2011 Chevrolet Malibu
 2009-2011 Chevrolet Traverse
 2007-2011 GMC Acadia
 2007-2010 Pontiac G6
 2007-2010 Saturn OUTLOOK
 Equipped with 3.6L Engine (RPOs LY7, LLT)

This PI is being revised to add the 2007-2010 G6 and update the 2007-2008 Parts Information. Please discard PI0746A.

Condition/Concern

Some customers may comment that the malfunction indicator lamp (MIL) is on.

They may also comment on poor engine performance and/or reduced acceleration.

The reduced engine power will be experienced after initial cold start up or driving in low ambient temperatures.



2837688

Technicians may find the presence of DTCs P0101, P0171, P0172, P0174, P0175, P1516, P2177, P2178, P2179, P2180, P2187, P2188, P2189, and/or P2190 along with either ice or oil deposits in the air inlet duct.

Ice formation is caused by condensation freezing at the base of the throttle body with additional collection of ice formation deposits in the air inlet duct. Freezing condensation forms after the vehicle has been driven and then parked in low ambient temperatures.

Oil deposits are the collection of the engine vapors, fuel dilution and oil mist at the base of the throttle body with additional formation collecting in the duct.

Recommendation/Instructions (2007-2008 Enclave, Malibu, Traverse, Acadia, G6, OUTLOOK)

Use the following steps for servicing the positive crankcase ventilation (PCV) system for the models listed above.

1. Remove both camshaft covers for servicing of the PCV system. Refer to Camshaft Cover Replacement Left and Right Side in SI.
2. Clean the PCV orifice with low VOC brake cleaner. Allow to air dry with compressed shop air.
3. Replace the bank1 camshaft cover gasket.
4. Reassemble the bank1 camshaft cover.

Tighten

Tighten the camshaft cover bolts to 10 N•m (89 lb in).

5. Replace the bank2 camshaft cover and replace the camshaft cover gasket.
6. Reassemble the bank2 camshaft cover.

Tighten

Tighten the camshaft cover bolts to 10 N•m (89 lb in).

7. Install the insulated PCV tube.

Parts Information (2007-2008 Enclave, Malibu, Traverse, Acadia, G6, OUTLOOK)

Part Number	Description
12616913	Tube, PCV (Enclave, Traverse, Acadia, OUTLOOK)
12613199	Tube, PCV (Malibu, G6)
12647768	Cover, CM/SHF (LH) (LLT, LY7)
12641261	Seal, CM/SHR CVR (RH) (LLT, LY7)

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
J7575*	Positive Crankcase Ventilation Tube/ Covers/ Seal (LLT)	4.6 hrs
	Positive Crankcase Ventilation Tube/ Covers/ Seal (LY7)	3.2 hrs
*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		

Recommendation/Instructions (2009-2010 Enclave, Malibu, Traverse, Acadia, G6, OUTLOOK)

Use the following steps for servicing the positive crankcase ventilation (PCV) system for the models listed above.

1. Remove both camshaft covers for servicing of the PCV system. Refer to Camshaft Cover Replacement Left and Right Side in SI.
2. Clean the PCV orifice with low VOC brake cleaner. Allow to air dry with compressed shop air.
3. Replace the bank1 camshaft cover gasket.
4. Reassemble the bank1 camshaft cover.

Tighten

Tighten the camshaft cover bolts to 10 N•m (89 lb in).

5. Replace the bank2 camshaft cover and replace the camshaft cover gasket.
6. Reassemble the bank2 camshaft cover.

Tighten

Tighten the camshaft cover bolts to 10 N•m (89 lb in).

Parts Information (2009-2010 Enclave, Malibu, Traverse, Acadia, G6, OUTLOOK)

Part Number	Description
12647772	Cover, CM/SHF (LH) (LLT)
12647768	Cover, CM/SHF (LH) (LY7)

Part Number	Description
12641261	Seal, CM/SHR CVR (RH) (LLT, LY7)

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
J7575*	Positive Crankcase Ventilation Tube/ Covers/ Seal (LLT)	4.6 hrs
	Positive Crankcase Ventilation Tube/ Covers/ Seal (LY7)	3.2 hrs
*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		

Use the following steps for servicing the positive crankcase ventilation (PCV) system for the models listed above.

Recommendation/Instructions (2011 Enclave, Malibu, Traverse, Acadia)

1. Remove the bank2 camshaft cover for servicing of the PCV system. Refer to Camshaft Cover Replacement Left Side in SI.
2. Clean the PCV orifice with low VOC brake cleaner. Allow to air dry with compressed shop air.
3. Replace the bank2 camshaft cover and replace the camshaft cover gasket.
4. Reassemble the bank2 camshaft cover.

Tighten

Tighten the camshaft cover bolts to 10 N•m (89 lb in).

Parts Information (2011 Enclave, Malibu, Traverse, Acadia)

Part Number	Description
12647772	Cover, CM/SHF (LH) (LLT)
12647768	Cover, CM/SHF (LH) (LY7)

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
J0311	Camshaft Cover Replacement	Use Published Labor Operation Time