



# Service Bulletin

File in Section: 02 - Steering

Bulletin No.: 13-02-32-001B

Date: July, 2013

## TECHNICAL

**Subject:** Power Steering Noise or Fluid Leak from Power Steering Pump, Gear or High Pressure Hose During Extreme Low Temperature Conditions

**Models:** 2009-2013 Buick LaCrosse  
 2010-2013 Buick Regal  
 2012-2013 Buick Enclave  
 2013 Buick Encore Equipped with RPO N40 Hydraulic Power Steering  
 2007-2013 Cadillac Escalade  
 2009-2013 Cadillac SRX  
 2013 Cadillac XTS  
 2007-2013 Chevrolet Avalanche, Silverado 1500, Suburban 1500, Tahoe  
 2010-2013 Chevrolet Captiva, Captiva Sport (V6 Only), Equinox (V6 Only)  
 2011-2013 Chevrolet Silverado 2500/3500  
 2012-2013 Chevrolet Traverse  
 2013 Chevrolet Caprice PPV  
 2013 Chevrolet Tracker, Trax Equipped with RPO N40 Hydraulic Power Steering  
 2007-2013 GMC Sierra 1500, Yukon Models 1500 Series Only  
 2010-2013 GMC Terrain (V6 Only)  
 2011-2013 GMC Sierra 2500/3500  
 2012-2013 GMC Acadia  
 2009-2012 Opel Insignia

**Attention:** This bulletin also applies to any of the above models that may be export vehicles.

This bulletin has been revised to update the Models information and add an Attention statement. Please discard Corporate Bulletin Number 13-02-32-001A.

### Condition

**Important:** The information contained in this bulletin applies only to the models listed. DEXRON HP cannot be used in any other products power steering system. Ensure the vehicle being serviced is listed in the Models information above.

Some customers may comment that their vehicle is experiencing a power steering noise/whine or fluid leak from the power steering pump, gear or high pressure side power steering hose during extreme low outdoor temperature operation that the cold weather fluid recommended in the latest version of Bulletin Number 12-02-32-002 may not resolve.

### Cause

During extremely low temperatures, -35°C (-31°F) or lower (usually in the -40°C/F or less range), the power steering fluid may thicken and the power steering system pressures may rise, causing damage to various components.

### Instructions

To resolve this condition, replace any damaged power steering system components. Refer to Power Steering in SI for diagnosing and repairing steering system component fluid leaks.

Flush the power steering system and refill with DEXRON HP power steering fluid.

Provide the customer DEXRON HP fluid Part Number information for their records for any future maintenance needs.

## Parts Information

DEXRON HP ATF, or ATF (212-B) fluid (P/N or spec# 9986333, spec # GMW16444 ) is serviced with bottles:

Part Number	Description
19300536	32 oz. with English language label
19300537 (Canada)	1 Liter with English/French language label

## Warranty Information

**Note:** For vehicles that require power steering component replacement, use the appropriate labor operation for the replaced component. Use the unique labor operation only when servicing the fluid to correct a noise concern.

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
7480008*	Flush and Bleed Power Steering System to Correct Noise Concern	0.9 hr
*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		

