



SERVICE BULLETIN

Classification:	Reference:	Date:
EM13-003a	NTB13-040a	July 5, 2013

2013 ALTIMA SEDAN WITH QR25DE ENGINE; RATTLE OR GROAN NOISE FROM ENGINE AREA

This bulletin has been amended under ACTION and in PARTS INFORMATION and CLAIMS INFORMATION. Please discard previous versions of this bulletin.

APPLIED VEHICLE: 2013 Altima Sedan (L33)

APPLIED VINs and DATES: Vehicles built before: 1N4AL3A(* *)DC 264999 and 4/19/2013
1N4AL3A(* *)DN 551924 and 4/22/2013

APPLIED ENGINE: QR25DE (4-cyl) **only**

IF YOU CONFIRM:

A rattle or groan type noise is coming from the right front strut tower / engine area when:

- An applied vehicle is traveling at 20 - 40 MPH

AND / OR

- The engine is running at 1,400 - 1,500 RPM

AND

- The generator (alternator) is the source of the noise.

NOTE: This noise may be misdiagnosed as CVT or heat shield related.

ACTION:

Replace the alternator with the one listed in **PARTS INFORMATION**.

- Refer to the **M ELECTRICAL & POWER CONTROL > CHG Charging System** section of the Electronic Service Manual (ESM).

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QTY
ALT ASSY (alternator)	23100-3TA1B	1

CLAIMS INFORMATION

Submit a Primary Part (PP) line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace Alternator Assembly	23100-3TA1B	GE10AA	ZL	32	(1)

(1) Reference the current Nissan Warranty Flat Rate Manual and use the indicated flat rate time.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.