



NUMBER: 18-040-13
GROUP: Vehicle Performance
DATE: September 12, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING "HELP" THEN "HELP CONTENTS" AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE LEVEL MUST BE AT RELEASE 14.01 OR HIGHER TO PERFORM THIS PROCEDURE.

SUBJECT:

Flash: MIL Illumination P0456- Evap System Small Leak or P0128- Thermostat Rationality

OVERVIEW:

This bulletin involves selectively erasing and reprogramming the Powertrain Control Module (PCM) with new software.

MODELS:

2013 (FF) Fiat 500/Abarth

NOTE: This bulletin applies to vehicles equipped with a 1.4L engine (sales code EAB or EAF) built on or before June 24, 2013 (MDH 0724XX).

SYMPTOM/CONDITION:

A small number of customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the Technician may find that the following Diagnostic Trouble Codes have been set:

- P0456- Evap System Small Leak
- P0128- Thermostat Rationality

Updating the PCM software will correct the condition listed above.

DIAGNOSIS:

Using a Scan Tool (wiTECH w/Smart Cable 410) and appropriate Diagnostic Procedures available in TechCONNECT, verify all engine systems are functioning as designed. If DTC's are present other than the ones listed above, record them on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition or if the technician finds the DTCs, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT REQUIRED:

Qty.	Part No.	Description
1	410	wiTECH Smart Cable

NOTE: The smart cable must be used to communicate and flash the Fiat 500. To obtain a smart cable, contact the wiTECH help desk at 1-888-948-3241.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Using the wiTECH Diagnostic Application for flashing a HVAC is made available through the wiTECH Diagnostic Application. For instructions select the "HELP" tab on upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.
2. Perform Cruise Control Learn Procedure.
 - a. Turn Ignition Key to the OFF/LOCK position for 10 seconds to allow the module to power down.
 - b. Turn Ignition Key to the ON/RUN position.
 - c. Press, then release the Cruise ON/OFF button on the steering wheel.
 - d. Start Engine.
 - e. Press the Cruise ON/OFF button to verify that the Cruise indicator illuminates on the cluster.
3. Is vehicle equipped with a manual transmission?
 - a. Yes >>> DTC P1302 - Transmission Self Learning will be present. **Depress clutch pedal fully to allow DTC to store**, proceed to Step 4.
 - b. No >>> DTC P1302 - Transmission Self Learning will be stored, proceed to Step 4.
4. **After PCM reprogramming, the following must be performed:** clear any DTC's that may have been set in other modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow the tech to clear them.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-06-W5	Module, Powertrain Control (PCM) - Reprogram (1 - Semi-Skilled)	8 - Engine Performance	0.3 Hrs.

FAILURE CODE:

FM	Flash Module
----	--------------