

SB-10056379-7702

LINCOLN:

2013-2014 MKZ

ISSUE

Some 2013-2014 MKZ vehicles with a power luggage compartment lid may have a luggage compartment lid that can be opened while the vehicle is locked using the exterior luggage compartment lid release button without a programmed Intelligent Access key present.

ACTION

Reprogram the Body Control Module (BCM) to the latest calibration using IDS release 90.01 and higher. Calibration files may also be obtained at www.motorcraft.com.

OPERATION	DESCRIPTION	TIME
140087A	2013-2014 MKZ: Reprogram The BCM And Clear DTCs (Do Not Use With Any Other Labor Operations)	0.3 Hr.

WARRANTY STATUS:

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

DEALER CODING

BASIC PART NO.	CONDITION CODE
15604	04

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.